

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-2/20/06	030605408-0001	Southwest Area (sidewalk bridge level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST2-2/20/06	030605408-0002	Southeast Area (sidewalk bridge level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST4-2/20/06	030605408-0003	Northwest Area (street-level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST5-2/20/06	030605408-0004	Firehouse #10 (roof level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	13.00	No	No	
ASBESTOS-ST10-2/20/06	030605408-0005	North Side Sidewalk Bridge	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST11-2/20/06	030605408-0006	90 Trinity Place (roof level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST12-2/20/06	030605408-0007	110 Greenwich Street (roof level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST13-2/20/06	030605408-0008	Marriott Hotel, 38th Floor (roof level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST14-2/20/06	030605408-0009	West Face - South end at corner (scaffolding level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST15-2/20/06	030605408-0010	South Face - East end at corner (scaffolding level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST16-2/20/06	030605408-0011	East Face - North end at corner (scaffolding level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST17-2/20/06	030605408-0012	North Face - West end at corner (scaffolding level)	2/20/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/21/06	< 13.00	No	No	
ASBESTOS-ST1-2/21/06	030605562-0001	Southwest Area (sidewalk bridge level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST2-2/21/06	030605562-0002	Southeast Area (sidewalk bridge level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST4-2/21/06	030605562-0003	Northwest Area (street-level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST5-2/21/06	030605562-0004	Firehouse #10 (roof level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST10-2/21/06	030605562-0005	North Side Sidewalk Bridge	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST11-2/21/06	030605562-0006	90 Trinity Place (roof level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST12-2/21/06	030605562-0007	110 Greenwich Street (roof level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST13-2/21/06	030605562-0008	Marriott Hotel, 38th Floor (roof level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST14-2/21/06	030605562-0009	West Face - South end at corner (scaffolding level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST16-2/21/06	030605562-0011	East Face - North end at corner (scaffolding level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST17-2/21/06	030605562-0012	North Face - West end at corner (scaffolding level)	2/21/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/22/06	< 13.00	No	No	
ASBESTOS-ST1-2/22/06	030605706-0001	Southwest Area (sidewalk bridge level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST2-2/22/06	030605706-0002	Southeast Area (sidewalk bridge level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST4-2/22/06	030605706-0003	Northwest Area (street-level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST5-2/22/06	030605706-0004	Firehouse #10 (roof level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST10-2/22/06	030605706-0005	North Side Sidewalk Bridge	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST11-2/22/06	030605706-0006	90 Trinity Place (roof level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST12-2/22/06	030605706-0007	110 Greenwich Street (roof level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST13-2/22/06	030605706-0008	Marriott Hotel, 38th Floor (roof level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST14-2/22/06	030605706-0009	West Face - South end at corner (scaffolding level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST15-2/22/06	030605706-0010	South Face - East end at corner (scaffolding level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST16-2/22/06	030605706-0011	East Face - North end at corner (scaffolding level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	
ASBESTOS-ST17-2/22/06	030605706-0012	North Face - West end at corner (scaffolding level)	2/22/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/23/06	< 13.00	No	No	

Note:

1. Asbestos sample at Station 15 (South Face - East end at corner [scaffolding level]) on February 21, 2006 was not available for analysis due to a damaged filter.