TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date			Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	
			Target Air Q	uality Levels						NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels										70	Levels	Trigger Levels	
ASBESTOS-ST1-3/14/09	030906843-0001	Southwest Area (sidewalk bridge level)	3/14/09	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/16/09	< 13.00	No	No	
ASBESTOS-ST2-3/14/09	030906843-0002	Southeast Area (sidewalk bridge level)	3/14/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/16/09	< 13.00	No	No	
ASBESTOS-ST4-3/14/09		Northwest Area (street-level)	3/14/09	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST5-3/14/09	030906843-0004 F	Firehouse #10 (roof level)	3/14/09	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/16/09	< 13.00	No	No	
ASBESTOS-ST10-3/14/09		North Side Sidewalk Bridge	3/14/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/16/09	< 15.00	No	No	
ASBESTOS-ST11-3/14/09		90 Trinity Place (roof level)	3/14/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST12-3/14/09	030906843-0007	110 Greenwich Street (roof level)	3/14/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST13-3/14/09		Marriott Hotel, 38th Floor (roof level)	3/14/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST14-3/14/09		West Face - South end at corner (scaffolding level)	3/14/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 15.00	No	No	Note 1
ASBESTOS-ST15-3/14/09		South Face - East end at corner (scaffolding level)	3/14/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	Note 1
ASBESTOS-ST16-3/14/09	030906843-0011 E	East Face - North end at corner (scaffolding level)	3/14/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	Note 1
ASBESTOS-ST17-3/14/09	030906843-0012	North Face - West end at corner (scaffolding level)	3/14/09	1	2.810	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/16/09	< 13.00	No	No	Note 2
ASBESTOS-ST1-3/15/09		Southwest Area (sidewalk bridge level)	3/15/09	1	3.220	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST2-3/15/09	030906849-0002	Southeast Area (sidewalk bridge level)	3/15/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST4-3/15/09		Northwest Area (street-level)	3/15/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST5-3/15/09	030906849-0004 F	Firehouse #10 (roof level)	3/15/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST10-3/15/09		North Side Sidewalk Bridge	3/15/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST11-3/15/09		90 Trinity Place (roof level)	3/15/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST12-3/15/09		110 Greenwich Street (roof level)	3/15/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST13-3/15/09		Marriott Hotel, 38th Floor (roof level)	3/15/09	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/16/09	< 13.00	No	No	
ASBESTOS-ST1-03/16/09		Southwest Area (sidewalk bridge level)	3/16/09	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/17/09	< 13.00	No	No	
ASBESTOS-ST2-03/16/09		Southeast Area (sidewalk bridge level)	3/16/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/17/09	< 13.00	No	No	
ASBESTOS-ST4-03/16/09		Northwest Area (street-level)	3/16/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/17/09	< 13.00	No	No	
ASBESTOS-ST5-03/16/09		Firehouse #10 (roof level)	3/16/09	1		Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/17/09	< 15.00	No	No	
		North Side Sidewalk Bridge	3/16/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/17/09	13.00	No	No	
ASBESTOS-ST11-03/16/09	030906926-0006	90 Trinity Place (roof level)	3/16/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/17/09	< 15.00	No	No	
ASBESTOS-ST12-03/16/09	030906926-0007	110 Greenwich Street (roof level)	3/16/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/17/09	< 15.00	No	No	
		Marriott Hotel, 38th Floor (roof level)	3/16/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/17/09	< 15.00	No	No	
ASBESTOS-ST14-03/16/09	030906926-0009	West Face - South end at corner (scaffolding level)	3/16/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/17/09	< 13.00	No	No	
		South Face - East end at corner (scaffolding level)	3/16/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/17/09	< 13.00	No	No	
		East Face - North end at corner (scaffolding level)	3/16/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)		3/17/09	< 15.00	No	No	
ASBESTOS-ST17-03/16/09	030906926-0012	North Face - West end at corner (scaffolding level)	3/16/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/17/09	< 13.00	No	No	Note 4

- 1. The asbestos sample volumes at Station 14 (West Face South end at corner [scaffolding level]), Station 15 [South Face East end at corner [scaffolding level]) and Station 16 (East Face North end at corner [scaffolding level]) on March 14, 2009 represent approximately 1443 minutes sampled on March 14, 2009 and March 15, 2009 due to intermittent power outages.

 2. The asbestos sample volume at Station 17 (North Face West end at corner [scaffolding level:15th floor]) on March 14, 2009 represents 1277 minutes sampled on March 14, 2009 and March 15, 2009 due to power outages.
- 3. The asbestos samples at Station 14 (West Face South end at corner [scaffolding level), Station 15 [South Face East end at corner [scaffolding level]), Station 16 (East Face North end at corner [scaffolding level]), and Station 17 (North Face West end at corner [scaffolding level]) on March 15, 2009 were composited with the samples for March 14, 2009. Refer to samples collected on March 14, 2009.

 4. The asbestos sample Station 17 (North Face West end at corner [scaffolding level]) on March 16, 2009 had a slightly reduced volume due to 160 minute power outage caused by an electrical leg failure.

Asbestos-AHERA Page 1 of 1 130 Liberty Street Deconstruction Project