

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-3/20/06	030608638-0001	Southwest Area (sidewalk bridge level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST2-3/20/06	030608638-0002	Southeast Area (sidewalk bridge level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST4-3/20/06	030608638-0003	Northwest Area (street-level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST5-3/20/06	030608638-0004	Firehouse #10 (roof level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST10-3/20/06	030608638-0005	North Side Sidewalk Bridge	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST11-3/20/06	030608638-0006	90 Trinity Place (roof level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST12-3/20/06	030608638-0007	110 Greenwich Street (roof level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST13-3/20/06	030608638-0008	Marriott Hotel, 38th Floor (roof level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST14-3/20/06	030608638-0009	West Face - South end at corner (scaffolding level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST15-3/20/06	030608638-0010	South Face - East end at corner (scaffolding level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST16-3/20/06	030608638-0011	East Face - North end at corner (scaffolding level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST17-3/20/06	030608638-0012	North Face - West end at corner (scaffolding level)	3/20/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/21/06	< 13.00	No	No	
ASBESTOS-ST1-3/21/06	030608771-0001	Southwest Area (sidewalk bridge level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST2-3/21/06	030608771-0002	Southeast Area (sidewalk bridge level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST4-3/21/06	030608771-0003	Northwest Area (street-level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST5-3/21/06	030608771-0004	Firehouse #10 (roof level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST10-3/21/06	030608771-0005	North Side Sidewalk Bridge	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST11-3/21/06	030608771-0006	90 Trinity Place (roof level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST12-3/21/06	030608771-0007	110 Greenwich Street (roof level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST13-3/21/06	030608771-0008	Marriott Hotel, 38th Floor (roof level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST14-3/21/06	030608771-0009	West Face - South end at corner (scaffolding level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST15-3/21/06	030608771-0010	South Face - East end at corner (scaffolding level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST16-3/21/06	030608771-0011	East Face - North end at corner (scaffolding level)	3/21/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/22/06	< 13.00	No	No	
ASBESTOS-ST1-3/22/06	030608913-0001	Southwest Area (sidewalk bridge level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST2-3/22/06	030608913-0002	Southeast Area (sidewalk bridge level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST4-3/22/06	030608913-0003	Northwest Area (street-level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST5-3/22/06	030608913-0004	Firehouse #10 (roof level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST10-3/22/06	030608913-0005	North Side Sidewalk Bridge	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	13.00	No	No	
ASBESTOS-ST11-3/22/06	030608913-0006	90 Trinity Place (roof level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST12-3/22/06	030608913-0007	110 Greenwich Street (roof level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST13-3/22/06	030608913-0008	Marriott Hotel, 38th Floor (roof level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST14-3/22/06	030608913-0009	West Face - South end at corner (scaffolding level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST15-3/22/06	030608913-0010	South Face - East end at corner (scaffolding level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST16-3/22/06	030608913-0011	East Face - North end at corner (scaffolding level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	
ASBESTOS-ST17-3/22/06	030608913-0012	North Face - West end at corner (scaffolding level)	3/22/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	3/23/06	< 13.00	No	No	

Note:

- The asbestos sample at Station 17 (North Face - West end at corner [scaffolding level]) on March 21, 2006 was not available for analysis on account of filter damage.