| TRC Field Sample No. | Sample No. Sampling Location | Collection Start Date | Sample Volume (m ³) | Analyte | Analytical Method | Lab L | Lab Sample Receipt Date | Mercury (Total) Concentration (ng/m3) | Exceeds Target | Exceeds EPA | |
|----------------------|--|--------------------------------|---------------------------------|---------|-------------------|-------|-------------------------|---------------------------------------|----------------|----------------|---|
| | <u> </u> | Target Air Quality Levels | • | | | | | 300 | Air Quality | Site Specific | Comments |
| | | EPA Site Specific Trigger Leve | els | | | | | 3,000 | Levels | Trigger Levels | |
| TotalHg-ST1-8/18/07 | 0734004-01 Southwest Area (sidewalk bridge level) | 8/18/07 | 0.56 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 27.0 | No | No | |
| TotalHg-ST2-8/18/07 | 0734004-02 Southeast Area (sidewalk bridge level) | 8/18/07 | 0.56 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 27.0 | No | No | |
| TotalHg-ST4-8/18/07 | 0734004-03 Northwest Area (street-level) | 8/18/07 | 0.60 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 25.0 | No | No | |
| TotalHg-ST5-8/18/07 | 0734004-04 Firehouse #10 (roof level) | 8/18/07 | 0.55 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 27.0 | No | No | |
| TotalHg-ST10-8/18/07 | 0734004-05 North Side Sidewalk Bridge | 8/18/07 | 0.57 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 26.0 | No | No | |
| TotalHg-ST11-8/18/07 | 0734004-06 90 Trinity Place (roof level) | 8/18/07 | 0.54 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 28.0 | No | No | |
| TotalHg-ST12-8/18/07 | 0734004-07 110 Greenwich Street (roof level) | 8/18/07 | 0.58 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 26.0 | No | No | |
| TotalHg-ST13-8/18/07 | 0734004-08 Marriott Hotel, 38th Floor (roof level) | 8/18/07 | 0.58 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 26.0 | No | No | |
| TotalHg-ST16-8/18/07 | 0735008-01 East Face - North end at corner (scaffolding le | evel) 8/18/07 | 4.18 | Mercury | EPA 324/1631 | BRL | 8/28/07 | < 4.0 | No | No | Result represents conditions from 8/18/07 through 8/27/07 |
| TotalHg-ST17-8/18/07 | 0735008-02 North Face - West end at corner (scaffolding I | evel) 8/18/07 | 4.24 | Mercury | EPA 324/1631 | BRL | 8/28/07 | 20.0 | No | No | Result represents conditions from 8/18/07 through 8/27/07 |
| TotalHg-ST1-8/19/07 | 0735014-01 Southwest Area (sidewalk bridge level) | 8/19/07 | 4.76 | Mercury | EPA 324/1631 | BRL | 8/29/07 | 3.0 | No | No | Result represents conditions from 8/19/07 through 8/28/07, Note 3 |
| TotalHg-ST2-8/19/07 | 0735014-02 Southeast Area (sidewalk bridge level) | 8/19/07 | 4.68 | Mercury | EPA 324/1631 | BRL | 8/29/07 | 3.0 | No | No | Result represents conditions from 8/19/07 through 8/28/07, Note 4 |
| TotalHg-ST4-8/19/07 | 0734005-01 Northwest Area (street-level) | 8/19/07 | 0.53 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 28.0 | No | No | |
| TotalHg-ST5-8/19/07 | 0734005-02 Firehouse #10 (roof level) | 8/19/07 | 0.59 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 25.0 | No | No | |
| TotalHg-ST10-8/19/07 | 0734005-03 North Side Sidewalk Bridge | 8/19/07 | 0.62 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 24.0 | No | No | |
| TotalHg-ST11-8/19/07 | 0734005-04 90 Trinity Place (roof level) | 8/19/07 | 0.55 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 27.0 | No | No | Note 5 |
| TotalHg-ST12-8/19/07 | 0734005-05 110 Greenwich Street (roof level) | 8/19/07 | 0.59 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 25.0 | No | No | |
| TotalHg-ST13-8/19/07 | 0734005-06 Marriott Hotel, 38th Floor (roof level) | 8/19/07 | 0.58 | Mercury | EPA 324/1631 | BRL | 8/21/07 | < 26.0 | No | No | |

- Note:

 1. Mercury sample at Station 14 (West Face South end at corner [scaffolding level]) on August 18, 2007 was not available for analysis on account of a power failure.

 2. Mercury sample at Station 15 (South Face East end at corner [scaffolding level]) on August 18, 2007 was not available for analysis on account of pump failure.

 3. Due to flow rate RPD exceedance (22.2%) for mercury at Station 1 (Southwest Area [sidewalk bridge level]) on August 19, 2007, the sample volume and subsequent sample result are estimated.

 4. Due to flow rate RPD exceedance (25.4%) for mercury at Station 2 Southeast Area [sidewalk bridge level]) on August 19, 2007, the sample volume and subsequent sample result are estimated.

 5. Due to flow rate RPD exceedance (22.2%) for mercury at Station 11 (90 Trinity Place [roof level]) on August 19, 2007, the sample volume and subsequent sample result are estimated.
- 6. Mercury samples at Station 14 (West Face South end at corner [scaffolding level]), Station 15 [South Face East end at corner [scaffolding level]), Station 16 (East Face North end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]), were not available for analysis on August 19, 2007. The stations were not accessible on account of a fire at 130 Liberty Street.

Page 1 of 1 130 Liberty Street Deconstruction Project Mercury