

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments
									5,000	5,000	20	40	600	10,000	1,500	500	200	160,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments
									Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels
METALS-ST1-2/8/06	G6B100245001	Southwest Area (sidewalk bridge level)	2/8/06	1856.1	Metals	6020	STL-SAC	2/10/06	< 1.3	< 66.4	< 0.66	< 0.66	< 6.6	56.6	27.8	9.8	3.4	32.7	No	No	
METALS-ST2-2/8/06	G6B100245002	Southeast Area (sidewalk bridge level)	2/8/06	1809.1	Metals	6020	STL-SAC	2/10/06	2.0	< 66.3	< 0.66	< 0.66	< 6.6	87.8	20.8	37.3	7.1	72.6	No	No	
METALS-ST4-2/8/06	G6B100245003	Northwest Area (street-level)	2/8/06	1847.6	Metals	6020	STL-SAC	2/10/06	< 1.3	< 64.9	< 0.65	< 0.65	< 6.5	142	11.4	7.8	< 3.2	22.4	No	No	
METALS-ST5-2/8/06	G6B100245004	Firehouse #10 (roof level)	2/8/06	1818.6	Metals	6020	STL-SAC	2/10/06	< 1.3	< 66.0	< 0.66	< 0.66	< 6.6	401	7.7	19.6	< 3.3	29.6	No	No	
METALS-ST10-2/8/06	G6B100245005	North Side Sidewalk Bridge	2/8/06	1849	Metals	6020	STL-SAC	2/10/06	< 1.3	< 64.9	< 0.65	< 0.65	< 6.5	120	6.4	11.2	< 3.2	27.4	No	No	
METALS-ST11-2/8/06	G6B100245006	90 Trinity Place (roof level)	2/8/06	1679.3	Metals	6020	STL-SAC	2/10/06	< 1.4	< 71.4	< 0.71	< 0.71	< 7.1	178	10.4	12.5	6.6	29.4	No	No	
METALS-ST13-2/8/06	G6B100245007	Marriott Hotel, 38th Floor (roof level)	2/8/06	1865.8	Metals	6020	STL-SAC	2/10/06	< 1.3	< 64.3	< 0.64	< 0.64	< 6.4	46.5	4.0	7.0	4.3	18.9	No	No	
METALS-ST14-2/8/06	G6B100245008	West Face - South end at corner (scaffolding level)	2/8/06	1841.9	Metals	6020	STL-SAC	2/10/06	< 1.3	< 65.2	< 0.65	< 0.65	< 6.5	16.9	3.8	5.2	< 3.2	15.7	No	No	
METALS-ST15-2/8/06	G6B100245009	South Face - East end at corner (scaffolding level)	2/8/06	1855.2	Metals	6020	STL-SAC	2/10/06	< 1.3	< 64.7	< 0.65	< 0.65	< 6.5	116	6.5	9.1	4.3	24.7	No	No	
METALS-ST16-2/8/06	G6B100245010	East Face - North end at corner (scaffolding level)	2/8/06	1819.4	Metals	6020	STL-SAC	2/10/06	< 1.3	< 66.0	< 0.66	< 0.66	< 6.6	142	6.7	9.8	4.0	30.3	No	No	
METALS-ST17-2/8/06	G6B100245011	North Face - West end at corner (scaffolding level)	2/8/06	1705.1	Metals	6020	STL-SAC	2/10/06	< 1.4	< 70.4	< 0.70	< 0.70	< 7.0	12.4	4.2	5.6	< 3.5	18.8	No	No	
METALS-ST1-2/9/06	G6B110188001	Southwest Area (sidewalk bridge level)	2/9/06	1807.56	Metals	6020	STL-SAC	2/11/06	1.4	< 66.4	< 0.66	< 0.66	< 6.6	108	74.7	18.2	7.7	55.9	No	No	
METALS-ST2-2/9/06	G6B110188002	Southeast Area (sidewalk bridge level)	2/9/06	1795.41	Metals	6020	STL-SAC	2/11/06	1.8	< 66.8	< 0.67	< 0.67	< 6.7	183	30.1	31.8	10.9	64.8	No	No	
METALS-ST4-2/9/06	G6B110188003	Northwest Area (street-level)	2/9/06	1829.86	Metals	6020	STL-SAC	2/11/06	< 1.3	< 65.6	< 0.66	< 0.66	< 6.6	219	45.4	12.6	7.5	41.1	No	No	
METALS-ST5-2/9/06	G6B110188004	Firehouse #10 (roof level)	2/9/06	1785.66	Metals	6020	STL-SAC	2/11/06	< 1.3	< 67.2	< 0.67	< 0.67	< 6.7	399	18.1	28.2	8.1	49.4	No	No	
METALS-ST10-2/9/06	G6B110188005	North Side Sidewalk Bridge	2/9/06	1850.35	Metals	6020	STL-SAC	2/11/06	< 1.3	< 64.8	< 0.65	< 0.65	< 6.5	85.8	12.4	12.7	7.1	33.4	No	No	
METALS-ST100-2/9/06	G6B110188013	Station 10 Field Duplicate	2/9/06	1875.89	Metals	6020	STL-SAC	2/11/06	< 1.3	< 64.0	< 0.64	< 0.64	< 6.4	140	12.4	13.7	7.5	34.5	No	No	
METALS-ST11-2/9/06	G6B110188006	90 Trinity Place (roof level)	2/9/06	1640.84	Metals	6020	STL-SAC	2/11/06	< 1.5	< 73.1	< 0.73	< 0.73	< 7.3	283	13.4	18.0	10.0	43.5	No	No	
METALS-ST12-2/9/06	G6B110188007	110 Greenwich Street (roof level)	2/9/06	1828.95	Metals	6020	STL-SAC	2/11/06	< 1.3	< 65.6	< 0.66	< 0.66	< 6.6	64.2	10.6	14.4	9.5	37.4	No	No	
METALS-ST13-2/9/06	G6B110188008	Marriott Hotel, 38th Floor (roof level)	2/9/06	1779	Metals	6020	STL-SAC	2/11/06	< 1.3	< 67.4	< 0.67	< 0.67	< 6.7	59.4	7.5	12.8	10.3	30.2	No	No	
METALS-ST14-2/9/06	G6B110188009	West Face - South end at corner (scaffolding level)	2/9/06	1795.38	Metals	6020	STL-SAC	2/11/06	< 1.3	< 66.8	< 0.67	< 0.67	< 6.7	22.3	7.3	9.5	5.8	27.4	No	No	
METALS-ST15-2/9/06	G6B110188010	South Face - East end at corner (scaffolding level)	2/9/06	1791.05	Metals	6020	STL-SAC	2/11/06	< 1.3	< 67.0	< 0.67	< 0.67	< 6.7	77.6	8.9	11.1	6.9	41.8	No	No	
METALS-ST16-2/9/06	G6B110188011	East Face - North end at corner (scaffolding level)	2/9/06	1727.29	Metals	6020	STL-SAC	2/11/06	< 1.4	< 69.5	< 0.69	< 0.69	< 6.9	320	12.9	18.1	10.2	47.9	No	No	
METALS-ST17-2/9/06	G6B110188012	North Face - North end at corner (scaffolding level)	2/9/06	1663.86	Metals	6020	STL-SAC	2/11/06	< 1.4	< 72.1	< 0.72	0.75	< 7.2	107	9.8	12.3	7.0	39.9	No	No	

Note:
1. Metals sample at Station 12 (110 Greenwich Street [roof level]) on February 8, 2006 was not available for analysis on account of pump failure.