

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels									5,000	5,000	20	40	500	10,000	1,500	500	200	16,000			
EPA Site Specific Trigger Levels									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-4/14/06	G6D180184001	Southwest Area (sidewalk bridge level)	4/14/06	1770.7	Metals	6020	STL-SAC	4/18/06	5.1	< 67.8	< 0.68	< 0.68	< 6.8	444	66.4	29.0	13.4	83.2	No	No	
METALS-ST2-4/14/06	G6D180184002	Southeast Area (sidewalk bridge level)	4/14/06	1758.8	Metals	6020	STL-SAC	4/18/06	4.8	< 68.2	< 0.68	< 0.68	< 6.8	64.2	46.4	30.5	13.8	77.3	No	No	
METALS-ST4-4/14/06	G6D180184003	Northwest Area (street-level)	4/14/06	1647.3	Metals	6020	STL-SAC	4/18/06	4.6	< 72.8	< 0.73	< 0.73	< 7.3	105	59.3	27.2	14.6	94.8	No	No	
METALS-ST5-4/14/06	G6D180184004	Firehouse #10 (roof level)	4/14/06	1916.5	Metals	6020	STL-SAC	4/18/06	3.9	< 62.6	< 0.63	< 0.63	< 6.3	60.1	25.8	28.4	13.9	121	No	No	
METALS-ST10-4/14/06	G6D180184005	North Side Sidewalk Bridge	4/14/06	1746.2	Metals	6020	STL-SAC	4/18/06	4.7	< 68.7	< 0.69	< 0.69	< 6.9	65.9	47.4	30.3	14.3	116	No	No	
METALS-ST11-4/14/06	G6D180184006	90 Trinity Place (roof level)	4/14/06	1775.8	Metals	6020	STL-SAC	4/18/06	3.8	< 67.6	< 0.68	< 0.68	< 6.8	79.5	21.3	25.0	12.5	70.7	No	No	
METALS-ST12-4/14/06	G6D180184007	110 Greenwich Street (roof level)	4/14/06	1710.9	Metals	6020	STL-SAC	4/18/06	4.0	< 70.1	< 0.70	< 0.70	< 7.0	91.1	25.4	25.3	14.0	68.0	No	No	
METALS-ST13-4/14/06	G6D180184008	Marront Hotel, 38th Floor (roof level)	4/14/06	1941.9	Metals	6020	STL-SAC	4/18/06	3.1	< 61.8	< 0.62	< 0.62	< 6.2	150	15.4	17.9	11.7	59.3	No	No	
METALS-ST14-4/14/06	G6D180184009	West Face - South end at corner (scaffolding level)	4/14/06	1677.8	Metals	6020	STL-SAC	4/18/06	3.6	< 71.5	< 0.72	< 0.72	< 7.2	114	13.6	18.3	13.2	59.9	No	No	
METALS-ST15-4/14/06	G6D180184010	South Face - East end at corner (scaffolding level)	4/14/06	1699.5	Metals	6020	STL-SAC	4/18/06	3.2	< 70.6	< 0.71	< 0.71	< 7.1	71.2	11.8	16.0	11.0	50.0	No	No	
METALS-ST16-4/14/06	G6D180184011	East Face - North end at corner (scaffolding level)	4/14/06	1694	Metals	6020	STL-SAC	4/18/06	3.3	< 70.8	< 0.71	< 0.71	< 7.1	60.5	13.5	17.0	12.3	66.6	No	No	
METALS-ST17-4/14/06	G6D180184012	North Face - West end at corner (scaffolding level)	4/14/06	1722.7	Metals	6020	STL-SAC	4/18/06	3.5	< 69.6	< 0.70	< 0.70	< 7.0	252	13.8	17.8	13.1	62.0	No	No	
METALS-ST1-4/15/06	G6D180180001	Southwest Area (sidewalk bridge level)	4/15/06	1748.8	Metals	6020	STL-SAC	4/18/06	1.9	< 68.6	< 0.69	< 0.69	< 6.9	148	13.5	11.8	3.7	57.2	No	No	
METALS-ST2-4/15/06	G6D180180002	Southeast Area (sidewalk bridge level)	4/15/06	1746.6	Metals	6020	STL-SAC	4/18/06	2.6	< 68.7	< 0.69	< 0.69	< 6.9	47.2	14.9	13.6	3.7	67.5	No	No	
METALS-ST4-4/15/06	G6D180180003	Northwest Area (street-level)	4/15/06	1634.4	Metals	6020	STL-SAC	4/18/06	< 1.5	< 73.4	< 0.73	< 0.73	< 7.3	36.0	14.4	8.5	< 3.7	40.6	No	No	
METALS-ST5-4/15/06	G6D180180004	Firehouse #10 (roof level)	4/15/06	1833.8	Metals	6020	STL-SAC	4/18/06	1.4	< 65.4	< 0.65	< 0.65	< 6.5	38.3	15.8	15.8	< 3.3	169	No	No	
METALS-ST10-4/15/06	G6D180180005	North Side Sidewalk Bridge	4/15/06	1748.4	Metals	6020	STL-SAC	4/18/06	1.4	< 68.6	< 0.69	< 0.69	< 6.9	47.2	11.3	10.9	< 3.4	70.8	No	No	
METALS-ST11-4/15/06	G6D180180006	90 Trinity Place (roof level)	4/15/06	1776.7	Metals	6020	STL-SAC	4/18/06	< 1.4	< 67.5	< 0.68	< 0.68	< 6.8	39.2	9.1	8.9	< 3.4	50.7	No	No	
METALS-ST12-4/15/06	G6D180180007	110 Greenwich Street (roof level)	4/15/06	1755.3	Metals	6020	STL-SAC	4/18/06	1.4	< 68.4	< 0.68	< 0.68	< 6.8	42.8	9.2	8.8	3.5	49.2	No	No	
METALS-ST13-4/15/06	G6D180180008	Marront Hotel, 38th Floor (roof level)	4/15/06	1768	Metals	6020	STL-SAC	4/18/06	< 1.4	< 67.9	< 0.68	< 0.68	< 6.8	88.2	5.1	5.9	< 3.4	19.5	No	No	
METALS-ST14-4/15/06	G6D180180009	West Face - South end at corner (scaffolding level)	4/15/06	1812.8	Metals	6020	STL-SAC	4/18/06	< 1.3	< 66.2	< 0.66	< 0.66	< 6.6	31.7	4.5	4.8	< 3.3	18.8	No	No	
METALS-ST15-4/15/06	G6D180180010	South Face - East end at corner (scaffolding level)	4/15/06	1807	Metals	6020	STL-SAC	4/18/06	< 1.3	< 66.4	< 0.66	< 0.66	< 6.6	49.5	5.1	5.4	< 3.3	21.9	No	No	
METALS-ST16-4/15/06	G6D180180011	East Face - North end at corner (scaffolding level)	4/15/06	1831.1	Metals	6020	STL-SAC	4/18/06	< 1.3	< 65.5	< 0.66	< 0.66	< 6.6	51.0	7.5	8.3	< 3.3	48.9	No	No	
METALS-ST17-4/15/06	G6D180180012	North Face - West end at corner (scaffolding level)	4/15/06	1846.1	Metals	6020	STL-SAC	4/18/06	< 1.3	< 65.0	< 0.65	< 0.65	< 6.5	190	4.3	4.5	< 3.2	24.8	No	No	
METALS-ST1-4/16/06	G6D180187001	Southwest Area (sidewalk bridge level)	4/16/06	1784.4	Metals	6020	STL-SAC	4/18/06	< 1.3	< 67.2	< 0.67	< 0.67	< 6.7	105	14.6	7.4	< 3.4	21.3	No	No	
METALS-ST2-4/16/06	G6D180187002	Southeast Area (sidewalk bridge level)	4/16/06	1771.7	Metals	6020	STL-SAC	4/18/06	2.7	< 67.7	< 0.68	< 0.68	< 6.8	75.4	14.4	3.7	3.7	53.4	No	No	
METALS-ST4-4/16/06	G6D180187003	Northwest Area (street-level)	4/16/06	1684.5	Metals	6020	STL-SAC	4/18/06	< 1.4	< 71.2	< 0.71	< 0.71	< 7.1	30.9	6.4	6.9	< 3.6	21.9	No	No	
METALS-ST5-4/16/06	G6D180187004	Firehouse #10 (roof level)	4/16/06	1885.3	Metals	6020	STL-SAC	4/18/06	< 1.3	< 63.6	< 0.64	< 0.64	< 6.4	28.8	4.5	7.8	< 3.2	21.8	No	No	
METALS-ST10-4/16/06	G6D180187005	North Side Sidewalk Bridge	4/16/06	1808.2	Metals	6020	STL-SAC	4/18/06	< 1.3	< 66.4	< 0.66	< 0.66	< 6.6	40.1	5.2	7.8	< 3.3	20.8	No	No	
METALS-ST11-4/16/06	G6D180187006	90 Trinity Place (roof level)	4/16/06	1783.5	Metals	6020	STL-SAC	4/18/06	< 1.3	< 67.3	< 0.67	< 0.67	< 6.7	28.2	4.4	6.8	< 3.4	17.4	No	No	
METALS-ST12-4/16/06	G6D180187007	110 Greenwich Street (roof level)	4/16/06	1785.5	Metals	6020	STL-SAC	4/18/06	< 1.3	< 67.2	< 0.67	< 0.67	< 6.7	364	4.0	5.4	< 3.4	14.7	No	No	
METALS-ST13-4/16/06	G6D180187008	Marront Hotel, 38th Floor (roof level)	4/16/06	1681.9	Metals	6020	STL-SAC	4/18/06	< 1.4	< 71.3	< 0.71	< 0.71	< 7.1	147	3.0	4.6	< 3.6	< 14.3	No	No	
METALS-ST14-4/16/06	G6D180187009	West Face - South end at corner (scaffolding level)	4/16/06	1758.9	Metals	6020	STL-SAC	4/18/06	< 1.4	< 68.2	< 0.68	< 0.68	< 6.8	44.0	3.8	6.1	< 3.4	17.1	No	No	
METALS-ST15-4/16/06	G6D180187010	South Face - East end at corner (scaffolding level)	4/16/06	1778.6	Metals	6020	STL-SAC	4/18/06	< 1.3	< 67.5	< 0.67	< 0.67	< 6.7	76.2	6.4	8.1	< 3.4	21.7	No	No	
METALS-ST16-4/16/06	G6D180187011	East Face - North end at corner (scaffolding level)	4/16/06	1747.8	Metals	6020	STL-SAC	4/18/06	< 1.4	< 68.6	< 0.69	< 0.69	< 6.9	52.9	4.6	6.6	< 3.4	25.4	No	No	

Note:
1. Metals sample at Station 17 (North Face - West end at corner (scaffolding level)) on April 16, 2006 was not available for analysis on account of a sampler failure.