

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m <sup>3</sup> )	Barium Concentration (ng/m <sup>3</sup> )	Beryllium Concentration (ng/m <sup>3</sup> )	Cadmium Concentration (ng/m <sup>3</sup> )	Chromium (Total) Concentration (ng/m <sup>3</sup> )	Copper Concentration (ng/m <sup>3</sup> )	Lead Concentration (ng/m <sup>3</sup> )	Manganese Concentration (ng/m <sup>3</sup> )	Nickel Concentration (ng/m <sup>3</sup> )	Zinc Concentration (ng/m <sup>3</sup> )	Exceeds Target	Exceeds EPA Site Specific	Comments
									14,000	5,000	20	40	600	10,000	1,500	500	200	16,000	Air Quality Levels	Site Specific Levels	
EPA Site Specific Trigger Levels									14,000	5,000	20	40	600	10,000	1,500	500	200	16,000			
METALS-ST11-4/28/08	G8D300236001	Southwest Area (sidewalk bridge level)	4/28/08	1732.9	Metals	6020	STL-SAC	4/30/08	2.2	< 69.2	< 0.69	< 0.69	< 6.9	126	7.2	11.4	5.4	51.2	No	No	
METALS-ST12-4/28/08	G8D300236002	Southeast Area (sidewalk bridge level)	4/28/08	1810.7	Metals	6020	STL-SAC	4/30/08	2.9	< 66.3	< 0.66	< 0.66	< 6.6	205	6.4	24.9	6.4	52.0	No	No	
METALS-ST15-4/28/08	G8D300236003	Firehouse #10 (roof level)	4/28/08	1814.9	Metals	6020	STL-SAC	4/30/08	1.9	< 66.1	< 0.66	< 0.66	< 6.6	124	5.1	14.7	5.7	38.2	No	No	
METALS-ST10-4/28/08	G8D300236004	North Side Sidewalk Bridge	4/28/08	1781.5	Metals	6020	STL-SAC	4/30/08	1.9	< 67.4	< 0.67	< 0.67	< 6.7	134	6.1	12.8	5.5	36.2	No	No	
METALS-ST11-4/28/08	G8D300236005	90 Trinity Place (roof level)	4/28/08	1742.7	Metals	6020	STL-SAC	4/30/08	1.9	< 68.8	< 0.68	< 0.68	< 6.9	194	3.6	5.2	5.2	27.5	No	No	
METALS-ST12-4/28/08	G8D300236006	110 Greenwich Street (roof level)	4/28/08	1756.8	Metals	6020	STL-SAC	4/30/08	1.8	< 68.3	< 0.68	< 0.68	< 6.8	2980	4.6	13.3	5.7	29.4	No	No	
METALS-ST13-4/28/08	G8D300236007	Marriott Hotel, 38th Floor (roof level)	4/28/08	1823.5	Metals	6020	STL-SAC	4/30/08	1.4	< 65.8	< 0.66	< 0.66	< 6.6	31.5	3.3	6.0	5.6	24.5	No	No	
METALS-ST14-4/28/08	G8D300236008	West Face - South end at corner (scaffolding level)	4/28/08	1781.9	Metals	6020	STL-SAC	4/30/08	1.6	< 67.3	< 0.67	< 0.67	< 6.7	40.7	6.1	12.2	9.2	72.2	No	No	
METALS-ST15-4/28/08	G8D300236009	South Face - East end at corner (scaffolding level)	4/28/08	1729.2	Metals	6020	STL-SAC	4/30/08	1.7	< 69.4	< 0.69	< 0.69	< 6.9	731	6.0	4.9	4.9	53.2	No	No	
METALS-ST16-4/28/08	G8D300236010	East Face - North end at corner (scaffolding level)	4/28/08	1752	Metals	6020	STL-SAC	4/30/08	1.4	< 68.5	< 0.68	< 0.68	< 6.8	760	3.5	7.8	4.4	23.1	No	No	
METALS-ST17-4/28/08	G8D300236011	North Face - West end at corner (scaffolding level)	4/28/08	1724.9	Metals	6020	STL-SAC	4/30/08	1.5	< 69.6	< 0.70	< 0.70	< 7.0	161	4.6	9.4	4.4	39.6	No	No	
METALS-ST11-4/29/08	G8E010203001	Southwest Area (sidewalk bridge level)	4/29/08	1760.8	Metals	6020	STL-SAC	5/1/08	1.5	< 68.2	< 0.68	< 0.68	< 6.8	454	7.0	11.4	< 3.4	47.2	No	No	
METALS-ST12-4/29/08	G8E010203002	Southeast Area (sidewalk bridge level)	4/29/08	1776.1	Metals	6020	STL-SAC	5/1/08	2.7	< 67.6	< 0.68	< 0.68	< 6.8	246	8.7	36.4	3.6	56.4	No	No	
METALS-ST14-4/29/08	G8E010203003	Northwest Area (street-level)	4/29/08	1797.9	Metals	6020	STL-SAC	5/1/08	< 1.3	< 66.7	< 0.67	< 0.67	< 6.7	410	6.7	10.8	< 3.3	49.2	No	No	
METALS-ST15-4/29/08	G8E010203004	Firehouse #10 (roof level)	4/29/08	1726.4	Metals	6020	STL-SAC	5/1/08	< 1.4	< 69.5	< 0.70	< 0.70	< 7.0	554	4.2	15.7	< 3.5	41.4	No	No	
METALS-ST10-4/29/08	G8E010203005	North Side Sidewalk Bridge	4/29/08	1751.3	Metals	6020	STL-SAC	5/1/08	< 1.4	< 68.5	< 0.68	< 0.68	< 6.8	236	5.0	18.4	< 3.4	51.5	No	No	
METALS-ST11-4/29/08	G8E010203006	90 Trinity Place (roof level)	4/29/08	1759.1	Metals	6020	STL-SAC	5/1/08	< 1.4	< 68.2	< 0.68	< 0.68	< 6.8	230	4.3	12.9	< 3.4	31.4	No	No	
METALS-ST13-4/29/08	G8E010203007	Marriott Hotel, 38th Floor (roof level)	4/29/08	1728.7	Metals	6020	STL-SAC	5/1/08	< 1.4	< 69.4	< 0.69	< 0.69	< 6.9	35.7	3.4	9.8	< 3.5	21.0	No	No	
METALS-ST14-4/29/08	G8E010203008	West Face - South end at corner (scaffolding level)	4/29/08	1795.5	Metals	6020	STL-SAC	5/1/08	< 1.3	< 66.8	< 0.67	< 0.67	< 6.7	59.8	4.9	13.8	< 3.3	36.4	No	No	
METALS-ST15-4/29/08	G8E010203009	South Face - East end at corner (scaffolding level)	4/29/08	1779	Metals	6020	STL-SAC	5/1/08	1.8	< 67.4	< 0.67	< 0.67	< 6.7	456	5.7	22.8	< 3.4	47.2	No	No	
METALS-ST16-4/29/08	G8E010203010	East Face - North end at corner (scaffolding level)	4/29/08	1747.3	Metals	6020	STL-SAC	5/1/08	< 1.4	< 68.7	< 0.69	< 0.69	< 6.9	6130	3.8	12.0	< 3.4	35.8	No	No	
METALS-ST17-4/29/08	G8E010203011	North Face - West end at corner (scaffolding level)	4/29/08	1768.1	Metals	6020	STL-SAC	5/1/08	< 1.4	< 67.9	< 0.68	< 0.68	< 6.8	170	4.6	13.5	< 3.4	45.5	No	No	

Note:  
1. Metals sample at Station 4 (Northwest Area [street-level]) on April 28, 2008 was not available for analysis on account of pump failure.  
2. Metals sample at Station 12 (110 Greenwich Street [roof level]) on April 29, 2008 was not available for analysis on account of pump failure.