

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target	Exceeds EPA	Comments	
									5,000	5,000	20	40	600	10,000	1,500	500	200	16,000				
EPA Site Specific Trigger Levels									14,000	5,000	20	2,000	600	100,000	5,000	500	28,000	160,000	Air Quality	Site Specific	Comments	
									Levels	Trigger Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels	Levels
METALS-ST1-10/9/06	G6J10174001	Southwest Area (sidewalk bridge level)	10/9/06	1745.7	Metals	6020	STL-SAC	10/11/06	4.9	< 68.7	< 0.69	< 0.69	< 6.9	142	46.9	24.5	9.4	104	No	No		
METALS-ST2-10/9/06	G6J10174002	Southeast Area (sidewalk bridge level)	10/9/06	1705.5	Metals	6020	STL-SAC	10/11/06	4.8	< 70.4	< 0.70	< 0.70	< 7.0	490	36.4	28.1	9.4	94.4	No	No		
METALS-ST4-10/9/06	G6J10174003	Northwest Area (street-level)	10/9/06	1821.3	Metals	6020	STL-SAC	10/11/06	4.0	< 65.9	< 0.66	< 0.66	< 6.6	196	33.7	20.3	8.1	75.4	No	No		
METALS-ST5-10/9/06	G6J10174004	Firehouse #10 (roof level)	10/9/06	1842.8	Metals	6020	STL-SAC	10/11/06	4.2	< 65.1	< 0.65	< 0.65	< 6.5	82.1	32.3	30.0	9.6	93.9	No	No		
METALS-ST10-10/9/06	G6J10174005	North Side Sidewalk Bridge	10/9/06	1786.4	Metals	6020	STL-SAC	10/11/06	4.4	< 67.2	< 0.67	< 0.67	< 6.7	218	30.2	29.1	9.3	85.3	No	No		
METALS-ST11-10/9/06	G6J10174006	90 Trinity Place (roof level)	10/9/06	1810.5	Metals	6020	STL-SAC	10/11/06	3.6	< 66.3	< 0.66	< 0.66	< 6.6	105	30.5	20.5	9.3	77.5	No	No		
METALS-ST12-10/9/06	G6J10174007	110 Greenwich Street (roof level)	10/9/06	1760.9	Metals	6020	STL-SAC	10/11/06	4.2	< 68.1	< 0.68	< 0.68	< 6.8	155	34.4	23.2	9.3	90.7	No	No		
METALS-ST13-10/9/06	G6J10174008	Marrion Hotel, 38th Floor (roof level)	10/9/06	1756	Metals	6020	STL-SAC	10/11/06	3.2	< 68.3	< 0.68	< 0.68	< 6.8	94.1	27.2	18.0	7.8	73.0	No	No		
METALS-ST14-10/9/06	G6J10174009	West Face - South end at corner (scaffolding level)	10/9/06	1789.9	Metals	6020	STL-SAC	10/11/06	3.2	< 67.0	< 0.67	< 0.67	< 6.7	75.6	33.7	17.6	7.0	62.8	No	No		
METALS-ST15-10/9/06	G6J10174010	South Face - East end at corner (scaffolding level)	10/9/06	1790.1	Metals	6020	STL-SAC	10/11/06	3.2	< 67.0	< 0.67	< 0.67	< 6.7	167	37.6	19.2	7.1	69.2	No	No		
METALS-ST16-10/9/06	G6J10174011	East Face - North end at corner (scaffolding level)	10/9/06	1791.1	Metals	6020	STL-SAC	10/11/06	3.5	< 67.0	< 0.67	< 0.67	< 6.7	46.0	29.4	19.4	7.5	69.0	No	No		
METALS-ST17-10/9/06	G6J10174012	North Face - West end at corner (scaffolding level)	10/9/06	1800	Metals	6020	STL-SAC	10/11/06	3.4	< 66.7	< 0.67	< 0.67	< 6.7	246	25.3	20.2	7.2	68.5	No	No		
METALS-ST1-10/10/06	G6J20172001	Southwest Area (sidewalk bridge level)	10/10/06	1805.5	Metals	6020	STL-SAC	10/12/06	4.5	< 66.5	< 0.66	< 0.66	< 6.6	198	62.7	31.7	96.5	No	No			
METALS-ST2-10/10/06	G6J20172002	Southwest Area (sidewalk bridge level)	10/10/06	1769.9	Metals	6020	STL-SAC	10/12/06	5.9	109	< 0.68	< 0.68	< 6.8	52.1	56.8	60.5	11.2	69.2	No	No		
METALS-ST4-10/10/06	G6J20172003	Northwest Area (street-level)	10/10/06	1794.3	Metals	6020	STL-SAC	10/12/06	4.1	< 66.9	< 0.67	< 0.67	< 6.7	103	32.4	30.3	9.1	81.4	No	No		
METALS-ST5-10/10/06	G6J20172004	Firehouse #10 (roof level)	10/10/06	1839.3	Metals	6020	STL-SAC	10/12/06	4.0	< 65.2	< 0.65	< 0.65	< 6.5	114	26.3	33.2	9.9	79.9	No	No		
METALS-ST10-10/10/06	G6J20172005	North Side Sidewalk Bridge	10/10/06	1764.7	Metals	6020	STL-SAC	10/12/06	4.0	< 68.0	< 0.68	< 0.68	< 6.8	238	35.6	34.9	9.7	76.9	No	No		
METALS-ST11-10/10/06	G6J20172006	90 Trinity Place (roof level)	10/10/06	1806.7	Metals	6020	STL-SAC	10/12/06	4.5	< 66.4	< 0.66	< 0.66	< 6.6	132	92.4	25.4	8.7	74.8	No	No		
METALS-ST12-10/10/06	G6J20172007	110 Greenwich Street (roof level)	10/10/06	1756.6	Metals	6020	STL-SAC	10/12/06	4.2	< 68.3	< 0.68	< 0.68	< 6.8	134	49.1	23.4	8.8	70.7	No	No		
METALS-ST13-10/10/06	G6J20172008	Marrion Hotel, 38th Floor (roof level)	10/10/06	1800	Metals	6020	STL-SAC	10/12/06	3.3	< 66.7	< 0.67	< 0.67	< 6.7	81.4	18.3	19.1	7.4	63.9	No	No		
METALS-ST14-10/10/06	G6J20172009	West Face - South end at corner (scaffolding level)	10/10/06	1764.6	Metals	6020	STL-SAC	10/12/06	3.3	< 68.0	< 0.68	< 0.68	< 6.8	75.3	17.4	19.4	8.2	57.1	No	No		
METALS-ST15-10/10/06	G6J20172010	South Face - East end at corner (scaffolding level)	10/10/06	1756.5	Metals	6020	STL-SAC	10/12/06	3.4	< 68.3	< 0.68	< 0.68	< 6.8	232	26.0	19.4	8.6	63.0	No	No		
METALS-ST16-10/10/06	G6J20172011	East Face - North end at corner (scaffolding level)	10/10/06	1773.9	Metals	6020	STL-SAC	10/12/06	3.1	< 67.6	< 0.68	< 0.68	< 6.8	36.6	26.0	18.3	8.1	56.8	No	No		
METALS-ST17-10/10/06	G6J20172012	North Face - West end at corner (scaffolding level)	10/10/06	1782.8	Metals	6020	STL-SAC	10/12/06	3.0	< 67.3	< 0.67	< 0.67	< 6.7	257	17.5	19.7	7.8	69.3	No	No		