

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m ³)	Barium Concentration (ng/m ³)	Beryllium Concentration (ng/m ³)	Cadmium Concentration (ng/m ³)	Chromium (Total) Concentration (ng/m ³)	Copper Concentration (ng/m ³)	Lead Concentration (ng/m ³)	Manganese Concentration (ng/m ³)	Nickel Concentration (ng/m ³)	Zinc Concentration (ng/m ³)	Exceeds Target Air Quality	Exceeds EPA Site Specific Trigger Levels	Comments
									5,000	5,000	200	40	600	10,000	1,500	500	200	16,000			
									14,000	5,000	200	2,000	600	100,000	5,000	500	28,000	160,000			
METALS-ST11-10/23/06	G6J250277001	Southwest Area (sidewalk bridge level)	10/23/06	1768.8	Metals	6020	STL-SAC	10/25/06	1.4	< 67.8	< 0.68	< 0.68	< 6.8	108	20.6	11.2	3.8	40.6	No	No	
METALS-ST2-10/23/06	G6J250277002	Southeast Area (sidewalk bridge level)	10/23/06	1759.2	Metals	6020	STL-SAC	10/25/06	1.7	< 68.2	< 0.68	< 0.68	< 6.8	294	12.0	17.9	5.2	40.1	No	No	
METALS-ST4-10/23/06	G6J250277003	Northwest Area (street-level)	10/23/06	1767.4	Metals	6020	STL-SAC	10/25/06	1.4	< 67.9	< 0.68	< 0.68	< 6.8	140	70.2	17.8	3.7	58.5	No	No	
METALS-ST5-10/23/06	G6J250277004	Firehouse #10 (roof level)	10/23/06	1773.8	Metals	6020	STL-SAC	10/25/06	1.5	< 67.6	< 0.68	< 0.68	< 6.8	114	17.5	28.8	5.0	48.5	No	No	
METALS-ST10-10/23/06	G6J250277005	North Side Sidewalk Bridge	10/23/06	1765.4	Metals	6020	STL-SAC	10/25/06	1.4	< 68.0	< 0.68	< 0.68	< 6.8	93.2	16.9	20.8	3.8	48.5	No	No	
METALS-ST10-10/23/06	G6J250277012	Station 10 Field Duplicate	10/23/06	1812.1	Metals	6020	STL-SAC	10/25/06	< 1.3	< 68.2	< 0.66	< 0.66	6.6	169	16.7	22.3	3.6	42.4	No	No	
METALS-ST11-10/23/06	G6J250277006	90 Trinity Place (roof level)	10/23/06	1759.5	Metals	6020	STL-SAC	10/25/06	< 1.4	< 68.2	< 0.68	< 0.68	< 6.8	102	8.9	11.4	5.1	30.5	No	No	
METALS-ST13-10/23/06	G6J250277007	Marrick Hotel, 38th Floor (roof level)	10/23/06	1759.3	Metals	6020	STL-SAC	10/25/06	< 1.4	< 68.2	< 0.68	< 0.68	< 6.8	120	7.0	9.4	4.0	30.8	No	No	
METALS-ST14-10/23/06	G6J250277008	West Face - South end at corner (scaffolding level)	10/23/06	1805.8	Metals	6020	STL-SAC	10/25/06	< 1.3	< 68.4	< 0.66	< 0.66	48.4	67.1	17.0	50.3	< 3.3	26.5	No	No	
METALS-ST15-10/23/06	G6J250277009	South Face - East end at corner (scaffolding level)	10/23/06	1797	Metals	6020	STL-SAC	10/25/06	< 1.3	< 67.2	< 0.67	< 0.67	< 6.7	80.1	8.7	8.9	3.6	28.5	No	No	
METALS-ST16-10/23/06	G6J250277010	East Face - North end at corner (scaffolding level)	10/23/06	1793	Metals	6020	STL-SAC	10/25/06	< 1.3	< 66.9	< 0.67	< 0.67	< 6.7	309	14.1	11.6	4.2	27.4	No	No	
METALS-ST17-10/23/06	G6J250277011	North Face - West end at corner (scaffolding level)	10/23/06	1752.2	Metals	6020	STL-SAC	10/25/06	< 1.4	< 68.5	< 0.68	< 0.68	< 6.8	161	6.6	7.1	< 3.4	25.6	No	No	
METALS-ST1-10/24/06	G6J260152001	Southwest Area (sidewalk bridge level)	10/24/06	1757	Metals	6020	STL-SAC	10/26/06	< 1.4	< 68.3	< 0.68	< 0.68	< 6.8	86.7	25.3	13.2	4.7	40.0	No	No	
METALS-ST2-10/24/06	G6J260152002	Southeast Area (sidewalk bridge level)	10/24/06	1781.9	Metals	6020	STL-SAC	10/26/06	2.5	< 67.3	< 0.67	< 0.67	< 6.7	122	29.1	41.5	8.2	228	No	No	
METALS-ST4-10/24/06	G6J260152003	Northwest Area (street-level)	10/24/06	1736.8	Metals	6020	STL-SAC	10/26/06	< 1.4	< 69.1	< 0.69	< 0.69	< 6.9	85.1	59.4	20.1	4.7	52.0	No	No	
METALS-ST5-10/24/06	G6J260152004	Firehouse #10 (roof level)	10/24/06	1791.6	Metals	6020	STL-SAC	10/26/06	1.4	< 67.0	< 0.67	< 0.67	< 6.7	73.5	36.4	30.8	5.3	53.9	No	No	
METALS-ST10-10/24/06	G6J260152005	North Side Sidewalk Bridge	10/24/06	1780	Metals	6020	STL-SAC	10/26/06	1.4	< 67.4	< 0.67	< 0.67	< 6.7	49.1	83.0	25.5	4.8	47.3	No	No	
METALS-ST11-10/24/06	G6J260152006	90 Trinity Place (roof level)	10/24/06	1773.5	Metals	6020	STL-SAC	10/26/06	< 1.4	< 67.7	< 0.68	< 0.68	< 6.8	51.5	10.2	14.2	6.0	30.9	No	No	
METALS-ST13-10/24/06	G6J260152007	Marrick Hotel, 38th Floor (roof level)	10/24/06	1814.6	Metals	6020	STL-SAC	10/26/06	< 1.3	< 66.1	< 0.66	< 0.66	< 6.6	57.1	6.8	11.5	4.8	25.5	No	No	
METALS-ST14-10/24/06	G6J260152008	West Face - South end at corner (scaffolding level)	10/24/06	1814.4	Metals	6020	STL-SAC	10/26/06	< 1.3	< 66.1	< 0.66	< 0.66	< 6.6	86.2	6.4	8.4	< 3.3	23.8	No	No	
METALS-ST15-10/24/06	G6J260152009	South Face - East end at corner (scaffolding level)	10/24/06	1763	Metals	6020	STL-SAC	10/26/06	< 1.4	< 68.1	< 0.68	< 0.68	< 6.8	41.5	9.2	13.2	4.7	36.7	No	No	
METALS-ST16-10/24/06	G6J260152010	East Face - North end at corner (scaffolding level)	10/24/06	1817.9	Metals	6020	STL-SAC	10/26/06	< 1.3	< 66.0	< 0.66	< 0.66	< 6.6	297	9.2	14.4	4.8	35.2	No	No	
METALS-ST17-10/24/06	G6J260152011	North Face - West end at corner (scaffolding level)	10/24/06	1797.3	Metals	6020	STL-SAC	10/26/06	< 1.3	< 66.8	< 0.67	< 0.67	< 6.7	73.8	6.4	8.5	< 3.3	26.6	No	No	

Note:
1. Metals sample at Station 12 (110 Greenwich Street [roof level]) on October 23, 2006 was not available on account of temporary power failure.
1. Metals sample at Station 12 (110 Greenwich Street [roof level]) on October 24, 2006 was not available on account of pump failure.