

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-1/26/08	030802326-0001	Southwest Area (sidewalk bridge level)	1/26/08	1	3.040	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST2-1/26/08	030802326-0002	Southeast Area (sidewalk bridge level)	1/26/08	1	2.970	Asbestos	PCME	EMSL	1/28/08	< 0.00083	No	No	
ASBESTOS-ST4-1/26/08	030802326-0003	Northwest Area (street-level)	1/26/08	1	3.040	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST5-1/26/08	030802326-0004	Firehouse #10 (roof level)	1/26/08	1	3.010	Asbestos	PCME	EMSL	1/28/08	< 0.00082	No	No	
ASBESTOS-ST10-1/26/08	030802326-0005	North Side Sidewalk Bridge	1/26/08	1	3.090	Asbestos	PCME	EMSL	1/28/08	< 0.00080	No	No	
ASBESTOS-ST11-1/26/08	030802326-0006	90 Trinity Place (roof level)	1/26/08	1	3.040	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST12-1/26/08	030802326-0007	110 Greenwich Street (roof level)	1/26/08	1	3.030	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST13-1/26/08	030802326-0008	Marriott Hotel, 38th Floor (roof level)	1/26/08	1	3.040	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST14-1/26/08	030802326-0009	West Face - South end at corner (scaffolding level)	1/26/08	1	3.010	Asbestos	PCME	EMSL	1/28/08	< 0.00082	No	No	
ASBESTOS-ST15-1/26/08	030802326-0010	South Face - East end at corner (scaffolding level)	1/26/08	1	3.000	Asbestos	PCME	EMSL	1/28/08	< 0.00082	No	No	
ASBESTOS-ST16-1/26/08	030802326-0011	East Face - North end at corner (scaffolding level)	1/26/08	1	3.010	Asbestos	PCME	EMSL	1/28/08	< 0.00082	No	No	
ASBESTOS-ST17-1/26/08	030802324-0012	North Face - West end at corner (scaffolding level)	1/26/08	1	3.020	Asbestos	PCME	EMSL	1/28/08	< 0.00082	No	No	
ASBESTOS-ST1-1/27/08	030802324-0001	Southwest Area (sidewalk bridge level)	1/27/08	1	3.060	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST2-1/27/08	030802324-0002	Southeast Area (sidewalk bridge level)	1/27/08	1	3.310	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST4-1/27/08	030802324-0003	Northwest Area (street-level)	1/27/08	1	3.060	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST5-1/27/08	030802324-0004	Firehouse #10 (roof level)	1/27/08	1	2.510	Asbestos	PCME	EMSL	1/28/08	< 0.00084	No	No	Note 1
ASBESTOS-ST10-1/27/08	030802324-0005	North Side Sidewalk Bridge	1/27/08	1	2.970	Asbestos	PCME	EMSL	1/28/08	< 0.00083	No	No	
ASBESTOS-ST11-1/27/08	030802324-0006	90 Trinity Place (roof level)	1/27/08	1	3.010	Asbestos	PCME	EMSL	1/28/08	< 0.00082	No	No	
ASBESTOS-ST12-1/27/08	030802324-0007	110 Greenwich Street (roof level)	1/27/08	1	3.000	Asbestos	PCME	EMSL	1/28/08	< 0.00082	No	No	
ASBESTOS-ST13-1/27/08	030802324-0008	Marriott Hotel, 38th Floor (roof level)	1/27/08	1	2.940	Asbestos	PCME	EMSL	1/28/08	< 0.00084	No	No	
ASBESTOS-ST14-1/27/08	030802324-0009	West Face - South end at corner (scaffolding level)	1/27/08	1	2.980	Asbestos	PCME	EMSL	1/28/08	< 0.00083	No	No	
ASBESTOS-ST15-1/27/08	030802324-0010	South Face - East end at corner (scaffolding level)	1/27/08	1	3.040	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST16-1/27/08	030802324-0011	East Face - North end at corner (scaffolding level)	1/27/08	1	3.010	Asbestos	PCME	EMSL	1/28/08	< 0.00082	No	No	
ASBESTOS-ST17-1/27/08	030802324-0012	North Face - West end at corner (scaffolding level)	1/27/08	1	3.050	Asbestos	PCME	EMSL	1/28/08	< 0.00081	No	No	
ASBESTOS-ST1-1/28/08	030802419-0001	Southwest Area (sidewalk bridge level)	1/28/08	1	3.590	Asbestos	PCME	EMSL	1/29/08	< 0.00082	No	No	Note 2
ASBESTOS-ST2-1/28/08	030802419-0002	Southeast Area (sidewalk bridge level)	1/28/08	1	3.020	Asbestos	PCME	EMSL	1/29/08	< 0.00082	No	No	
ASBESTOS-ST4-1/28/08	030802419-0003	Northwest Area (street-level)	1/28/08	1	3.070	Asbestos	PCME	EMSL	1/29/08	< 0.00080	No	No	
ASBESTOS-ST5-1/28/08	030802419-0004	Firehouse #10 (roof level)	1/28/08	1	3.190	Asbestos	PCME	EMSL	1/29/08	< 0.00077	No	No	
ASBESTOS-ST10-1/28/08	030802419-0005	North Side Sidewalk Bridge	1/28/08	1	2.880	Asbestos	PCME	EMSL	1/29/08	< 0.00086	No	No	
ASBESTOS-ST11-1/28/08	030802419-0006	90 Trinity Place (roof level)	1/28/08	1	3.040	Asbestos	PCME	EMSL	1/29/08	< 0.00081	No	No	
ASBESTOS-ST12-1/28/08	030802419-0007	110 Greenwich Street (roof level)	1/28/08	1	3.060	Asbestos	PCME	EMSL	1/29/08	< 0.00081	No	No	
ASBESTOS-ST13-1/28/08	030802419-0008	Marriott Hotel, 38th Floor (roof level)	1/28/08	1	3.000	Asbestos	PCME	EMSL	1/29/08	< 0.00082	No	No	
ASBESTOS-ST14-1/28/08	030802419-0009	West Face - South end at corner (scaffolding level)	1/28/08	1	2.950	Asbestos	PCME	EMSL	1/29/08	< 0.00084	No	No	
ASBESTOS-ST15-1/28/08	030802419-0010	South Face - East end at corner (scaffolding level)	1/28/08	1	3.020	Asbestos	PCME	EMSL	1/29/08	< 0.00082	No	No	
ASBESTOS-ST16-1/28/08	030802419-0011	East Face - North end at corner (scaffolding level)	1/28/08	1	3.020	Asbestos	PCME	EMSL	1/29/08	< 0.00082	No	No	
ASBESTOS-ST17-1/28/08	030802419-0012	North Face - West end at corner (scaffolding level)	1/28/08	1	3.070	Asbestos	PCME	EMSL	1/29/08	< 0.00080	No	No	
ASBESTOS-ST1-1/29/08	030802494-0001	Southwest Area (sidewalk bridge level)	1/29/08	1	3.010	Asbestos	PCME	EMSL	1/30/08	< 0.00082	No	No	
ASBESTOS-ST2-1/29/08	030802494-0002	Southeast Area (sidewalk bridge level)	1/29/08	1	3.000	Asbestos	PCME	EMSL	1/30/08	< 0.00082	No	No	
ASBESTOS-ST4-1/29/08	030802494-0003	Northwest Area (street-level)	1/29/08	1	3.030	Asbestos	PCME	EMSL	1/30/08	< 0.00081	No	No	
ASBESTOS-ST5-1/29/08	030802494-0004	Firehouse #10 (roof level)	1/29/08	1	3.010	Asbestos	PCME	EMSL	1/30/08	< 0.00082	No	No	
ASBESTOS-ST10-1/29/08	030802494-0005	North Side Sidewalk Bridge	1/29/08	1	2.970	Asbestos	PCME	EMSL	1/30/08	< 0.00083	No	No	
ASBESTOS-ST11-1/29/08	030802494-0006	90 Trinity Place (roof level)	1/29/08	1	3.040	Asbestos	PCME	EMSL	1/30/08	< 0.00081	No	No	
ASBESTOS-ST12-1/29/08	030802494-0007	110 Greenwich Street (roof level)	1/29/08	1	3.060	Asbestos	PCME	EMSL	1/30/08	< 0.00081	No	No	
ASBESTOS-ST13-1/29/08	030802494-0008	Marriott Hotel, 38th Floor (roof level)	1/29/08	1	2.990	Asbestos	PCME	EMSL	1/30/08	< 0.00083	No	No	
ASBESTOS-ST14-1/29/08	030802494-0009	West Face - South end at corner (scaffolding level)	1/29/08	1	3.020	Asbestos	PCME	EMSL	1/30/08	< 0.00082	No	No	
ASBESTOS-ST15-1/29/08	030802494-0010	South Face - East end at corner (scaffolding level)	1/29/08	1	3.040	Asbestos	PCME	EMSL	1/30/08	< 0.00081	No	No	
ASBESTOS-ST16-1/29/08	030802494-0011	East Face - North end at corner (scaffolding level)	1/29/08	1	3.000	Asbestos	PCME	EMSL	1/30/08	< 0.00082	No	No	
ASBESTOS-ST17-1/29/08	030802494-0012	North Face - West end at corner (scaffolding level)	1/29/08	1	3.000	Asbestos	PCME	EMSL	1/30/08	< 0.00082	No	No	

Note:

1. Due to flow rate RPD exceedance (40.6%) for asbestos at Station 5 (Firehouse #10 [roof level]) on January 27, 2008 the sample volume and subsequent sample result are estimated.
2. Due to flow rate RPD exceedance (31.6%) for asbestos at Station 1 (Southwest Area [sidewalk bridge level]) on January 28, 2008 the sample volume and subsequent sample result are estimated.