

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm ³)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-4/3/06	030610235-0001	Southwest Area (sidewalk bridge level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST2-4/3/06	030610235-0002	Southeast Area (sidewalk bridge level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST4-4/3/06	030610235-0003	Northwest Area (street-level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST5-4/3/06	030610235-0004	Firehouse #10 (roof level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST10-4/3/06	030610235-0005	North Side Sidewalk Bridge	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST11-4/3/06	030610235-0006	90 Trinity Place (roof level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST12-4/3/06	030610235-0007	110 Greenwich Street (roof level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST13-4/3/06	030610235-0008	Marriott Hotel, 38th Floor (roof level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST14-4/3/06	030610235-0009	West Face - South end at corner (scaffolding level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST15-4/3/06	030610235-0010	South Face - East end at corner (scaffolding level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST16-4/3/06	030610235-0011	East Face - North end at corner (scaffolding level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST17-4/3/06	030610235-0012	North Face - West end at corner (scaffolding level)	4/3/06	1	3.000	Asbestos	PCME	EMSL	4/4/06	< 0.00082	No	No	
ASBESTOS-ST1-4/4/06	030610341-0001	Southwest Area (sidewalk bridge level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST2-4/4/06	030610341-0002	Southeast Area (sidewalk bridge level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST4-4/4/06	030610341-0003	Northwest Area (street-level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST5-4/4/06	030610341-0004	Firehouse #10 (roof level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST10-4/4/06	030610341-0005	North Side Sidewalk Bridge	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST100-4/4/06	030610341-0013	Station 10 Field Duplicate	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST11-4/4/06	030610341-0006	90 Trinity Place (roof level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST12-4/4/06	030610341-0007	110 Greenwich Street (roof level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST13-4/4/06	030610341-0008	Marriott Hotel, 38th Floor (roof level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST14-4/4/06	030610341-0009	West Face - South end at corner (scaffolding level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST15-4/4/06	030610341-0010	South Face - East end at corner (scaffolding level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST17-4/4/06	030610341-0012	North Face - West end at corner (scaffolding level)	4/4/06	1	3.000	Asbestos	PCME	EMSL	4/5/06	< 0.00082	No	No	
ASBESTOS-ST1-4/5/06	030610439-0001	Southwest Area (sidewalk bridge level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST2-4/5/06	030610439-0002	Southeast Area (sidewalk bridge level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST4-4/5/06	030610439-0003	Northwest Area (street-level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST5-4/5/06	030610439-0004	Firehouse #10 (roof level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST10-4/5/06	030610439-0005	North Side Sidewalk Bridge	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST11-4/5/06	030610439-0006	90 Trinity Place (roof level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST12-4/5/06	030610439-0007	110 Greenwich Street (roof level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST13-4/5/06	030610439-0008	Marriott Hotel, 38th Floor (roof level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST14-4/5/06	030610439-0009	West Face - South end at corner (scaffolding level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST15-4/5/06	030610439-0010	South Face - East end at corner (scaffolding level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST16-4/5/06	030610439-0011	East Face - North end at corner (scaffolding level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	
ASBESTOS-ST17-4/5/06	030610439-0012	North Face - West end at corner (scaffolding level)	4/5/06	1	3.000	Asbestos	PCME	EMSL	4/6/06	< 0.00082	No	No	

Note:

1. Asbestos sample on April 4, 2006 at Station 16 (East Face - North end at corner [scaffolding level]) was not available for analysis on account of filter damage.