

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target	Exceeds EPA	Comments
										0.0009	Air Quality Levels	Site Specific Trigger Levels	
										NA			
ASBESTOS-ST1-7/20/06	030622811-0001	Southwest Area (sidewalk bridge level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST2-7/20/06	030622811-0002	Southeast Area (sidewalk bridge level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST4-7/20/06	030622811-0003	Northwest Area (street-level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST5-7/20/06	030622811-0004	Firehouse #10 (roof level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST6-7/20/06	030622796-0001	Southwest Area (roof level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST7-7/20/06	030622796-0002	Southeast Area (roof level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST8-7/20/06	030622796-0003	Northeast Area (roof level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST9-7/20/06	030622796-0004	Northwest Area (roof level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST10-7/20/06	030622811-0005	North Side Sidewalk Bridge	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST11-7/20/06	030622811-0006	90 Trinity Place (roof level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST12-7/20/06	030622811-0007	110 Greenwich Street (roof level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST13-7/20/06	030622811-0008	Marriott Hotel, 38th Floor (roof level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST14-7/20/06	030622811-0009	West Face - South end at corner (scaffolding level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST15-7/20/06	030622811-0010	South Face - East end at corner (scaffolding level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST16-7/20/06	030622811-0011	East Face - North end at corner (scaffolding level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST17-7/20/06	030622811-0012	North Face - West end at corner (scaffolding level)	7/20/06	1	2.940	Asbestos	PCME	EMSL	7/21/06	< 0.00084	No	No	
ASBESTOS-ST1-7/21/06	030623118-0001	Southwest Area (sidewalk bridge level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST2-7/21/06	030623118-0002	Southeast Area (sidewalk bridge level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST4-7/21/06	030623118-0003	Northwest Area (street-level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST5-7/21/06	030623118-0004	Firehouse #10 (roof level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST6-7/21/06	030623120-0001	Southwest Area (roof level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST7-7/21/06	030623120-0002	Southeast Area (roof level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST8-7/21/06	030623120-0003	Northeast Area (roof level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST10-7/21/06	030623118-0005	North Side Sidewalk Bridge	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST100-7/21/06	030623118-0013	Station 10 Field Duplicate	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST11-7/21/06	030623118-0006	90 Trinity Place (roof level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST12-7/21/06	030623118-0007	110 Greenwich Street (roof level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST13-7/21/06	030623118-0008	Marriott Hotel, 38th Floor (roof level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST14-7/21/06	030623118-0009	West Face - South end at corner (scaffolding level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST15-7/21/06	030623118-0010	South Face - East end at corner (scaffolding level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST16-7/21/06	030623118-0011	East Face - North end at corner (scaffolding level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST17-7/21/06	030623118-0012	North Face - West end at corner (scaffolding level)	7/21/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST1-7/22/06	030623107-0001	Southwest Area (sidewalk bridge level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST4-7/22/06	030623107-0003	Northwest Area (street-level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST5-7/22/06	030623107-0004	Firehouse #10 (roof level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST6-7/22/06	030623111-0001	Southwest Area (roof level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST7-7/22/06	030623111-0002	Southeast Area (roof level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST8-7/22/06	030623111-0003	Northeast Area (roof level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST9-7/22/06	030623111-0004	Northwest Area (roof level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST10-7/22/06	030623107-0005	North Side Sidewalk Bridge	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST11-7/22/06	030623107-0006	90 Trinity Place (roof level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST12-7/22/06	030623107-0007	110 Greenwich Street (roof level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST13-7/22/06	030623107-0008	Marriott Hotel, 38th Floor (roof level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST14-7/22/06	030623107-0009	West Face - South end at corner (scaffolding level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST15-7/22/06	030623107-0010	South Face - East end at corner (scaffolding level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST16-7/22/06	030623107-0011	East Face - North end at corner (scaffolding level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST17-7/22/06	030623107-0012	North Face - West end at corner (scaffolding level)	7/22/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST1-7/23/06	030623117-0001	Southwest Area (sidewalk bridge level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST2-7/23/06	030623117-0002	Southeast Area (sidewalk bridge level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST4-7/23/06	030623117-0003	Northwest Area (street-level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST5-7/23/06	030623117-0004	Firehouse #10 (roof level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST6-7/23/06	030623115-0001	Southwest Area (roof level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST7-7/23/06	030623115-0002	Southeast Area (roof level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST8-7/23/06	030623115-0003	Northeast Area (roof level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST9-7/23/06	030623115-0004	Northwest Area (roof level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST10-7/23/06	030623117-0005	North Side Sidewalk Bridge	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST11-7/23/06	030623117-0006	90 Trinity Place (roof level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST12-7/23/06	030623117-0007	110 Greenwich Street (roof level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST13-7/23/06	030623117-0008	Marriott Hotel, 38th Floor (roof level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST14-7/23/06	030623117-0009	West Face - South end at corner (scaffolding level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST15-7/23/06	030623117-0010	South Face - East end at corner (scaffolding level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST16-7/23/06	030623117-0011	East Face - North end at corner (scaffolding level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	
ASBESTOS-ST17-7/23/06	030623117-0012	North Face - West end at corner (scaffolding level)	7/23/06	1	2.940	Asbestos	PCME	EMSL	7/24/06	< 0.00084	No	No	

Notes:

- Asbestos sample at Station 9 (Northwest Area [roof level]) on July 21, 2006 was not available for analysis on account of sample damage. High winds overturned the sampling equipment damaging the sample.
- Asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on July 22, 2006 was not available for analysis on account of damaged filter.