

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm <sup>3</sup> )	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										0.0009			
										NA			
ASBESTOS-ST1-10/7/05	030530293-0001	Southwest Area (street-level)	10/7/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/7/05	030530293-0002	Southeast Area (street-level)	10/7/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/7/05	030530293-0003	Northwest Area (street-level)	10/7/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/7/05	030530293-0004	Firehouse #10 (roof level)	10/7/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/7/05	030530293-0005	North Side Sidewalk Bridge	10/7/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/7/05	030530293-0006	90 Trinity Place (roof level)	10/7/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/7/05	030530293-0007	110 Greenwich Street (roof level)	10/7/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/7/05	030530293-0008	Marriott Hotel, 38th Floor (roof level)	10/7/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST1-10/8/05	030530294-0001	Southwest Area (street-level)	10/8/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/8/05	030530294-0002	Southeast Area (street-level)	10/8/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/8/05	030530294-0003	Northwest Area (street-level)	10/8/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/8/05	030530294-0004	Firehouse #10 (roof level)	10/8/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/8/05	030530294-0005	North Side Sidewalk Bridge	10/8/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/8/05	030530294-0006	90 Trinity Place (roof level)	10/8/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/8/05	030530294-0007	110 Greenwich Street (roof level)	10/8/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/8/05	030530294-0008	Marriott Hotel, 38th Floor (roof level)	10/8/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST1-10/9/05	030530291-0001	Southwest Area (street-level)	10/9/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/9/05	030530291-0002	Southeast Area (street-level)	10/9/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/9/05	030530291-0003	Northwest Area (street-level)	10/9/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/9/05	030530291-0004	Firehouse #10 (roof level)	10/9/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/9/05	030530291-0005	North Side Sidewalk Bridge	10/9/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/9/05	030530291-0006	90 Trinity Place (roof level)	10/9/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/9/05	030530291-0007	110 Greenwich Street (roof level)	10/9/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/9/05	030530291-0008	Marriott Hotel, 38th Floor (roof level)	10/9/2005	1	2.890	Asbestos	PCME	EMSL	10/10/2005	< 0.00085	No	No	
ASBESTOS-ST1-10/10/05	030530400-0001	Southwest Area (street-level)	10/10/2005	1	2.890	Asbestos	PCME	EMSL	10/11/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/10/05	030530400-0002	Southeast Area (street-level)	10/10/2005	1	2.890	Asbestos	PCME	EMSL	10/11/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/10/05	030530400-0003	Northwest Area (street-level)	10/10/2005	1	2.890	Asbestos	PCME	EMSL	10/11/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/10/05	030530400-0004	Firehouse #10 (roof level)	10/10/2005	1	2.890	Asbestos	PCME	EMSL	10/11/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/10/05	030530400-0005	North Side Sidewalk Bridge	10/10/2005	1	2.890	Asbestos	PCME	EMSL	10/11/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/10/05	030530400-0006	90 Trinity Place (roof level)	10/10/2005	1	2.890	Asbestos	PCME	EMSL	10/11/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/10/05	030530400-0007	110 Greenwich Street (roof level)	10/10/2005	1	2.890	Asbestos	PCME	EMSL	10/11/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/10/05	030530400-0008	Marriott Hotel, 38th Floor (roof level)	10/10/2005	1	2.890	Asbestos	PCME	EMSL	10/11/2005	< 0.00085	No	No	
ASBESTOS-ST1-10/11/05	030530487-0001	Southwest Area (street-level)	10/11/2005	1	2.890	Asbestos	PCME	EMSL	10/12/2005	< 0.00085	No	No	
ASBESTOS-ST2-10/11/05	030530487-0002	Southeast Area (street-level)	10/11/2005	1	2.890	Asbestos	PCME	EMSL	10/12/2005	< 0.00085	No	No	
ASBESTOS-ST4-10/11/05	030530487-0003	Northwest Area (street-level)	10/11/2005	1	2.890	Asbestos	PCME	EMSL	10/12/2005	< 0.00085	No	No	
ASBESTOS-ST5-10/11/05	030530487-0004	Firehouse #10 (roof level)	10/11/2005	1	2.890	Asbestos	PCME	EMSL	10/12/2005	< 0.00085	No	No	
ASBESTOS-ST10-10/11/05	030530487-0005	North Side Sidewalk Bridge	10/11/2005	1	2.890	Asbestos	PCME	EMSL	10/12/2005	< 0.00085	No	No	
ASBESTOS-ST11-10/11/05	030530487-0006	90 Trinity Place (roof level)	10/11/2005	1	2.890	Asbestos	PCME	EMSL	10/12/2005	< 0.00085	No	No	
ASBESTOS-ST12-10/11/05	030530487-0007	110 Greenwich Street (roof level)	10/11/2005	1	2.890	Asbestos	PCME	EMSL	10/12/2005	< 0.00085	No	No	
ASBESTOS-ST13-10/11/05	030530487-0008	Marriott Hotel, 38th Floor (roof level)	10/11/2005	1	2.890	Asbestos	PCME	EMSL	10/12/2005	< 0.00085	No	No	