

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST1-12/9/05	030537038-0001	Southwest Area (sidewalk bridge level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST2-12/9/05	030537038-0002	Southeast Area (sidewalk bridge level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST4-12/9/05	030537038-0003	Northwest Area (street-level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST5-12/9/05	030537038-0004	Firehouse #10 (roof level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST10-12/9/05	030537038-0005	North Side Sidewalk Bridge	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST11-12/9/05	030537038-0006	90 Trinity Place (roof level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST12-12/9/05	030537038-0007	110 Greenwich Street (roof level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST13-12/9/05	030537038-0008	Marriott Hotel, 38th Floor (roof level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST14-12/9/05	030537038-0009	West Face - South end at corner (scaffolding level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST15-12/9/05	030537038-0010	South Face - East end at corner (scaffolding level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST16-12/9/05	030537038-0011	East Face - North end at corner (scaffolding level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST17-12/9/05	030537038-0012	North Face - West end at corner (scaffolding level)	12/9/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST1-12/10/05	030537039-0001	Southwest Area (sidewalk bridge level)	12/10/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST2-12/10/05	030537039-0002	Southeast Area (sidewalk bridge level)	12/10/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST4-12/10/05	030537039-0003	Northwest Area (street-level)	12/10/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST5-12/10/05	030537039-0004	Firehouse #10 (roof level)	12/10/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST10-12/10/05	030537039-0005	North Side Sidewalk Bridge	12/10/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST11-12/10/05	030537039-0006	90 Trinity Place (roof level)	12/10/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST12-12/10/05	030537039-0007	110 Greenwich Street (roof level)	12/10/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST13-12/10/05	030537039-0008	Marriott Hotel, 38th Floor (roof level)	12/10/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST1-12/11/05	030537037-0001	Southwest Area (sidewalk bridge level)	12/11/05	1	3.020	Asbestos	PCME	EMSL	12/12/05	< 0.00089	No	No	
ASBESTOS-ST2-12/11/05	030537037-0002	Southeast Area (sidewalk bridge level)	12/11/05	1	2.960	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST4-12/11/05	030537037-0003	Northwest Area (street-level)	12/11/05	1	3.020	Asbestos	PCME	EMSL	12/12/05	< 0.00089	No	No	
ASBESTOS-ST5-12/11/05	030537037-0004	Firehouse #10 (roof level)	12/11/05	1	3.020	Asbestos	PCME	EMSL	12/12/05	< 0.00089	No	No	
ASBESTOS-ST10-12/11/05	030537037-0005	North Side Sidewalk Bridge	12/11/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST11-12/11/05	030537037-0006	90 Trinity Place (roof level)	12/11/05	1	3.000	Asbestos	PCME	EMSL	12/12/05	< 0.00082	No	No	
ASBESTOS-ST12-12/11/05	030537037-0007	110 Greenwich Street (roof level)	12/11/05	1	3.080	Asbestos	PCME	EMSL	12/12/05	< 0.00087	No	No	
ASBESTOS-ST13-12/11/05	030537037-0008	Marriott Hotel, 38th Floor (roof level)	12/11/05	1	2.920	Asbestos	PCME	EMSL	12/12/05	< 0.00085	No	No	
ASBESTOS-ST14-12/11/05	030537037-0009	West Face - South end at corner (scaffolding level)	12/11/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST15-12/11/05	030537037-0010	South Face - East end at corner (scaffolding level)	12/11/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST16-12/11/05	030537037-0011	East Face - North end at corner (scaffolding level)	12/11/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST17-12/11/05	030537037-0012	North Face - West end at corner (scaffolding level)	12/11/05	1	2.970	Asbestos	PCME	EMSL	12/12/05	< 0.00083	No	No	
ASBESTOS-ST1-12/12/05	030537169-0001	Southwest Area (sidewalk bridge level)	12/12/05	1	3.070	Asbestos	PCME	EMSL	12/13/05	< 0.00080	No	No	
ASBESTOS-ST2-12/12/05	030537169-0002	Southeast Area (sidewalk bridge level)	12/12/05	1	2.970	Asbestos	PCME	EMSL	12/13/05	< 0.00083	No	No	
ASBESTOS-ST4-12/12/05	030537169-0003	Northwest Area (street-level)	12/12/05	1	3.000	Asbestos	PCME	EMSL	12/13/05	< 0.00082	No	No	
ASBESTOS-ST5-12/12/05	030537169-0004	Firehouse #10 (roof level)	12/12/05	1	1.390	Asbestos	PCME	EMSL	12/13/05	< 0.00082	No	No	Note 2
ASBESTOS-ST10-12/12/05	030537169-0005	North Side Sidewalk Bridge	12/12/05	1	2.970	Asbestos	PCME	EMSL	12/13/05	< 0.00083	No	No	
ASBESTOS-ST11-12/12/05	030537169-0006	90 Trinity Place (roof level)	12/12/05	1	2.970	Asbestos	PCME	EMSL	12/13/05	< 0.00083	No	No	
ASBESTOS-ST12-12/12/05	030537169-0007	110 Greenwich Street (roof level)	12/12/05	1	2.970	Asbestos	PCME	EMSL	12/13/05	< 0.00083	No	No	
ASBESTOS-ST14-12/12/05	030537169-0009	West Face - South end at corner (scaffolding level)	12/12/05	1	2.970	Asbestos	PCME	EMSL	12/13/05	< 0.00083	No	No	
ASBESTOS-ST15-12/12/05	030537169-0010	South Face - East end at corner (scaffolding level)	12/12/05	1	2.970	Asbestos	PCME	EMSL	12/13/05	< 0.00083	No	No	
ASBESTOS-ST16-12/12/05	030537169-0011	East Face - North end at corner (scaffolding level)	12/12/05	1	2.970	Asbestos	PCME	EMSL	12/13/05	< 0.00083	No	No	
ASBESTOS-ST17-12/12/05	030537169-0012	North Face - West end at corner (scaffolding level)	12/12/05	1	2.970	Asbestos	PCME	EMSL	12/13/05	< 0.00083	No	No	
ASBESTOS-ST1-12/13/05	030537315-0001	Southwest Area (sidewalk bridge level)	12/13/05	1	3.020	Asbestos	PCME	EMSL	12/14/05	< 0.00082	No	No	
ASBESTOS-ST2-12/13/05	030537315-0002	Southeast Area (sidewalk bridge level)	12/13/05	1	3.020	Asbestos	PCME	EMSL	12/14/05	< 0.00082	No	No	
ASBESTOS-ST4-12/13/05	030537315-0003	Northwest Area (street-level)	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST5-12/13/05	030537315-0004	Firehouse #10 (roof level)	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST10-12/13/05	030537315-0005	North Side Sidewalk Bridge	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST100-12/13/05	030537315-0013	Station 10 Field Duplicate	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST11-12/13/05	030537315-0006	90 Trinity Place (roof level)	12/13/05	1	3.000	Asbestos	PCME	EMSL	12/14/05	< 0.00082	No	No	
ASBESTOS-ST12-12/13/05	030537315-0007	110 Greenwich Street (roof level)	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST13-12/13/05	030537315-0008	Marriott Hotel, 38th Floor (roof level)	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST14-12/13/05	030537315-0009	West Face - South end at corner (scaffolding level)	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST15-12/13/05	030537315-0010	South Face - East end at corner (scaffolding level)	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST16-12/13/05	030537315-0011	East Face - North end at corner (scaffolding level)	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	
ASBESTOS-ST17-12/13/05	030537315-0012	North Face - West end at corner (scaffolding level)	12/13/05	1	2.970	Asbestos	PCME	EMSL	12/14/05	< 0.00083	No	No	

Notes

- On December 10, 2005, Stations 14 through 17 were moved from the 10th floor scaffolding level to the 20th floor scaffolding level and were temporarily disabled. No measurements were collected this day. No abatement activities took place on December 10, 2005. Work activities were limited to scaffolding erection.
- Reduced asbestos sample volume at Station 5 (Firehouse #10 [roof level]) on December 12, 2005 was due to pump failure caused by power outage.
- Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on December 12, 2005 was not available for analysis on account of sample damage.