TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-6/22/06	030619209-0001	Southwest Area (sidewalk bridge level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST2-6/22/06	030619209-0002	Southeast Area (sidewalk bridge level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST4-6/22/06	030619209-0003	Northwest Area (street-level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST5-6/22/06	030619209-0004	Firehouse #10 (roof level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST10-6/22/06	030619209-0005	North Side Sidewalk Bridge	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST11-6/22/06	030619209-0006	90 Trinity Place (roof level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST12-6/22/06	030619209-0007	110 Greenwich Street (roof level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST13-6/22/06	030619209-0008	Marriott Hotel, 38th Floor (roof level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST14-6/22/06	030619209-0009	West Face - South end at corner (scaffolding level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST15-6/22/06	030619209-0010	South Face - East end at corner (scaffolding level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST16-6/22/06	030619209-0011	East Face - North end at corner (scaffolding level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST17-6/22/06	030619209-0012	North Face - West end at corner (scaffolding level)	6/22/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/06	< 13.00	No	No	
ASBESTOS-ST1-6/23/06	030619470-0001	Southwest Area (sidewalk bridge level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST2-6/23/06	030619470-0002	Southeast Area (sidewalk bridge level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST4-6/23/06	030619470-0003	Northwest Area (street-level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST5-6/23/06	030619470-0004	Firehouse #10 (roof level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST10-6/23/06	030619470-0005	North Side Sidewalk Bridge	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST11-6/23/06	030619470-0006	90 Trinity Place (roof level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST12-6/23/06	030619470-0007	110 Greenwich Street (roof level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST13-6/23/06	030619470-0008	Marriott Hotel, 38th Floor (roof level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST14-6/23/06	030619470-0009	West Face - South end at corner (scaffolding level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST15-6/23/06	030619470-0010	South Face - East end at corner (scaffolding level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST16-6/23/06	030619470-0011	East Face - North end at corner (scaffolding level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST17-6/23/06	030619470-0012	North Face - West end at corner (scaffolding level)	6/23/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST1-6/24/06	030619471-0001	Southwest Area (sidewalk bridge level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST2-6/24/06	030619471-0002	Southeast Area (sidewalk bridge level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST4-6/24/06	030619471-0003	Northwest Area (street-level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST5-6/24/06	030619471-0004	Firehouse #10 (roof level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST10-6/24/06	030619471-0005	North Side Sidewalk Bridge	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST11-6/24/06	030619471-0006	90 Trinity Place (roof level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST12-6/24/06	030619471-0007	110 Greenwich Street (roof level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST13-6/24/06	030619471-0008	Marriott Hotel, 38th Floor (roof level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST14-6/24/06	030619471-0009	West Face - South end at corner (scaffolding level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST15-6/24/06	030619471-0010	South Face - East end at corner (scaffolding level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST16-6/24/06	030619471-0011	East Face - North end at corner (scaffolding level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST17-6/24/06	030619471-0012	North Face - West end at corner (scaffolding level)	6/24/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST1-6/25/06	030619468-0001	Southwest Area (sidewalk bridge level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST2-6/25/06	030619468-0002	Southeast Area (sidewalk bridge level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST4-6/25/06	030619468-0003	Northwest Area (street-level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST5-6/25/06	030619468-0004	Firehouse #10 (roof level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST10-6/25/06	030619468-0005	North Side Sidewalk Bridge	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST11-6/25/06	030619468-0006	90 Trinity Place (roof level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST12-6/25/06	030619468-0007	110 Greenwich Street (roof level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST13-6/25/06	030619468-0008	Marriott Hotel, 38th Floor (roof level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST14-6/25/06	030619468-0009	West Face - South end at corner (scaffolding level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST15-6/25/06	030619468-0010	South Face - East end at corner (scaffolding level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST16-6/25/06	030619468-0011	East Face - North end at corner (scaffolding level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST17-6/25/06	030619468-0012	North Face - West end at corner (scaffolding level)	6/25/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/26/06	< 13.00	No	No	
ASBESTOS-ST1-6/26/06	030619613-0001	Southwest Area (sidewalk bridge level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST2-6/26/06	030619613-0002	Southeast Area (sidewalk bridge level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST4-6/26/06	030619613-0003	Northwest Area (street-level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST5-6/26/06	030619613-0004	Firehouse #10 (roof level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST10-6/26/06	030619613-0005	North Side Sidewalk Bridge	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST11-6/26/06	030619613-0006	90 Trinity Place (roof level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST12-6/26/06	030619613-0007	110 Greenwich Street (roof level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST13-6/26/06	030619613-0008	Marriott Hotel, 38th Floor (roof level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST14-6/26/06	030619613-0009	West Face - South end at corner (scaffolding level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST15-6/26/06	030619613-0010	South Face - East end at corner (scaffolding level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST16-6/26/06	030619613-0011	East Face - North end at corner (scaffolding level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	
ASBESTOS-ST17-6/26/06	030619613-0012	North Face - West end at corner (scaffolding level)	6/26/06	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/27/06	< 13.00	No	No	