TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										**NA**			
EPA Site Specific Trigger Levels										**70**			
ASBESTOS-ST1-8/25/06	030628093-0001	Southwest Area (sidewalk bridge level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST2-8/25/06	030628093-0002	Southeast Area (sidewalk bridge level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST4-8/25/06	030628093-0003	Northwest Area (street-level)	8/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST5-8/25/06	030628093-0004	Firehouse #10 (roof level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST6-8/25/06	030628094-0001	Southwest Area (roof level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST7-8/25/06	030628094-0002	Southeast Area (roof level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST8-8/25/06	030628094-0003	Northeast Area (roof level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST9-8/25/06	030628094-0004	Northwest Area (roof level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST10-8/25/06	030628093-0005	North Side Sidewalk Bridge	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST11-8/25/06	030628093-0006	90 Trinity Place (roof level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST12-8/25/06	030628093-0007	110 Greenwich Street (roof level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST13-8/25/06	030628093-0008	Marriott Hotel, 38th Floor (roof level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST14-8/25/06	030628093-0009	West Face - South end at corner (scaffolding level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST15-8/25/06	030628093-0010	South Face - East end at corner (scaffolding level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	13.00	No	No	
ASBESTOS-ST16-8/25/06	030628093-0011	East Face - North end at corner (scaffolding level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST17-8/25/06	030628093-0012	North Face - West end at corner (scaffolding level)	8/25/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST1-8/26/06	030628095-0001	Southwest Area (sidewalk bridge level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST2-8/26/06	030628095-0002	Southeast Area (sidewalk bridge level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST4-8/26/06	030628095-0003	Northwest Area (street-level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST5-8/26/06	030628095-0004	Firehouse #10 (roof level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST6-8/26/06	030628096-0001	Southwest Area (roof level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST7-8/26/06	030628096-0002	Southeast Area (roof level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST8-8/26/06	030628096-0003	Northeast Area (roof level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST9-8/26/06	030628096-0004	Northwest Area (roof level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST10-8/26/06	030628095-0005	North Side Sidewalk Bridge	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST11-8/26/06	030628095-0006	90 Trinity Place (roof level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST12-8/26/06	030628095-0007	110 Greenwich Street (roof level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST13-8/26/06	030628095-0008	Marriott Hotel, 38th Floor (roof level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST14-8/26/06	030628095-0009	West Face - South end at corner (scaffolding level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST15-8/26/06	030628095-0010	South Face - East end at corner (scaffolding level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST16-8/26/06	030628095-0011	East Face - North end at corner (scaffolding level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST17-8/26/06	030628095-0012	North Face - West end at corner (scaffolding level)	8/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST1-8/27/06	030628097-0001	Southwest Area (sidewalk bridge level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST2-8/27/06	030628097-0002	Southeast Area (sidewalk bridge level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST4-8/27/06	030628097-0003	Northwest Area (street-level)	8/27/06	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST5-8/27/06	030628097-0004	Firehouse #10 (roof level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST6-8/27/06	030628098-0001	Southwest Area (roof level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST7-8/27/06	030628098-0002	Southeast Area (roof level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST8-8/27/06	030628098-0003	Northeast Area (roof level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST9-8/27/06	030628098-0004	Northwest Area (roof level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST10-8/27/06	030628097-0005	North Side Sidewalk Bridge	8/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST11-8/27/06	030628097-0006	90 Trinity Place (roof level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST12-8/27/06	030628097-0007	110 Greenwich Street (roof level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST13-8/27/06	030628097-0008	Marriott Hotel, 38th Floor (roof level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST15-8/27/06	030628097-0009	South Face - East end at corner (scaffolding level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST16-8/27/06	030628097-0010	East Face - North end at corner (scaffolding level)	8/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/06	< 13.00	No	No	
ASBESTOS-ST1-8/28/06	030628251-0001	Southwest Area (sidewalk bridge level)	8/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST2-8/28/06	030628251-0002	Southeast Area (sidewalk bridge level)	8/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST4-8/28/06	030628251-0003	Northwest Area (street-level)	8/28/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST5-8/28/06	030628251-0004	Firehouse #10 (roof level)	8/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST6-8/28/06	030628252-0001	Southwest Area (roof level)	8/28/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST7-8/28/06	030628252-0002	Southeast Area (roof level)	8/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST8-8/28/06	030628252-0003	Northeast Area (roof level)	8/28/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST9-8/28/06	030628252-0004	Northwest Area (roof level)	8/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST10-8/28/06	030628251-0005	North Side Sidewalk Bridge	8/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST11-8/28/06	030628251-0006	90 Trinity Place (roof level)	8/28/06	1	2.750	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST12-8/28/06	030628251-0007	110 Greenwich Street (roof level)	8/28/06	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST13-8/28/06	030628251-0008	Marriott Hotel, 38th Floor (roof level)	8/28/06	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST14-8/28/06	030628251-0009	West Face - South end at corner (scaffolding level)	8/28/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST15-8/28/06	030628251-0010	South Face - East end at corner (scaffolding level)	8/28/06	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST16-8/28/06	030628251-0011	East Face - North end at corner (scaffolding level)	8/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	
ASBESTOS-ST17-8/28/06	030628251-0012	North Face - West end at corner (scaffolding level)	8/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/29/06	< 13.00	No	No	

Note:
1. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]) on August 27, 2006 were not available for analysis on account of pump failure.