| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume ($m^3$) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Target Air Quality Levels | | | | | | | | | | NA | | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | 70 | | | |
| ASBESTOS-ST1-12/20/07 | 030739533-0001 | Southwest Area (sidewalk bridge level) | 12/20/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST2-12/20/07 | 030739533-0002 | Southeast Area (sidewalk bridge level) | 12/20/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST4-12/20/07 | 030739533-0003 | Northwest Area (street-level) | 12/20/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST5-12/20/07 | 030739533-0004 | Firehouse #10 (roof level) | 12/20/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST10-12/20/07 | 030739533-0005 | North Side Sidewalk Bridge | 12/20/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST11-12/20/07 | 030739533-0006 | 90 Trinity Place (roof level) | 12/20/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST12-12/20/07 | 030739533-0007 | 110 Greenwich Street (roof level) | 12/20/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST13-12/20/07 | 030739533-0008 | Marriott Hotel, 38th Floor (roof level) | 12/20/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST14-12/20/07 | 030739533-0009 | West Face - South end at corner (scaffolding level) | 12/20/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST15-12/20/07 | 030739533-0010 | South Face - East end at corner (scaffolding level) | 12/20/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST16-12/20/07 | 030739533-0011 | East Face - North end at corner (scaffolding level) | 12/20/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST17-12/20/07 | 030739533-0012 | North Face - West end at corner (scaffolding level) | 12/20/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/21/07 | < 13.00 | No | No | |
| ASBESTOS-ST1-12/21/07 | 030739754-0001 | Southwest Area (sidewalk bridge level) | 12/21/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST2-12/21/07 | 030739754-0002 | Southeast Area (sidewalk bridge level) | 12/21/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST4-12/21/07 | 030739754-0003 | Northwest Area (street-level) | 12/21/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST5-12/21/07 | 030739754-0004 | Firehouse #10 (roof level) | 12/21/07 | 1 | 3.100 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST10-12/21/07 | 030739754-0005 | North Side Sidewalk Bridge | 12/21/07 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST11-12/21/07 | 030739754-0006 | 90 Trinity Place (roof level) | 12/21/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST12-12/21/07 | 030739754-0007 | 110 Greenwich Street (roof level) | 12/21/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST13-12/21/07 | 030739754-0008 | Marriott Hotel, 38th Floor (roof level) | 12/21/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST14-12/21/07 | 030739754-0009 | West Face - South end at corner (scaffolding level) | 12/21/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST15-12/21/07 | 030739754-0010 | South Face - East end at corner (scaffolding level) | 12/21/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST16-12/21/07 | 030739754-0011 | East Face - North end at corner (scaffolding level) | 12/21/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST17-12/21/07 | 030739754-0012 | North Face - West end at corner (scaffolding level) | 12/21/07 | 1 | 3.150 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST1-12/22/07 | 030739757-0001 | Southwest Area (sidewalk bridge level) | 12/22/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST2-12/22/07 | 030739757-0002 | Southeast Area (sidewalk bridge level) | 12/22/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST4-12/22/07 | 030739757-0003 | Northwest Area (street-level) | 12/22/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST5-12/22/07 | 030739757-0004 | Firehouse #10 (roof level) | 12/22/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST10-12/22/07 | 030739757-0005 | North Side Sidewalk Bridge | 12/22/07 | 1 | 3.120 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST11-12/22/07 | 030739757-0006 | 90 Trinity Place (roof level) | 12/22/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST12-12/22/07 | 030739757-0007 | 110 Greenwich Street (roof level) | 12/22/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST13-12/22/07 | 030739757-0008 | Marriott Hotel, 38th Floor (roof level) | 12/22/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST14-12/22/07 | 030739757-0009 | West Face - South end at corner (scaffolding level) | 12/22/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST15-12/22/07 | 030739757-0010 | South Face - East end at corner (scaffolding level) | 12/22/07 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST16-12/22/07 | 030739757-0011 | East Face - North end at corner (scaffolding level) | 12/22/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST17-12/22/07 | 030739757-0012 | North Face - West end at corner (scaffolding level) | 12/22/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST1-12/23/07 | 030739756-0001 | Southwest Area (sidewalk bridge level) | 12/23/07 | 1 | 3.240 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST2-12/23/07 | 030739756-0002 | Southeast Area (sidewalk bridge level) | 12/23/07 | 1 | 3.130 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST4-12/23/07 | 030739756-0003 | Northwest Area (street-level) | 12/23/07 | 1 | 3.140 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST5-12/23/07 | 030739756-0004 | Firehouse #10 (roof level) | 12/23/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST10-12/23/07 | 030739756-0005 | North Side Sidewalk Bridge | 12/23/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST11-12/23/07 | 030739756-0006 | 90 Trinity Place (roof level) | 12/23/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST12-12/23/07 | 030739756-0007 | 110 Greenwich Street (roof level) | 12/23/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST13-12/23/07 | 030739756-0008 | Marriott Hotel, 38th Floor (roof level) | 12/23/07 | 1 | 2.950 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST14-12/23/07 | 030739756-0009 | West Face - South end at corner (scaffolding level) | 12/23/07 | 1 | 3.150 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST15-12/23/07 | 030739756-0010 | South Face - East end at corner (scaffolding level) | 12/23/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 13.00 | No | No | |
| ASBESTOS-ST16-12/23/07 | 030739756-0011 | East Face - North end at corner (scaffolding level) | 12/23/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/24/07 | < 15.00 | No | No | |
| ASBESTOS-ST1-12/24/07 | 030739793-0001 | Southwest Area (sidewalk bridge level) | 12/24/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST2-12/24/07 | 030739793-0002 | Southeast Area (sidewalk bridge level) | 12/24/07 | 1 | 3.120 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST4-12/24/07 | 030739793-0003 | Northwest Area (street-level) | 12/24/07 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST5-12/24/07 | 030739793-0004 | Firehouse #10 (roof level) | 12/24/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST10-12/24/07 | 030739793-0005 | North Side Sidewalk Bridge | 12/24/07 | 1 | 3.140 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST11-12/24/07 | 030739793-0006 | 90 Trinity Place (roof level) | 12/24/07 | 1 | 3.080 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST12-12/24/07 | 030739793-0007 | 110 Greenwich Street (roof level) | 12/24/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 15.00 | No | No | |
| ASBESTOS-ST13-12/24/07 | 030739793-0008 | Marriott Hotel, 38th Floor (roof level) | 12/24/07 | 1 | 3.010 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST14-12/24/07 | 030739793-0009 | West Face - South end at corner (scaffolding level) | 12/24/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST15-12/24/07 | 030739793-0010 | South Face - East end at corner (scaffolding level) | 12/24/07 | 1 | 3.070 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST16-12/24/07 | 030739793-0011 | East Face - North end at corner (scaffolding level) | 12/24/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST17-12/24/07 | 030739793-0012 | North Face - West end at corner (scaffolding level) | 12/24/07 | 1 | 2.500 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 9.60 | No | No | |
| ASBESTOS-ST1-12/25/07 | 030739789-0001 | Southwest Area (sidewalk bridge level) | 12/25/07 | 1 | 2.980 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST2-12/25/07 | 030739789-0002 | Southeast Area (sidewalk bridge level) | 12/25/07 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST4-12/25/07 | 030739789-0003 | Northwest Area (street-level) | 12/25/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST5-12/25/07 | 030739789-0004 | Firehouse #10 (roof level) | 12/25/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST10-12/25/07 | 030739789-0005 | North Side Sidewalk Bridge | 12/25/07 | 1 | 3.030 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST11-12/25/07 | 030739789-0006 | 90 Trinity Place (roof level) | 12/25/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST12-12/25/07 | 030739789-0007 | 110 Greenwich Street (roof level) | 12/25/07 | 1 | 3.060 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST13-12/25/07 | 030739789-0008 | Marriott Hotel, 38th Floor (roof level) | 12/25/07 | 1 | 3.040 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST14-12/25/07 | 030739789-0009 | West Face - South end at corner (scaffolding level) | 12/25/07 | 1 | 3.020 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST15-12/25/07 | 030739789-0010 | South Face - East end at corner (scaffolding level) | 12/25/07 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST16-12/25/07 | 030739789-0011 | East Face - North end at corner (scaffolding level) | 12/25/07 | 1 | 2.990 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |
| ASBESTOS-ST17-12/25/07 | 030739789-0012 | North Face - West end at corner (scaffolding level) | 12/25/07 | 1 | 3.050 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 12/26/07 | < 13.00 | No | No | |

Note:
1. Asbestos sample at Station 17 (North Face - West end at corner [scaffolding level]) on December 23, 2007 was not available for analysis on account of power failure.