TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-12/23/05	030538458-0001	Southwest Area (sidewalk bridge level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST2-12/23/05	030538458-0002	Southeast Area (sidewalk bridge level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST4-12/23/05	030538458-0003	Northwest Area (street-level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST5-12/23/05	030538458-0004	Firehouse #10 (roof level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST10-12/23/05	030538458-0005	North Side Sidewalk Bridge	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST11-12/23/05	030538458-0006	90 Trinity Place (roof level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST12-12/23/05	030538458-0007	110 Greenwich Street (roof level)	12/23/05	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST13-12/23/05	030538458-0008	Marriott Hotel, 38th Floor (roof level)	12/23/05	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST14-12/23/05	030538458-0009	West Face - South end at corner (scaffolding level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST15-12/23/05	030538458-0010	South Face - East end at corner (scaffolding level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST16-12/23/05	030538458-0011	East Face - North end at corner (scaffolding level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST17-12/23/05	030538458-0012	North Face - West end at corner (scaffolding level)	12/23/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST1-12/24/05	030538459-0001	Southwest Area (sidewalk bridge level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST2-12/24/05	030538459-0002	Southeast Area (sidewalk bridge level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST4-12/24/05	030538459-0003	Northwest Area (street-level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST5-12/24/05	030538459-0004	Firehouse #10 (roof level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST10-12/24/05	030538459-0005	North Side Sidewalk Bridge	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST11-12/24/05	030538459-0006	90 Trinity Place (roof level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST12-12/24/05	030538459-0007	110 Greenwich Street (roof level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST13-12/24/05	030538459-0008	Marriott Hotel, 38th Floor (roof level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST14-12/24/05	030538459-0009	West Face - South end at corner (scaffolding level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST15-12/24/05	030538459-0010	South Face - East end at corner (scaffolding level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST16-12/24/05	030538459-0011	East Face - North end at corner (scaffolding level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST17-12/24/05	030538459-0012	North Face - West end at corner (scaffolding level)	12/24/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST1-12/25/05	030538460-0001	Southwest Area (sidewalk bridge level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST2-12/25/05	030538460-0002	Southeast Area (sidewalk bridge level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST4-12/25/05	030538460-0003	Northwest Area (street-level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST5-12/25/05	030538460-0004	Firehouse #10 (roof level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST10-12/25/05	030538460-0005	North Side Sidewalk Bridge	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST11-12/25/05	030538460-0006	90 Trinity Place (roof level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST12-12/25/05	030538460-0007	110 Greenwich Street (roof level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST13-12/25/05	030538460-0008	Marriott Hotel, 38th Floor (roof level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST14-12/25/05	030538460-0009	West Face - South end at corner (scaffolding level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST15-12/25/05	030538460-0010	South Face - East end at corner (scaffolding level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST16-12/25/05	030538460-0011	East Face - North end at corner (scaffolding level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST17-12/25/05	030538460-0012	North Face - West end at corner (scaffolding level)	12/25/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST1-12/26/05	030538461-0001	Southwest Area (sidewalk bridge level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST2-12/26/05	030538461-0002	Southeast Area (sidewalk bridge level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST4-12/26/05	030538461-0003	Northwest Area (street-level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST5-12/26/05	030538461-0004	Firehouse #10 (roof level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST10-12/26/05	030538461-0005	North Side Sidewalk Bridge	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST11-12/26/05	030538461-0006	90 Trinity Place (roof level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST12-12/26/05	030538461-0007	110 Greenwich Street (roof level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST13-12/26/05	030538461-0008	Marriott Hotel, 38th Floor (roof level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST14-12/26/05	030538461-0009	West Face - South end at corner (scaffolding level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST15-12/26/05	030538461-0010	South Face - East end at corner (scaffolding level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST16-12/26/05	030538461-0011	East Face - North end at corner (scaffolding level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	
ASBESTOS-ST17-12/26/05	030538461-0012	North Face - West end at corner (scaffolding level)	12/26/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/27/05	< 13.00	No	No	