

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels											Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels													
											NA		
											70		
ASBESTOS-ST1-1/6/06	030600661-0001	Southwest Area (sidewalk bridge level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST2-1/6/06	030600661-0002	Southeast Area (sidewalk bridge level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST4-1/6/06	030600661-0003	Northwest Area (street-level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST5-1/6/06	030600661-0004	Firehouse #10 (roof level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST10-1/6/06	030600661-0005	North Side Sidewalk Bridge	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST100-1/6/06	030600661-0013	Station 10 Field Duplicate	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST11-1/6/06	030600661-0006	90 Trinity Place (roof level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST12-1/6/06	030600661-0007	110 Greenwich Street (roof level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST13-1/6/06	030600661-0008	Marriott Hotel, 38th Floor (roof level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST14-1/6/06	030600661-0009	West Face - South end at corner (scaffolding level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST15-1/6/06	030600661-0010	South Face - East end at corner (scaffolding level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST16-1/6/06	030600661-0011	East Face - North end at corner (scaffolding level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST17-1/6/06	030600661-0012	North Face - West end at corner (scaffolding level)	1/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST1-1/7/06	030600662-0001	Southwest Area (sidewalk bridge level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST2-1/7/06	030600662-0002	Southeast Area (sidewalk bridge level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST4-1/7/06	030600662-0003	Northwest Area (street-level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST5-1/7/06	030600662-0004	Firehouse #10 (roof level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST10-1/7/06	030600662-0005	North Side Sidewalk Bridge	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST11-1/7/06	030600662-0006	90 Trinity Place (roof level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST12-1/7/06	030600662-0007	110 Greenwich Street (roof level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST13-1/7/06	030600662-0008	Marriott Hotel, 38th Floor (roof level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST14-1/7/06	030600662-0009	West Face - South end at corner (scaffolding level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST15-1/7/06	030600662-0010	South Face - East end at corner (scaffolding level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST16-1/7/06	030600662-0011	East Face - North end at corner (scaffolding level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST17-1/7/06	030600662-0012	North Face - West end at corner (scaffolding level)	1/7/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST1-1/8/06	030600663-0001	Southwest Area (sidewalk bridge level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST2-1/8/06	030600663-0002	Southeast Area (sidewalk bridge level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST4-1/8/06	030600663-0003	Northwest Area (street-level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST5-1/8/06	030600663-0004	Firehouse #10 (roof level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST10-1/8/06	030600663-0005	North Side Sidewalk Bridge	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST11-1/8/06	030600663-0006	90 Trinity Place (roof level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST12-1/8/06	030600663-0007	110 Greenwich Street (roof level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST13-1/8/06	030600663-0008	Marriott Hotel, 38th Floor (roof level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST14-1/8/06	030600663-0009	West Face - South end at corner (scaffolding level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST15-1/8/06	030600663-0010	South Face - East end at corner (scaffolding level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST16-1/8/06	030600663-0011	East Face - North end at corner (scaffolding level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST17-1/8/06	030600663-0012	North Face - West end at corner (scaffolding level)	1/8/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/9/06	< 13.00	No	No	
ASBESTOS-ST1-1/9/06	030600786-0001	Southwest Area (sidewalk bridge level)	1/9/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/10/06	< 13.00	No	No	
ASBESTOS-ST2-1/9/06	030600786-0002	Southeast Area (sidewalk bridge level)	1/9/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/10/06	< 13.00	No	No	
ASBESTOS-ST4-1/9/06	030600786-0003	Northwest Area (street-level)	1/9/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/10/06	< 13.00	No	No	
ASBESTOS-ST5-1/9/06	030600786-0004	Firehouse #10 (roof level)	1/9/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/10/06	< 13.00	No	No	
ASBESTOS-ST10-1/9/06	030600786-0005	North Side Sidewalk Bridge	1/9/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/10/06	< 13.00	No	No	
ASBESTOS-ST11-1/9/06	030600786-0006	90 Trinity Place (roof level)	1/9/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/10/06	< 13.00	No	No	
ASBESTOS-ST12-1/9/06	030600786-0007	110 Greenwich Street (roof level)	1/9/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/10/06	< 13.00	No	No	
ASBESTOS-ST13-1/9/06	030600786-0008	Marriott Hotel, 38th Floor (roof level)	1/9/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/10/06	< 13.00	No	No	

Note:  
1. On January 9, 2006, Stations 14 through 17 were moved from the 20th floor scaffolding level to the 30th floor scaffolding level and were temporarily disabled. No measurements were collected this day. No abatement activities took place on January 9, 2006. Work activities were limited to scaffolding erection.