

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-2/2/07	030703628-0001	Southwest Area (sidewalk bridge level)	2/2/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST2-2/2/07	030703628-0002	Southeast Area (sidewalk bridge level)	2/2/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST4-2/2/07	030703628-0003	Northwest Area (street-level)	2/2/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST5-2/2/07	030703628-0004	Firehouse #10 (roof level)	2/2/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST10-2/2/07	030703628-0005	North Side Sidewalk Bridge	2/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST11-2/2/07	030703628-0006	90 Trinity Place (roof level)	2/2/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST12-2/2/07	030703628-0007	110 Greenwich Street (roof level)	2/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST13-2/2/07	030703628-0008	Marriott Hotel, 38th Floor (roof level)	2/2/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST14-2/2/07	030703628-0009	West Face - South end at corner (scaffolding level)	2/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST15-2/2/07	030703628-0010	South Face - East end at corner (scaffolding level)	2/2/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST16-2/2/07	030703628-0011	East Face - North end at corner (scaffolding level)	2/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST17-2/2/07	030703628-0012	North Face - West end at corner (scaffolding level)	2/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST1-2/3/07	030703625-0001	Southwest Area (sidewalk bridge level)	2/3/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST2-2/3/07	030703625-0002	Southeast Area (sidewalk bridge level)	2/3/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST4-2/3/07	030703625-0003	Northwest Area (street-level)	2/3/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 15.00	No	No	
ASBESTOS-ST5-2/3/07	030703625-0004	Firehouse #10 (roof level)	2/3/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 15.00	No	No	
ASBESTOS-ST10-2/3/07	030703625-0005	North Side Sidewalk Bridge	2/3/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST11-2/3/07	030703625-0006	90 Trinity Place (roof level)	2/3/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST12-2/3/07	030703625-0007	110 Greenwich Street (roof level)	2/3/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST13-2/3/07	030703625-0008	Marriott Hotel, 38th Floor (roof level)	2/3/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST14-2/3/07	030703625-0009	West Face - South end at corner (scaffolding level)	2/3/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 15.00	No	No	
ASBESTOS-ST15-2/3/07	030703625-0010	South Face - East end at corner (scaffolding level)	2/3/07	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST16-2/3/07	030703625-0011	East Face - North end at corner (scaffolding level)	2/3/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	15.00	No	No	
ASBESTOS-ST17-2/3/07	030703625-0012	North Face - West end at corner (scaffolding level)	2/3/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST1-2/4/07	030703627-0001	Southwest Area (sidewalk bridge level)	2/4/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST2-2/4/07	030703627-0002	Southeast Area (sidewalk bridge level)	2/4/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST4-2/4/07	030703627-0003	Northwest Area (street-level)	2/4/07	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST5-2/4/07	030703627-0004	Firehouse #10 (roof level)	2/4/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST10-2/4/07	030703627-0005	North Side Sidewalk Bridge	2/4/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST11-2/4/07	030703627-0006	90 Trinity Place (roof level)	2/4/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST12-2/4/07	030703627-0007	110 Greenwich Street (roof level)	2/4/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST13-2/4/07	030703627-0008	Marriott Hotel, 38th Floor (roof level)	2/4/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST14-2/4/07	030703627-0009	West Face - South end at corner (scaffolding level)	2/4/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST15-2/4/07	030703627-0010	South Face - East end at corner (scaffolding level)	2/4/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST16-2/4/07	030703627-0011	East Face - North end at corner (scaffolding level)	2/4/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST17-2/4/07	030703627-0012	North Face - West end at corner (scaffolding level)	2/4/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/5/07	< 13.00	No	No	
ASBESTOS-ST1-2/5/07	030703719-0001	Southwest Area (sidewalk bridge level)	2/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST2-2/5/07	030703719-0002	Southeast Area (sidewalk bridge level)	2/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST4-2/5/07	030703719-0003	Northwest Area (street-level)	2/5/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST5-2/5/07	030703719-0004	Firehouse #10 (roof level)	2/5/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST10-2/5/07	030703719-0005	North Side Sidewalk Bridge	2/5/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST11-2/5/07	030703719-0006	90 Trinity Place (roof level)	2/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST12-2/5/07	030703719-0007	110 Greenwich Street (roof level)	2/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST13-2/5/07	030703719-0008	Marriott Hotel, 38th Floor (roof level)	2/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST14-2/5/07	030703719-0009	West Face - South end at corner (scaffolding level)	2/5/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST15-2/5/07	030703719-0010	South Face - East end at corner (scaffolding level)	2/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST16-2/5/07	030703719-0011	East Face - North end at corner (scaffolding level)	2/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	
ASBESTOS-ST17-2/5/07	030703719-0012	North Face - West end at corner (scaffolding level)	2/5/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/6/07	< 13.00	No	No	