

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels											Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels													
											NA		
											70		
ASBESTOS-ST1-2/10/06	030604530-0001	Southwest Area (sidewalk bridge level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST2-2/10/06	030604530-0002	Southeast Area (sidewalk bridge level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST4-2/10/06	030604530-0003	Northwest Area (street-level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST5-2/10/06	030604530-0004	Firehouse #10 (roof level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST10-2/10/06	030604530-0005	North Side Sidewalk Bridge	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST11-2/10/06	030604530-0006	90 Trinity Place (roof level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST12-2/10/06	030604530-0007	110 Greenwich Street (roof level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST13-2/10/06	030604530-0008	Marriott Hotel, 38th Floor (roof level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST14-2/10/06	030604530-0009	West Face - South end at corner (scaffolding level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST15-2/10/06	030604530-0010	South Face - East end at corner (scaffolding level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST16-2/10/06	030604530-0011	East Face - North end at corner (scaffolding level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST17-2/10/06	030604530-0012	North Face - West end at corner (scaffolding level)	2/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST1-2/11/06	030604532-0001	Southwest Area (sidewalk bridge level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST2-2/11/06	030604532-0002	Southeast Area (sidewalk bridge level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST4-2/11/06	030604532-0003	Northwest Area (street-level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST5-2/11/06	030604532-0004	Firehouse #10 (roof level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST10-2/11/06	030604532-0005	North Side Sidewalk Bridge	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST11-2/11/06	030604532-0006	90 Trinity Place (roof level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST12-2/11/06	030604532-0007	110 Greenwich Street (roof level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST14-2/11/06	030604532-0009	West Face - South end at corner (scaffolding level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST15-2/11/06	030604532-0010	South Face - East end at corner (scaffolding level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST16-2/11/06	030604532-0011	East Face - North end at corner (scaffolding level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST17-2/11/06	030604532-0012	North Face - West end at corner (scaffolding level)	2/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST1-2/12/06	030604533-0001	Southwest Area (sidewalk bridge level)	2/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST2-2/12/06	030604533-0002	Southeast Area (sidewalk bridge level)	2/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST4-2/12/06	030604533-0003	Northwest Area (street-level)	2/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST11-2/12/06	030604533-0006	90 Trinity Place (roof level)	2/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST14-2/12/06	030604533-0009	West Face - South end at corner (scaffolding level)	2/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST15-2/12/06	030604533-0010	South Face - East end at corner (scaffolding level)	2/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/13/06	< 13.00	No	No	
ASBESTOS-ST1-2/13/06	030604593-0001	Southwest Area (sidewalk bridge level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST2-2/13/06	030604593-0002	Southeast Area (sidewalk bridge level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST4-2/13/06	030604593-0003	Northwest Area (street-level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST5-2/13/06	030604593-0004	Firehouse #10 (roof level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST10-2/13/06	030604593-0005	North Side Sidewalk Bridge	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST11-2/13/06	030604593-0006	90 Trinity Place (roof level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST12-2/13/06	030604593-0007	110 Greenwich Street (roof level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST13-2/13/06	030604593-0008	Marriott Hotel, 38th Floor (roof level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST14-2/13/06	030604593-0009	West Face - South end at corner (scaffolding level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST15-2/13/06	030604593-0010	South Face - East end at corner (scaffolding level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	
ASBESTOS-ST17-2/13/06	030604593-0012	North Face - West end at corner (scaffolding level)	2/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	2/14/06	< 13.00	No	No	

Notes:

1. Asbestos samples were not available for analysis due to damaged filters at the following locations: Station 5 (Firehouse #10 [roof level]) on February 12, 2006, Station 10 (North Side [sidewalk bridge level]) on February 12, 2006, Station 12 (110 Greenwich Street [roof level]) on February 12, 2006, Station 13 (Marriott Hotel, 38th Floor [roof level]) on February 11 and 12, 2006, Station 16 (East Face - North end at corner [scaffolding level]) on February 12 and 13, 2006, and Station 17 (North Face - West end at corner [scaffolding level]) on February 12, 2006. Damaged filters may be attributable to inclement weather (high winds and blizzard conditions) on each of the days noted.