

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-4/14/06	030611513-0001	Southwest Area (sidewalk bridge level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST2-4/14/06	030611513-0002	Southeast Area (sidewalk bridge level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST4-4/14/06	030611513-0003	Northwest Area (street-level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST5-4/14/06	030611513-0004	Firehouse #10 (roof level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST10-4/14/06	030611513-0005	North Side Sidewalk Bridge	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST11-4/14/06	030611513-0006	90 Trinity Place (roof level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST12-4/14/06	030611513-0007	110 Greenwich Street (roof level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST13-4/14/06	030611513-0008	Marriott Hotel, 38th Floor (roof level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST14-4/14/06	030611513-0009	West Face - South end at corner (scaffolding level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST15-4/14/06	030611513-0010	South Face - East end at corner (scaffolding level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST17-4/14/06	030611513-0012	North Face - West end at corner (scaffolding level)	4/14/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST1-4/15/06	030611514-0001	Southwest Area (sidewalk bridge level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST2-4/15/06	030611514-0002	Southeast Area (sidewalk bridge level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST4-4/15/06	030611514-0003	Northwest Area (street-level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST5-4/15/06	030611514-0004	Firehouse #10 (roof level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST10-4/15/06	030611514-0005	North Side Sidewalk Bridge	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST11-4/15/06	030611514-0006	90 Trinity Place (roof level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST12-4/15/06	030611514-0007	110 Greenwich Street (roof level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST13-4/15/06	030611514-0008	Marriott Hotel, 38th Floor (roof level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST14-4/15/06	030611514-0009	West Face - South end at corner (scaffolding level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST15-4/15/06	030611514-0010	South Face - East end at corner (scaffolding level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST16-4/15/06	030611514-0011	East Face - North end at corner (scaffolding level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST17-4/15/06	030611514-0012	North Face - West end at corner (scaffolding level)	4/15/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST1-4/16/06	030611515-0001	Southwest Area (sidewalk bridge level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST2-4/16/06	030611515-0002	Southeast Area (sidewalk bridge level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST4-4/16/06	030611515-0003	Northwest Area (street-level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST5-4/16/06	030611515-0004	Firehouse #10 (roof level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST10-4/16/06	030611515-0005	North Side Sidewalk Bridge	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST11-4/16/06	030611515-0006	90 Trinity Place (roof level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST12-4/16/06	030611515-0007	110 Greenwich Street (roof level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST13-4/16/06	030611515-0008	Marriott Hotel, 38th Floor (roof level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST14-4/16/06	030611515-0009	West Face - South end at corner (scaffolding level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST15-4/16/06	030611515-0010	South Face - East end at corner (scaffolding level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST17-4/16/06	030611515-0012	North Face - West end at corner (scaffolding level)	4/16/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/17/06	< 13.00	No	No		
ASBESTOS-ST1-4/17/06	030611658-0001	Southwest Area (sidewalk bridge level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST2-4/17/06	030611658-0002	Southeast Area (sidewalk bridge level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST4-4/17/06	030611658-0003	Northwest Area (street-level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST5-4/17/06	030611658-0004	Firehouse #10 (roof level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST10-4/17/06	030611658-0005	North Side Sidewalk Bridge	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST11-4/17/06	030611658-0006	90 Trinity Place (roof level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST12-4/17/06	030611658-0007	110 Greenwich Street (roof level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST13-4/17/06	030611658-0008	Marriott Hotel, 38th Floor (roof level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST14-4/17/06	030611658-0009	West Face - South end at corner (scaffolding level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST15-4/17/06	030611658-0010	South Face - East end at corner (scaffolding level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST16-4/17/06	030611658-0011	East Face - North end at corner (scaffolding level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		
ASBESTOS-ST17-4/17/06	030611658-0012	North Face - West end at corner (scaffolding level)	4/17/06	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/18/06	< 13.00	No	No		

Note:

1. Asbestos samples at Station 16 (East Face - North end at corner [scaffolding level]) on April 14 and 16, 2006 were not available for analysis on account of filter damage.