

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target Air Quality Levels | Exceeds EPA Site Specific Trigger Levels | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|-----------------------------------|--|----------|
| Target Air Quality Levels | | | | | | | | | | | NA | | |
| EPA Site Specific Trigger Levels | | | | | | | | | | | 70 | | |
| ASBESTOS-ST1-4/21/06 | 030612302-0001 | Southwest Area (sidewalk bridge level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-4/21/06 | 030612302-0002 | Southeast Area (sidewalk bridge level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-4/21/06 | 030612302-0003 | Northwest Area (street-level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-4/21/06 | 030612302-0004 | Firehouse #10 (roof level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-4/21/06 | 030612302-0005 | North Side Sidewalk Bridge | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-4/21/06 | 030612302-0006 | 90 Trinity Place (roof level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-4/21/06 | 030612302-0007 | 110 Greenwich Street (roof level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-4/21/06 | 030612302-0008 | Marriott Hotel, 38th Floor (roof level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-4/21/06 | 030612302-0009 | West Face - South end at corner (scaffolding level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-4/21/06 | 030612302-0010 | South Face - East end at corner (scaffolding level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST16-4/21/06 | 030612302-0011 | East Face - North end at corner (scaffolding level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-4/21/06 | 030612302-0012 | North Face - West end at corner (scaffolding level) | 4/21/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST1-4/22/06 | 030612303-0001 | Southwest Area (sidewalk bridge level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-4/22/06 | 030612303-0002 | Southeast Area (sidewalk bridge level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-4/22/06 | 030612303-0003 | Northwest Area (street-level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-4/22/06 | 030612303-0004 | Firehouse #10 (roof level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-4/22/06 | 030612303-0005 | North Side Sidewalk Bridge | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-4/22/06 | 030612303-0006 | 90 Trinity Place (roof level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-4/22/06 | 030612303-0007 | 110 Greenwich Street (roof level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-4/22/06 | 030612303-0008 | Marriott Hotel, 38th Floor (roof level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-4/22/06 | 030612303-0009 | West Face - South end at corner (scaffolding level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-4/22/06 | 030612303-0010 | South Face - East end at corner (scaffolding level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-4/22/06 | 030612303-0012 | North Face - West end at corner (scaffolding level) | 4/22/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-4/23/06 | 030612304-0002 | Southeast Area (sidewalk bridge level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-4/23/06 | 030612304-0003 | Northwest Area (street-level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-4/23/06 | 030612304-0004 | Firehouse #10 (roof level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-4/23/06 | 030612304-0005 | North Side Sidewalk Bridge | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-4/23/06 | 030612304-0006 | 90 Trinity Place (roof level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-4/23/06 | 030612304-0007 | 110 Greenwich Street (roof level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-4/23/06 | 030612304-0008 | Marriott Hotel, 38th Floor (roof level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-4/23/06 | 030612304-0009 | West Face - South end at corner (scaffolding level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-4/23/06 | 030612304-0010 | South Face - East end at corner (scaffolding level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST16-4/23/06 | 030612304-0011 | East Face - North end at corner (scaffolding level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-4/23/06 | 030612304-0012 | North Face - West end at corner (scaffolding level) | 4/23/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/24/06 | < 13.00 | No | No | |
| ASBESTOS-ST1-4/24/06 | 030612430-0001 | Southwest Area (sidewalk bridge level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-4/24/06 | 030612430-0002 | Southeast Area (sidewalk bridge level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-4/24/06 | 030612430-0003 | Northwest Area (street-level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-4/24/06 | 030612430-0004 | Firehouse #10 (roof level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-4/24/06 | 030612430-0005 | North Side Sidewalk Bridge | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-4/24/06 | 030612430-0006 | 90 Trinity Place (roof level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-4/24/06 | 030612430-0007 | 110 Greenwich Street (roof level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-4/24/06 | 030612430-0008 | Marriott Hotel, 38th Floor (roof level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-4/24/06 | 030612430-0009 | West Face - South end at corner (scaffolding level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-4/24/06 | 030612430-0010 | South Face - East end at corner (scaffolding level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-4/24/06 | 030612430-0012 | North Face - West end at corner (scaffolding level) | 4/24/06 | 1 | 3.000 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 4/25/06 | < 13.00 | No | No | |

Note:

- Asbestos samples at Station 16 (East Face - North end at corner [scaffolding level]) on April 22 and 24, 2006 were not available for analysis on account of a damaged filter.
- Asbestos sample at Station 1 (Southwest Area (sidewalk bridge level)) on April 23, 2006 was not available for analysis on account of a damaged filter.