

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-4/23/08	030812227-0001	Southwest Area (sidewalk bridge level)	4/23/08	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 13.00		No	No	
ASBESTOS-ST2-4/23/08	030812227-0002	Southeast Area (sidewalk bridge level)	4/23/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 13.00		No	No	
ASBESTOS-ST4-4/23/08	030812227-0003	Northwest Area (street-level)	4/23/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 13.00		No	No	
ASBESTOS-ST5-4/23/08	030812227-0004	Firehouse #10 (roof level)	4/23/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 13.00		No	No	
ASBESTOS-ST10-4/23/08	030812227-0005	North Side Sidewalk Bridge	4/23/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 13.00		No	No	
ASBESTOS-ST11-4/23/08	030812227-0006	90 Trinity Place (roof level)	4/23/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 13.00		No	No	
ASBESTOS-ST12-4/23/08	030812227-0007	110 Greenwich Street (roof level)	4/23/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 15.00		No	No	
ASBESTOS-ST13-4/23/08	030812227-0008	Marriott Hotel, 38th Floor (roof level)	4/23/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 13.00		No	No	
ASBESTOS-ST14-4/23/08	030812227-0009	West Face - South end at corner (scaffolding level)	4/23/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 15.00		No	No	
ASBESTOS-ST15-4/23/08	030812227-0010	South Face - East end at corner (scaffolding level)	4/23/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 15.00		No	No	
ASBESTOS-ST16-4/23/08	030812227-0011	East Face - North end at corner (scaffolding level)	4/23/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 15.00		No	No	
ASBESTOS-ST17-4/23/08	030812227-0012	North Face - West end at corner (scaffolding level)	4/23/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/24/08	< 15.00		No	No	
ASBESTOS-ST1-4/24/08	030812427-0001	Southwest Area (sidewalk bridge level)	4/24/08	1	3.200	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST2-4/24/08	030812427-0002	Southeast Area (sidewalk bridge level)	4/24/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST4-4/24/08	030812427-0003	Northwest Area (street-level)	4/24/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST5-4/24/08	030812427-0004	Firehouse #10 (roof level)	4/24/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST10-4/24/08	030812427-0005	North Side Sidewalk Bridge	4/24/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST11-4/24/08	030812427-0006	90 Trinity Place (roof level)	4/24/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST12-4/24/08	030812427-0007	110 Greenwich Street (roof level)	4/24/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST13-4/24/08	030812427-0008	Marriott Hotel, 38th Floor (roof level)	4/24/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST14-4/24/08	030812427-0009	West Face - South end at corner (scaffolding level)	4/24/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST15-4/24/08	030812427-0010	South Face - East end at corner (scaffolding level)	4/24/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST16-4/24/08	030812427-0011	East Face - North end at corner (scaffolding level)	4/24/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST17-4/24/08	030812427-0012	North Face - West end at corner (scaffolding level)	4/24/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/25/08	< 13.00		No	No	
ASBESTOS-ST1-4/25/08	030812622-0001	Southwest Area (sidewalk bridge level)	4/25/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST2-4/25/08	030812622-0002	Southeast Area (sidewalk bridge level)	4/25/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST4-4/25/08	030812622-0003	Northwest Area (street-level)	4/25/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST5-4/25/08	030812622-0004	Firehouse #10 (roof level)	4/25/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST10-4/25/08	030812622-0005	North Side Sidewalk Bridge	4/25/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST11-4/25/08	030812622-0006	90 Trinity Place (roof level)	4/25/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST12-4/25/08	030812622-0007	110 Greenwich Street (roof level)	4/25/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST13-4/25/08	030812622-0008	Marriott Hotel, 38th Floor (roof level)	4/25/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST14-4/25/08	030812622-0009	West Face - South end at corner (scaffolding level)	4/25/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST15-4/25/08	030812622-0010	South Face - East end at corner (scaffolding level)	4/25/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST16-4/25/08	030812622-0011	East Face - North end at corner (scaffolding level)	4/25/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST17-4/25/08	030812622-0012	North Face - West end at corner (scaffolding level)	4/25/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/26/08	< 13.00		No	No	
ASBESTOS-ST1-4/26/08	030812754-0001	Southwest Area (sidewalk bridge level)	4/26/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST2-4/26/08	030812754-0002	Southeast Area (sidewalk bridge level)	4/26/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST4-4/26/08	030812754-0003	Northwest Area (street-level)	4/26/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 15.00		No	No	
ASBESTOS-ST5-4/26/08	030812754-0004	Firehouse #10 (roof level)	4/26/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST10-4/26/08	030812754-0005	North Side Sidewalk Bridge	4/26/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 15.00		No	No	
ASBESTOS-ST11-4/26/08	030812754-0006	90 Trinity Place (roof level)	4/26/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 15.00		No	No	
ASBESTOS-ST12-4/26/08	030812754-0007	110 Greenwich Street (roof level)	4/26/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST13-4/26/08	030812754-0008	Marriott Hotel, 38th Floor (roof level)	4/26/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST14-4/26/08	030812754-0009	West Face - South end at corner (scaffolding level)	4/26/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST15-4/26/08	030812754-0010	South Face - East end at corner (scaffolding level)	4/26/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST16-4/26/08	030812754-0011	East Face - North end at corner (scaffolding level)	4/26/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST17-4/26/08	030812754-0012	North Face - West end at corner (scaffolding level)	4/26/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST1-4/27/08	030812757-0001	Southwest Area (sidewalk bridge level)	4/27/08	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST2-4/27/08	030812757-0002	Southeast Area (sidewalk bridge level)	4/27/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST4-4/27/08	030812757-0003	Northwest Area (street-level)	4/27/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST5-4/27/08	030812757-0004	Firehouse #10 (roof level)	4/27/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST10-4/27/08	030812757-0005	North Side Sidewalk Bridge	4/27/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST11-4/27/08	030812757-0006	90 Trinity Place (roof level)	4/27/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST12-4/27/08	030812757-0007	110 Greenwich Street (roof level)	4/27/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST13-4/27/08	030812757-0008	Marriott Hotel, 38th Floor (roof level)	4/27/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST14-4/27/08	030812757-0009	West Face - South end at corner (scaffolding level)	4/27/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST15-4/27/08	030812757-0010	South Face - East end at corner (scaffolding level)	4/27/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST16-4/27/08	030812757-0011	East Face - North end at corner (scaffolding level)	4/27/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	
ASBESTOS-ST17-4/27/08	030812757-0012	North Face - West end at corner (scaffolding level)	4/27/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	4/28/08	< 13.00		No	No	

Note:

1. Asbestos sample at Station 100 (Station 10 Field Duplicate) on April 23, 2008 was overloaded with carbonaceous material and not available for analysis.