

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality	Exceeds EPA	Comments
EPA Site Specific Trigger Levels										70	Levels	Site Specific	
ASBESTOS-ST1-5/5/09	030911398-0001	Southwest Area (sidewalk bridge level)	5/5/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST2-5/5/09	030911398-0002	Southeast Area (sidewalk bridge level)	5/5/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST4-5/5/09	030911398-0003	Northwest Area (street-level)	5/5/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST5-5/5/09	030911398-0004	Firehouse #10 (roof level)	5/5/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST10-5/5/09	030911398-0005	North Side Sidewalk Bridge	5/5/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST11-5/5/09	030911398-0006	90 Trinity Place (roof level)	5/5/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST12-5/5/09	030911398-0007	110 Greenwich Street (roof level)	5/5/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST13-5/5/09	030911398-0008	Marriott Hotel, 38th Floor (roof level)	5/5/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST14-5/5/09	030911398-0009	West Face - South end at corner (scaffolding level)	5/5/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST15-5/5/09	030911398-0010	South Face - East end at corner (scaffolding level)	5/5/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST16-5/5/09	030911398-0011	East Face - North end at corner (scaffolding level)	5/5/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST17-5/5/09	030911398-0012	North Face - West end at corner (scaffolding level)	5/5/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/6/09	< 13.00	No	No	
ASBESTOS-ST1-5/6/09	030911552-0001	Southwest Area (sidewalk bridge level)	5/6/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST2-5/6/09	030911552-0002	Southeast Area (sidewalk bridge level)	5/6/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST4-5/6/09	030911552-0003	Northwest Area (street-level)	5/6/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST5-5/6/09	030911552-0004	Firehouse #10 (roof level)	5/6/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST10-5/6/09	030911552-0005	North Side Sidewalk Bridge	5/6/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST11-5/6/09	030911552-0006	90 Trinity Place (roof level)	5/6/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST12-5/6/09	030911552-0007	110 Greenwich Street (roof level)	5/6/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST13-5/6/09	030911552-0008	Marriott Hotel, 38th Floor (roof level)	5/6/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST14-5/6/09	030911552-0009	West Face - South end at corner (scaffolding level)	5/6/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST15-5/6/09	030911552-0010	South Face - East end at corner (scaffolding level)	5/6/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST16-5/6/09	030911552-0011	East Face - North end at corner (scaffolding level)	5/6/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST17-5/6/09	030911552-0012	North Face - West end at corner (scaffolding level)	5/6/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/7/09	< 13.00	No	No	
ASBESTOS-ST1-5/7/09	030911647-0001	Southwest Area (sidewalk bridge level)	5/7/09	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST2-5/7/09	030911647-0002	Southeast Area (sidewalk bridge level)	5/7/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST4-5/7/09	030911647-0003	Northwest Area (street-level)	5/7/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST5-5/7/09	030911647-0004	Firehouse #10 (roof level)	5/7/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST10-5/7/09	030911647-0005	North Side Sidewalk Bridge	5/7/09	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST11-5/7/09	030911647-0006	90 Trinity Place (roof level)	5/7/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST12-5/7/09	030911647-0007	110 Greenwich Street (roof level)	5/7/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST13-5/7/09	030911647-0008	Marriott Hotel, 38th Floor (roof level)	5/7/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST14-5/7/09	030911647-0009	West Face - South end at corner (scaffolding level)	5/7/09	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST15-5/7/09	030911647-0010	South Face - East end at corner (scaffolding level)	5/7/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST16-5/7/09	030911647-0011	East Face - North end at corner (scaffolding level)	5/7/09	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST17-5/7/09	030911647-0012	North Face - West end at corner (scaffolding level)	5/7/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/8/09	< 13.00	No	No	
ASBESTOS-ST1-5/8/09	030911738-0001	Southwest Area (sidewalk bridge level)	5/8/09	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 15.00	No	No	
ASBESTOS-ST2-5/8/09	030911738-0002	Southeast Area (sidewalk bridge level)	5/8/09	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 15.00	No	No	
ASBESTOS-ST4-5/8/09	030911738-0003	Northwest Area (street-level)	5/8/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST5-5/8/09	030911738-0004	Firehouse #10 (roof level)	5/8/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST10-5/8/09	030911738-0005	North Side Sidewalk Bridge	5/8/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST11-5/8/09	030911738-0006	90 Trinity Place (roof level)	5/8/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST12-5/8/09	030911738-0007	110 Greenwich Street (roof level)	5/8/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST13-5/8/09	030911738-0008	Marriott Hotel, 38th Floor (roof level)	5/8/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST14-5/8/09	030911738-0009	West Face - South end at corner (scaffolding level)	5/8/09	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST15-5/8/09	030911738-0010	South Face - East end at corner (scaffolding level)	5/8/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST16-5/8/09	030911738-0011	East Face - North end at corner (scaffolding level)	5/8/09	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	
ASBESTOS-ST17-5/8/09	030911738-0012	North Face - West end at corner (scaffolding level)	5/8/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/9/09	< 13.00	No	No	