

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA				
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-5/15/08	030815095-0001	Southwest Area (sidewalk bridge level)	5/15/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST2-5/15/08	030815095-0002	Southeast Area (sidewalk bridge level)	5/15/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST4-5/15/08	030815095-0003	Northwest Area (street-level)	5/15/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST5-5/15/08	030815095-0004	Firehouse #10 (roof level)	5/15/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST10-5/15/08	030815095-0005	North Side Sidewalk Bridge	5/15/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST11-5/15/08	030815095-0006	90 Trinity Place (roof level)	5/15/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST12-5/15/08	030815095-0007	110 Greenwich Street (roof level)	5/15/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST13-5/15/08	030815095-0008	Marriott Hotel, 38th Floor (roof level)	5/15/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST14-5/15/08	030815095-0009	West Face - South end at corner (scaffolding level)	5/15/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST15-5/15/08	030815095-0010	South Face - East end at corner (scaffolding level)	5/15/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST16-5/15/08	030815095-0011	East Face - North end at corner (scaffolding level)	5/15/08	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST17-5/15/08	030815095-0012	North Face - West end at corner (scaffolding level)	5/15/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST1-5/16/08	030815093-0001	Southwest Area (sidewalk bridge level)	5/16/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST2-5/16/08	030815093-0002	Southeast Area (sidewalk bridge level)	5/16/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST4-5/16/08	030815093-0003	Northwest Area (street-level)	5/16/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST5-5/16/08	030815093-0004	Firehouse #10 (roof level)	5/16/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST10-5/16/08	030815093-0005	North Side Sidewalk Bridge	5/16/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST11-5/16/08	030815093-0006	90 Trinity Place (roof level)	5/16/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST12-5/16/08	030815093-0007	110 Greenwich Street (roof level)	5/16/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST13-5/16/08	030815093-0008	Marriott Hotel, 38th Floor (roof level)	5/16/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST14-5/16/08	030815093-0009	West Face - South end at corner (scaffolding level)	5/16/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST15-5/16/08	030815093-0010	South Face - East end at corner (scaffolding level)	5/16/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST16-5/16/08	030815093-0011	East Face - North end at corner (scaffolding level)	5/16/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST17-5/16/08	030815093-0012	North Face - West end at corner (scaffolding level)	5/16/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/17/08	< 13.00	No	No		
ASBESTOS-ST1-5/17/08	030815260-0001	Southwest Area (sidewalk bridge level)	5/17/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST2-5/17/08	030815260-0002	Southeast Area (sidewalk bridge level)	5/17/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST4-5/17/08	030815260-0003	Northwest Area (street-level)	5/17/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST5-5/17/08	030815260-0004	Firehouse #10 (roof level)	5/17/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST10-5/17/08	030815260-0005	North Side Sidewalk Bridge	5/17/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST11-5/17/08	030815260-0006	90 Trinity Place (roof level)	5/17/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST12-5/17/08	030815260-0007	110 Greenwich Street (roof level)	5/17/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST13-5/17/08	030815260-0008	Marriott Hotel, 38th Floor (roof level)	5/17/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST14-5/17/08	030815260-0009	West Face - South end at corner (scaffolding level)	5/17/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST15-5/17/08	030815260-0010	South Face - East end at corner (scaffolding level)	5/17/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST16-5/17/08	030815260-0011	East Face - North end at corner (scaffolding level)	5/17/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST17-5/17/08	030815260-0012	North Face - West end at corner (scaffolding level)	5/17/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST1-5/18/08	030815288-0001	Southwest Area (sidewalk bridge level)	5/18/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST2-5/18/08	030815288-0002	Southeast Area (sidewalk bridge level)	5/18/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 15.00	No	No		
ASBESTOS-ST4-5/18/08	030815288-0003	Northwest Area (street-level)	5/18/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 15.00	No	No		
ASBESTOS-ST5-5/18/08	030815288-0004	Firehouse #10 (roof level)	5/18/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST10-5/18/08	030815288-0005	North Side Sidewalk Bridge	5/18/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST11-5/18/08	030815288-0006	90 Trinity Place (roof level)	5/18/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST12-5/18/08	030815288-0007	110 Greenwich Street (roof level)	5/18/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST13-5/18/08	030815288-0008	Marriott Hotel, 38th Floor (roof level)	5/18/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 15.00	No	No		
ASBESTOS-ST15-5/18/08	030815288-0009	South Face - East end at corner (scaffolding level)	5/18/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST16-5/18/08	030815288-0010	East Face - North end at corner (scaffolding level)	5/18/08	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST17-5/18/08	030815288-0011	North Face - West end at corner (scaffolding level)	5/18/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/19/08	< 13.00	No	No		
ASBESTOS-ST1-5/19/08	030815408-0001	Southwest Area (sidewalk bridge level)	5/19/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST2-5/19/08	030815408-0002	Southeast Area (sidewalk bridge level)	5/19/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST4-5/19/08	030815408-0003	Northwest Area (street-level)	5/19/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST5-5/19/08	030815408-0004	Firehouse #10 (roof level)	5/19/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST10-5/19/08	030815408-0005	North Side Sidewalk Bridge	5/19/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST11-5/19/08	030815408-0006	90 Trinity Place (roof level)	5/19/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST12-5/19/08	030815408-0007	110 Greenwich Street (roof level)	5/19/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST13-5/19/08	030815408-0008	Marriott Hotel, 38th Floor (roof level)	5/19/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST14-5/19/08	030815408-0009	West Face - South end at corner (scaffolding level)	5/19/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST15-5/19/08	030815408-0010	South Face - East end at corner (scaffolding level)	5/19/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST16-5/19/08	030815408-0011	East Face - North end at corner (scaffolding level)	5/19/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		
ASBESTOS-ST17-5/19/08	030815408-0012	North Face - West end at corner (scaffolding level)	5/19/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/20/08	< 13.00	No	No		

Note:
1. Asbestos sample at Station 14 (West Face - South end at corner [scaffolding level]) on May 18, 2008 was not available for analysis on account of power failure.