

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-5/26/06	030616432-0001	Southwest Area (sidewalk bridge level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST2-5/26/06	030616432-0002	Southeast Area (sidewalk bridge level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST4-5/26/06	030616432-0003	Northwest Area (street-level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST5-5/26/06	030616432-0004	Firehouse #10 (roof level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST10-5/26/06	030616432-0005	North Side Sidewalk Bridge	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST11-5/26/06	030616432-0006	90 Trinity Place (roof level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST12-5/26/06	030616432-0007	110 Greenwich Street (roof level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST13-5/26/06	030616432-0008	Marriott Hotel, 38th Floor (roof level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST14-5/26/06	030616432-0009	West Face - South end at corner (scaffolding level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST15-5/26/06	030616432-0010	South Face - East end at corner (scaffolding level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST16-5/26/06	030616432-0011	East Face - North end at corner (scaffolding level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST17-5/26/06	030616432-0012	North Face - West end at corner (scaffolding level)	5/26/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST1-5/27/06	030616433-0001	Southwest Area (sidewalk bridge level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST2-5/27/06	030616433-0002	Southeast Area (sidewalk bridge level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST4-5/27/06	030616433-0003	Northwest Area (street-level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST5-5/27/06	030616433-0004	Firehouse #10 (roof level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST10-5/27/06	030616433-0005	North Side Sidewalk Bridge	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST11-5/27/06	030616433-0006	90 Trinity Place (roof level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST12-5/27/06	030616433-0007	110 Greenwich Street (roof level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST13-5/27/06	030616433-0008	Marriott Hotel, 38th Floor (roof level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST14-5/27/06	030616433-0009	West Face - South end at corner (scaffolding level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST15-5/27/06	030616433-0010	South Face - East end at corner (scaffolding level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST16-5/27/06	030616433-0011	East Face - North end at corner (scaffolding level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST17-5/27/06	030616433-0012	North Face - West end at corner (scaffolding level)	5/27/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST1-5/28/06	030616434-0001	Southwest Area (sidewalk bridge level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST2-5/28/06	030616434-0002	Southeast Area (sidewalk bridge level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST4-5/28/06	030616434-0003	Northwest Area (street-level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST5-5/28/06	030616434-0004	Firehouse #10 (roof level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST10-5/28/06	030616434-0005	North Side Sidewalk Bridge	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST11-5/28/06	030616434-0006	90 Trinity Place (roof level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST12-5/28/06	030616434-0007	110 Greenwich Street (roof level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST13-5/28/06	030616434-0008	Marriott Hotel, 38th Floor (roof level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST14-5/28/06	030616434-0009	West Face - South end at corner (scaffolding level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST15-5/28/06	030616434-0010	South Face - East end at corner (scaffolding level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST16-5/28/06	030616434-0011	East Face - North end at corner (scaffolding level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST17-5/28/06	030616434-0012	North Face - West end at corner (scaffolding level)	5/28/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST1-5/29/06	030616435-0001	Southwest Area (sidewalk bridge level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST2-5/29/06	030616435-0002	Southeast Area (sidewalk bridge level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST4-5/29/06	030616435-0003	Northwest Area (street-level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST5-5/29/06	030616435-0004	Firehouse #10 (roof level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST10-5/29/06	030616435-0005	North Side Sidewalk Bridge	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST11-5/29/06	030616435-0006	90 Trinity Place (roof level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST12-5/29/06	030616435-0007	110 Greenwich Street (roof level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST14-5/29/06	030616435-0009	West Face - South end at corner (scaffolding level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST15-5/29/06	030616435-0010	South Face - East end at corner (scaffolding level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST16-5/29/06	030616435-0011	East Face - North end at corner (scaffolding level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	
ASBESTOS-ST17-5/29/06	030616435-0012	North Face - West end at corner (scaffolding level)	5/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	5/30/06	< 13.00	No	No	

Note:

1. Asbestos sample at Station 13 (Marriott Hotel, 38th Floor [roof level]) on May 29, 2006 was not available for analysis on account of a damaged filter.