

| TRC Field Sample No. | Sample No.     | Sampling Location                                   | Collection Start Date | Work Shift | Sample Volume (m <sup>3</sup> ) | Analyte  | Analytical Method               | Lab  | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target     | Exceeds EPA                  | Comments |
|----------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|--------------------|------------------------------|----------|
|                      |                |   |                       |            |                                 |          |                                 |      |                         | NA                                   | Air Quality Levels | Site Specific Trigger Levels |          |
|                      |                |   |                       |            |                                 |          |                                 |      |                         | 70                                   |                    |                              |          |
|                      |                |   |                       |            |                                 |          |                                 |      |                         |                                      |                    |                              |          |
| ASBESTOS-ST1-6/1/07  | 030717860-0001 | Southwest Area (sidewalk bridge level)              | 6/1/07                | 1          | 2.970                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST2-6/1/07  | 030717860-0002 | Southeast Area (sidewalk bridge level)              | 6/1/07                | 1          | 3.030                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST4-6/1/07  | 030717860-0003 | Northwest Area (street-level)                       | 6/1/07                | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST5-6/1/07  | 030717860-0004 | Firehouse #10 (roof level)                          | 6/1/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST10-6/1/07 | 030717860-0005 | North Side Sidewalk Bridge                          | 6/1/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST11-6/1/07 | 030717860-0006 | 90 Trinity Place (roof level)                       | 6/1/07                | 1          | 3.070                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST12-6/1/07 | 030717860-0007 | 110 Greenwich Street (roof level)                   | 6/1/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST13-6/1/07 | 030717860-0008 | Marriott Hotel, 38th Floor (roof level)             | 6/1/07                | 1          | 3.090                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST14-6/1/07 | 030717860-0009 | West Face - South end at corner (scaffolding level) | 6/1/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST15-6/1/07 | 030717860-0010 | South Face - East end at corner (scaffolding level) | 6/1/07                | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST16-6/1/07 | 030717860-0011 | East Face - North end at corner (scaffolding level) | 6/1/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST17-6/1/07 | 030717860-0012 | North Face - West end at corner (scaffolding level) | 6/1/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST1-6/2/07  | 030717861-0001 | Southwest Area (sidewalk bridge level)              | 6/2/07                | 1          | 3.350                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST2-6/2/07  | 030717861-0002 | Southeast Area (sidewalk bridge level)              | 6/2/07                | 1          | 3.070                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST4-6/2/07  | 030717861-0003 | Northwest Area (street-level)                       | 6/2/07                | 1          | 2.940                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST5-6/2/07  | 030717861-0004 | Firehouse #10 (roof level)                          | 6/2/07                | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST10-6/2/07 | 030717861-0005 | North Side Sidewalk Bridge                          | 6/2/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST11-6/2/07 | 030717861-0006 | 90 Trinity Place (roof level)                       | 6/2/07                | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST12-6/2/07 | 030717861-0007 | 110 Greenwich Street (roof level)                   | 6/2/07                | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST13-6/2/07 | 030717861-0008 | Marriott Hotel, 38th Floor (roof level)             | 6/2/07                | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST14-6/2/07 | 030717861-0009 | West Face - South end at corner (scaffolding level) | 6/2/07                | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST15-6/2/07 | 030717861-0010 | South Face - East end at corner (scaffolding level) | 6/2/07                | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST16-6/2/07 | 030717861-0011 | East Face - North end at corner (scaffolding level) | 6/2/07                | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST17-6/2/07 | 030717861-0012 | North Face - West end at corner (scaffolding level) | 6/2/07                | 1          | 3.020                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST1-6/3/07  | 030717862-0001 | Southwest Area (sidewalk bridge level)              | 6/3/07                | 1          | 2.960                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST2-6/3/07  | 030717862-0002 | Southeast Area (sidewalk bridge level)              | 6/3/07                | 1          | 3.070                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST4-6/3/07  | 030717862-0003 | Northwest Area (street-level)                       | 6/3/07                | 1          | 2.990                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST5-6/3/07  | 030717862-0004 | Firehouse #10 (roof level)                          | 6/3/07                | 1          | 3.060                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST10-6/3/07 | 030717862-0005 | North Side Sidewalk Bridge                          | 6/3/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST11-6/3/07 | 030717862-0006 | 90 Trinity Place (roof level)                       | 6/3/07                | 1          | 2.960                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST12-6/3/07 | 030717862-0007 | 110 Greenwich Street (roof level)                   | 6/3/07                | 1          | 2.970                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST13-6/3/07 | 030717862-0008 | Marriott Hotel, 38th Floor (roof level)             | 6/3/07                | 1          | 3.010                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST14-6/3/07 | 030717862-0009 | West Face - South end at corner (scaffolding level) | 6/3/07                | 1          | 3.080                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST15-6/3/07 | 030717862-0010 | South Face - East end at corner (scaffolding level) | 6/3/07                | 1          | 3.040                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST16-6/3/07 | 030717862-0011 | East Face - North end at corner (scaffolding level) | 6/3/07                | 1          | 3.000                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |
| ASBESTOS-ST17-6/3/07 | 030717862-0012 | North Face - West end at corner (scaffolding level) | 6/3/07                | 1          | 3.030                           | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/4/07                  | < 13.00                              | No                 | No                           |          |