

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
										<b>Target Air Quality Levels</b>			
										<b>EPA Site Specific Trigger Levels</b>			
ASBESTOS-ST1-6/6/07	030718250-0001	Southwest Area (sidewalk bridge level)	6/6/07	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST2-6/6/07	030718250-0002	Southeast Area (sidewalk bridge level)	6/6/07	1	2.620	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	Note 1
ASBESTOS-ST4-6/6/07	030718250-0003	Northwest Area (street-level)	6/6/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST5-6/6/07	030718250-0004	Firehouse #10 (roof level)	6/6/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST10-6/6/07	030718250-0005	North Side Sidewalk Bridge	6/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST11-6/6/07	030718250-0006	90 Trinity Place (roof level)	6/6/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST12-6/6/07	030718250-0007	110 Greenwich Street (roof level)	6/6/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST13-6/6/07	030718250-0008	Marriott Hotel, 38th Floor (roof level)	6/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST14-6/6/07	030718250-0009	West Face - South end at corner (scaffolding level)	6/6/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST15-6/6/07	030718250-0010	South Face - East end at corner (scaffolding level)	6/6/07	1	3.340	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST17-6/6/07	030718250-0011	North Face - West end at corner (scaffolding level)	6/6/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/7/07	< 13.00	No	No	
ASBESTOS-ST1-6/7/07	030718416-0001	Southwest Area (sidewalk bridge level)	6/7/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST2-6/7/07	030718416-0002	Southeast Area (sidewalk bridge level)	6/7/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST5-6/7/07	030718416-0003	Firehouse #10 (roof level)	6/7/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST10-6/7/07	030718416-0004	North Side Sidewalk Bridge	6/7/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST11-6/7/07	030718416-0005	90 Trinity Place (roof level)	6/7/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST12-6/7/07	030718416-0006	110 Greenwich Street (roof level)	6/7/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST13-6/7/07	030718416-0007	Marriott Hotel, 38th Floor (roof level)	6/7/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST14-6/7/07	030718416-0008	West Face - South end at corner (scaffolding level)	6/7/07	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST15-6/7/07	030718416-0009	South Face - East end at corner (scaffolding level)	6/7/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST16-6/7/07	030718416-0010	East Face - North end at corner (scaffolding level)	6/7/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	
ASBESTOS-ST17-6/7/07	030718416-0011	North Face - West end at corner (scaffolding level)	6/7/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/8/07	< 13.00	No	No	

Note:

1. Due to flow rate RPD exceedance (30.8%) for asbestos at Station 2 (Southeast Area [sidewalk bridge level]) on June 6, 2007, the sample volume and subsequent sample result are estimated.
2. Asbestos sample at Station 16 (East Face - North end at corner [scaffolding level]) on June 6, 2007 was not available for analysis on account of operator error.
3. Asbestos sample at Station 4 (Northwest Area [street-level]) on June 7, 2007 was not available for analysis on account of pump failure.