

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										Target Air Quality Levels				
										NA	70			
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-6/12/08	030818331-0001	Southwest Area (sidewalk bridge level)	6/12/08	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST2-6/12/08	030818331-0002	Southeast Area (sidewalk bridge level)	6/12/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST4-6/12/08	030818331-0003	Northwest Area (street-level)	6/12/08	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST5-6/12/08	030818331-0004	Firehouse #10 (roof level)	6/12/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST10-6/12/08	030818331-0005	North Side Sidewalk Bridge	6/12/08	1	2.600	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	Note 1
ASBESTOS-ST11-6/12/08	030818331-0006	90 Trinity Place (roof level)	6/12/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST12-6/12/08	030818331-0007	110 Greenwich Street (roof level)	6/12/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST13-6/12/08	030818331-0008	Marriott Hotel, 38th Floor (roof level)	6/12/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST14-6/12/08	030818331-0009	West Face - South end at corner (scaffolding level)	6/12/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST15-6/12/08	030818331-0010	South Face - East end at corner (scaffolding level)	6/12/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST16-6/12/08	030818331-0011	East Face - North end at corner (scaffolding level)	6/12/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST17-6/12/08	030818331-0012	North Face - West end at corner (scaffolding level)	6/12/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/13/08	< 13.00		No	No	
ASBESTOS-ST1-6/13/08	030818468-0001	Southwest Area (sidewalk bridge level)	6/13/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST2-6/13/08	030818468-0002	Southeast Area (sidewalk bridge level)	6/13/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST4-6/13/08	030818468-0003	Northwest Area (street-level)	6/13/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST5-6/13/08	030818468-0004	Firehouse #10 (roof level)	6/13/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST10-6/13/08	030818468-0005	North Side Sidewalk Bridge	6/13/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST100-6/13/08	030818468-0013	Station 10 Field Duplicate	6/13/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST11-6/13/08	030818468-0006	90 Trinity Place (roof level)	6/13/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST12-6/13/08	030818468-0007	110 Greenwich Street (roof level)	6/13/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST13-6/13/08	030818468-0008	Marriott Hotel, 38th Floor (roof level)	6/13/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST14-6/13/08	030818468-0009	West Face - South end at corner (scaffolding level)	6/13/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST15-6/13/08	030818468-0010	South Face - East end at corner (scaffolding level)	6/13/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST16-6/13/08	030818468-0011	East Face - North end at corner (scaffolding level)	6/13/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST17-6/13/08	030818468-0012	North Face - West end at corner (scaffolding level)	6/13/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/14/08	< 13.00		No	No	
ASBESTOS-ST1-6/14/08	030818572-0001	Southwest Area (sidewalk bridge level)	6/14/08	1	3.170	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 15.00		No	No	
ASBESTOS-ST2-6/14/08	030818572-0002	Southeast Area (sidewalk bridge level)	6/14/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 15.00		No	No	
ASBESTOS-ST4-6/14/08	030818572-0003	Northwest Area (street-level)	6/14/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 15.00		No	No	
ASBESTOS-ST5-6/14/08	030818572-0004	Firehouse #10 (roof level)	6/14/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 15.00		No	No	
ASBESTOS-ST10-6/14/08	030818572-0005	North Side Sidewalk Bridge	6/14/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 15.00		No	No	
ASBESTOS-ST11-6/14/08	030818572-0006	90 Trinity Place (roof level)	6/14/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST12-6/14/08	030818572-0007	110 Greenwich Street (roof level)	6/14/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST13-6/14/08	030818572-0008	Marriott Hotel, 38th Floor (roof level)	6/14/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST14-6/14/08	030818572-0009	West Face - South end at corner (scaffolding level)	6/14/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST15-6/14/08	030818572-0010	South Face - East end at corner (scaffolding level)	6/14/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST16-6/14/08	030818572-0011	East Face - North end at corner (scaffolding level)	6/14/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST17-6/14/08	030818572-0012	North Face - West end at corner (scaffolding level)	6/14/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST1-6/15/08	030818639-0001	Southwest Area (sidewalk bridge level)	6/15/08	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST2-6/15/08	030818639-0002	Southeast Area (sidewalk bridge level)	6/15/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST4-6/15/08	030818639-0003	Northwest Area (street-level)	6/15/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST5-6/15/08	030818639-0004	Firehouse #10 (roof level)	6/15/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST10-6/15/08	030818639-0005	North Side Sidewalk Bridge	6/15/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST11-6/15/08	030818639-0006	90 Trinity Place (roof level)	6/15/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST12-6/15/08	030818639-0007	110 Greenwich Street (roof level)	6/15/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST13-6/15/08	030818639-0008	Marriott Hotel, 38th Floor (roof level)	6/15/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST14-6/15/08	030818639-0009	West Face - South end at corner (scaffolding level)	6/15/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST15-6/15/08	030818639-0010	South Face - East end at corner (scaffolding level)	6/15/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST16-6/15/08	030818639-0011	East Face - North end at corner (scaffolding level)	6/15/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	
ASBESTOS-ST17-6/15/08	030818639-0012	North Face - West end at corner (scaffolding level)	6/15/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/16/08	< 13.00		No	No	

Note:
1. Due to flow rate RPD exceedance (33.0%) for asbestos at Station 10 (North Side Sidewalk Bridge) on June 12, 2008, the sample volume and subsequent sample result are estimated.