

| TRC Field Sample No. | Sample No. | Sampling Location | Collection Start Date | Work Shift | Sample Volume (m ³) | Analyte | Analytical Method | Lab | Lab Sample Receipt Date | Asbestos AHERA Concentration (S/mm2) | Exceeds Target | Exceeds EPA | Comments |
|----------------------------------|----------------|---|-----------------------|------------|---------------------------------|----------|---------------------------------|------|-------------------------|--------------------------------------|----------------|----------------|----------|
| Target Air Quality Levels | | | | | | | | | | NA | Air Quality | Site Specific | Comments |
| EPA Site Specific Trigger Levels | | | | | | | | | | 70 | Levels | Trigger Levels | |
| ASBESTOS-ST1-6/13/06 | 030618088-0001 | Southwest Area (sidewalk bridge level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-6/13/06 | 030618088-0002 | Southeast Area (sidewalk bridge level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-6/13/06 | 030618088-0003 | Northwest Area (street-level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-6/13/06 | 030618088-0004 | Firehouse #10 (roof level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-6/13/06 | 030618088-0005 | North Side Sidewalk Bridge | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-6/13/06 | 030618088-0006 | 90 Trinity Place (roof level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-6/13/06 | 030618088-0007 | 110 Greenwich Street (roof level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-6/13/06 | 030618088-0008 | Marriott Hotel, 38th Floor (roof level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-6/13/06 | 030618088-0009 | West Face - South end at corner (scaffolding level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-6/13/06 | 030618088-0010 | South Face - East end at corner (scaffolding level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST16-6/13/06 | 030618088-0011 | East Face - North end at corner (scaffolding level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-6/13/06 | 030618088-0012 | North Face - West end at corner (scaffolding level) | 6/13/06 | 1 | 2.970 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/14/06 | < 13.00 | No | No | |
| ASBESTOS-ST1-6/14/06 | 030618231-0001 | Southwest Area (sidewalk bridge level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST2-6/14/06 | 030618231-0002 | Southeast Area (sidewalk bridge level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST4-6/14/06 | 030618231-0003 | Northwest Area (street-level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST5-6/14/06 | 030618231-0004 | Firehouse #10 (roof level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST10-6/14/06 | 030618231-0005 | North Side Sidewalk Bridge | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST11-6/14/06 | 030618231-0006 | 90 Trinity Place (roof level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST12-6/14/06 | 030618231-0007 | 110 Greenwich Street (roof level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST13-6/14/06 | 030618231-0008 | Marriott Hotel, 38th Floor (roof level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST14-6/14/06 | 030618231-0009 | West Face - South end at corner (scaffolding level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST15-6/14/06 | 030618231-0010 | South Face - East end at corner (scaffolding level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST16-6/14/06 | 030618231-0011 | East Face - North end at corner (scaffolding level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |
| ASBESTOS-ST17-6/14/06 | 030618231-0012 | North Face - West end at corner (scaffolding level) | 6/14/06 | 1 | 2.940 | Asbestos | TEM EPA 40 CFR PART 763 (AHERA) | EMSL | 6/15/06 | < 13.00 | No | No | |