

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-6/22/09	030915494-0001	Southwest Area (sidewalk bridge level)	6/22/09	1	3.220	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/09	< 13.00	No	No	
ASBESTOS-ST2-6/22/09	030915494-0002	Southeast Area (sidewalk bridge level)	6/22/09	1	3.220	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/09	< 13.00	No	No	
ASBESTOS-ST4-6/22/09	030915494-0003	Northwest Area (street-level)	6/22/09	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/09	< 13.00	No	No	
ASBESTOS-ST5-6/22/09	030915494-0004	Firehouse #10 (roof level)	6/22/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/09	< 13.00	No	No	
ASBESTOS-ST10-6/22/09	030915494-0005	North Side Sidewalk Bridge	6/22/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/09	< 13.00	No	No	
ASBESTOS-ST11-6/22/09	030915494-0006	90 Trinity Place (roof level)	6/22/09	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/09	< 13.00	No	No	
ASBESTOS-ST12-6/22/09	030915494-0007	110 Greenwich Street (roof level)	6/22/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/09	< 13.00	No	No	
ASBESTOS-ST13-6/22/09	030915494-0008	Marriott Hotel, 38th Floor (roof level)	6/22/09	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/23/09	< 13.00	No	No	
ASBESTOS-ST1-6/23/09	030915664-0001	Southwest Area (sidewalk bridge level)	6/23/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	Note 1
ASBESTOS-ST2-6/23/09	030915664-0002	Southeast Area (sidewalk bridge level)	6/23/09	1	2.850	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	Note 2
ASBESTOS-ST4-6/23/09	030915664-0003	Northwest Area (street-level)	6/23/09	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	
ASBESTOS-ST5-6/23/09	030915664-0004	Firehouse #10 (roof level)	6/23/09	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	Note 1
ASBESTOS-ST10-6/23/09	030915664-0005	North Side Sidewalk Bridge	6/23/09	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	
ASBESTOS-ST100-6/23/09	030915664-0009	Station 10 Field Duplicate	6/23/09	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	
ASBESTOS-ST11-6/23/09	030915664-0006	90 Trinity Place (roof level)	6/23/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	
ASBESTOS-ST12-6/23/09	030915664-0007	110 Greenwich Street (roof level)	6/23/09	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	
ASBESTOS-ST13-6/23/09	030915664-0008	Marriott Hotel, 38th Floor (roof level)	6/23/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	6/24/09	< 13.00	No	No	

Note:

1. The asbestos samples from Station 1 (Southwest Area [sidewalk bridge level]) and Station 5 (Firehouse #10 [roof level]) on June 23, 2009 had reduced volumes due to a 90 minute planned power outage.
2. The asbestos sample from Station 2 (Southeast Area [sidewalk bridge level]) on June 23, 2009 had a reduced volume due to a 130 minute power outage.