

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels											70	Levels	Trigger Levels	
ASBESTOS-ST1-7/13/07	030723239-0001	Southwest Area (sidewalk bridge level)	7/13/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST2-7/13/07	030723239-0002	Southeast Area (sidewalk bridge level)	7/13/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST4-7/13/07	030723239-0003	Northwest Area (street-level)	7/13/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST5-7/13/07	030723239-0004	Firehouse #10 (roof level)	7/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST10-7/13/07	030723239-0005	North Side Sidewalk Bridge	7/13/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST100-7/13/07	030723239-0013	Station 10 Field Duplicate	7/13/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST11-7/13/07	030723239-0006	90 Trinity Place (roof level)	7/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST12-7/13/07	030723239-0007	110 Greenwich Street (roof level)	7/13/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST13-7/13/07	030723239-0008	Marriott Hotel, 38th Floor (roof level)	7/13/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST14-7/13/07	030723239-0009	West Face - South end at corner (scaffolding level)	7/13/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST15-7/13/07	030723239-0010	South Face - East end at corner (scaffolding level)	7/13/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST16-7/13/07	030723239-0011	East Face - North end at corner (scaffolding level)	7/13/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST17-7/13/07	030723239-0012	North Face - West end at corner (scaffolding level)	7/13/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/14/07	< 13.00	No	No		
ASBESTOS-ST1-7/14/07	030723413-0001	Southwest Area (sidewalk bridge level)	7/14/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 15.00	No	No		
ASBESTOS-ST2-7/14/07	030723413-0002	Southeast Area (sidewalk bridge level)	7/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 15.00	No	No		
ASBESTOS-ST5-7/14/07	030723413-0003	Firehouse #10 (roof level)	7/14/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 15.00	No	No		
ASBESTOS-ST10-7/14/07	030723413-0004	North Side Sidewalk Bridge	7/14/07	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST11-7/14/07	030723413-0005	90 Trinity Place (roof level)	7/14/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST12-7/14/07	030723413-0006	110 Greenwich Street (roof level)	7/14/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST13-7/14/07	030723413-0007	Marriott Hotel, 38th Floor (roof level)	7/14/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST14-7/14/07	030723413-0008	West Face - South end at corner (scaffolding level)	7/14/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST15-7/14/07	030723413-0009	South Face - East end at corner (scaffolding level)	7/14/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST16-7/14/07	030723413-0010	East Face - North end at corner (scaffolding level)	7/14/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST17-7/14/07	030723413-0011	North Face - West end at corner (scaffolding level)	7/14/07	1	2.370	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 11.00	No	No		
ASBESTOS-ST1-7/15/07	030723415-0001	Southwest Area (sidewalk bridge level)	7/15/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST2-7/15/07	030723415-0002	Southeast Area (sidewalk bridge level)	7/15/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST5-7/15/07	030723415-0003	Firehouse #10 (roof level)	7/15/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST10-7/15/07	030723415-0004	North Side Sidewalk Bridge	7/15/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST11-7/15/07	030723415-0005	90 Trinity Place (roof level)	7/15/07	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST13-7/15/07	030723415-0006	Marriott Hotel, 38th Floor (roof level)	7/15/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST14-7/15/07	030723415-0007	West Face - South end at corner (scaffolding level)	7/15/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST15-7/15/07	030723415-0008	South Face - East end at corner (scaffolding level)	7/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST16-7/15/07	030723415-0009	East Face - North end at corner (scaffolding level)	7/15/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		
ASBESTOS-ST17-7/15/07	030723415-0010	North Face - West end at corner (scaffolding level)	7/15/07	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	7/16/07	< 13.00	No	No		

Note:

1. Asbestos samples at Station 4 (Northwest Area [street-level]) on July 14 and 15, 2007 were not available for analysis on account of power failure.
2. Asbestos sample at Station 12 (110 Greenwich Street [roof level]) on July 15, 2007 was not available for analysis. The station was not accessible and the sample could not be collected.