

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-8/17/07	030728305-0001	Southwest Area (sidewalk bridge level)	8/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST2-8/17/07	030728305-0002	Southeast Area (sidewalk bridge level)	8/17/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST4-8/17/07	030728305-0003	Northwest Area (street-level)	8/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST5-8/17/07	030728305-0004	Firehouse #10 (roof level)	8/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST10-8/17/07	030728305-0005	North Side Sidewalk Bridge	8/17/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST11-8/17/07	030728305-0006	90 Trinity Place (roof level)	8/17/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST12-8/17/07	030728305-0007	110 Greenwich Street (roof level)	8/17/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST13-8/17/07	030728305-0008	Marriott Hotel, 38th Floor (roof level)	8/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST14-8/17/07	030728305-0009	West Face - South end at corner (scaffolding level)	8/17/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST15-8/17/07	030728305-0010	South Face - East end at corner (scaffolding level)	8/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST16-8/17/07	030728305-0011	East Face - North end at corner (scaffolding level)	8/17/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST17-8/17/07	030728305-0012	North Face - West end at corner (scaffolding level)	8/17/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST1-8/18/07	030728279-0001	Southwest Area (sidewalk bridge level)	8/18/07	1	2.750	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 19.00	No	No	
ASBESTOS-ST2-8/18/07	030728279-0002	Southeast Area (sidewalk bridge level)	8/18/07	1	2.770	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 19.00	No	No	
ASBESTOS-ST5-8/18/07	030728278-0001	Firehouse #10 (roof level)	8/18/07	1	2.430	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 19.00	No	No	
ASBESTOS-ST10-8/18/07	030728278-0002	North Side Sidewalk Bridge	8/18/07	1	2.590	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 19.00	No	No	
ASBESTOS-ST11-8/18/07	030728288-0006	90 Trinity Place (roof level)	8/18/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 13.00	No	No	
ASBESTOS-ST12-8/18/07	030728278-0003	110 Greenwich Street (roof level)	8/18/07	1	2.470	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 19.00	No	No	
ASBESTOS-ST13-8/18/07	030728278-0004	Marriott Hotel, 38th Floor (roof level)	8/18/07	1	2.440	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/19/07	< 19.00	No	No	
ASBESTOS-ST1-8/19/07	030729526-0001	Southwest Area (sidewalk bridge level)	8/19/07	1	23.750	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/28/07	6.17	No	No	Result represents conditions from 8/19/07 through 8/28/07
ASBESTOS-ST4-8/19/07	030728415-0001	Northwest Area (street-level)	8/19/07	1	2.830	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/20/07	< 13.00	No	No	
ASBESTOS-ST5-8/19/07	030728415-0002	Firehouse #10 (roof level)	8/19/07	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/20/07	< 13.00	No	No	
ASBESTOS-ST10-8/19/07	030728415-0003	North Side Sidewalk Bridge	8/19/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/20/07	< 13.00	No	No	
ASBESTOS-ST11-8/19/07	030728415-0004	90 Trinity Place (roof level)	8/19/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/20/07	< 13.00	No	No	
ASBESTOS-ST12-8/19/07	030728415-0005	110 Greenwich Street (roof level)	8/19/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/20/07	< 13.00	No	No	
ASBESTOS-ST13-8/19/07	030728415-0006	Marriott Hotel, 38th Floor (roof level)	8/19/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/20/07	< 13.00	No	No	
ASBESTOS-ST17-8/19/07	030729351-0006	North Face - West end at corner (scaffolding level)	8/19/07	1	23.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/07	8.50	No	No	Result represents conditions from 8/19/07 through 8/27/07

Note:

- Asbestos results at Station 4 (Northwest Area [street-level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]) and Station 17 (North Face - West end at corner [scaffolding level]), on August 18, 2007 were not available as these samples were overloaded with carbanaceous particulate and completely obscured and could be analyzed.
- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]) on August 18, 2007 was not available for analysis on account of power failure.
- Asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on August 19, 2007 is not available as this sample was overloaded with carbanaceous particulate and completely obscured and could therefore not be analyzed.
- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]) on August 19, 2007 was not available for analysis on account of pump failure.
- Asbestos results at Station 15 (South Face - East end at corner [scaffolding level]) and Station 16 (East Face - North end at corner [scaffolding level]) on August 19, 2007 were not available as these samples were overloaded with carbanaceous particulate and completely obscured and could therefore not be analyzed.

erefore not be analyze