TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	
	NA	Air Quality	Site Specific	Comments									
	70	Levels	Trigger Levels										
ASBESTOS-ST5-8/25/07	030729248-0001	Firehouse #10 (roof level)	8/25/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/26/07	< 13.00	No	No	
ASBESTOS-ST10-8/25/07	030729248-0002	North Side Sidewalk Bridge	8/25/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/26/07	< 13.00	No	No	
ASBESTOS-ST11-8/25/07	030729248-0003	90 Trinity Place (roof level)	8/25/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/26/07	< 13.00	No	No	
ASBESTOS-ST12-8/25/07	030729248-0004	110 Greenwich Street (roof level)	8/25/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/26/07	< 13.00	No	No	
ASBESTOS-ST13-8/25/07	030729248-0005	Marriott Hotel, 38th Floor (roof level)	8/25/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/26/07	< 13.00	No	No	
ASBESTOS-ST5-8/26/07	030729353-0001	Firehouse #10 (roof level)	8/26/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/07	< 13.00	No	No	
ASBESTOS-ST10-8/26/07	030729353-0002	North Side Sidewalk Bridge	8/26/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/07	< 13.00	No	No	
ASBESTOS-ST11-8/26/07	030729353-0003	90 Trinity Place (roof level)	8/26/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/07	< 13.00	No	No	
ASBESTOS-ST12-8/26/07	030729353-0004	110 Greenwich Street (roof level)	8/26/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/07	< 13.00	No	No	
ASBESTOS-ST13-8/26/07	030729353-0005	Marriott Hotel, 38th Floor (roof level)	8/26/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/27/07	< 13.00	No	No	

- 1. Asbestos samples at Station 1 (Southwest Area [sidewalk bridge level]) and Station 2 (Southeast Area [sidewalk bridge level]) on August 25, 2007 were not collected. The stations were not accessible on account of a fire at 130 Liberty Street that caused unsafe conditions in the vicinity of the stations.
- 2. Asbestos result at Station 4 (Northwest Area [street-level]) on August 25, 2007 is not available as this sample was overloaded with carbanaceous particulate and completely obscured and could therefore not be analyzed.
- 3. Asbestos samples at Station 1 (Southwest Area [sidewalk bridge level]), Station 2 (Southeast Area [sidewalk bridge level]) and Station 4 (Northwest Area [street-level]) on August 26, 2007 were not collected. The stations were not accessible on account of a fire at 130 Liberty Street that caused unsafe conditions in the vicinity of the stations.
- 4. Asbestos samples at Station 14 (West Face South end at corner [scaffolding level]), Station 15 [South Face East end at corner [scaffolding level]), Station 16 (East Face North end at corner [scaffolding level]) and Station 17 (North Face West end at corner [scaffolding level]) on August 25 and 26, 2007 were not collected. The stations were not accessible on account of a fire at 130 Liberty Street.

Page 1 of 1 130 Liberty Street Deconstruction Project Asbestos