

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
										NA	Air Quality Levels	Site Specific Trigger Levels	
										70			
<b>Target Air Quality Levels</b>													
<b>EPA Site Specific Trigger Levels</b>													
ASBESTOS-ST1-9/6/06	030629276-0001	Southwest Area (sidewalk bridge level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST2-9/6/06	030629276-0002	Southeast Area (sidewalk bridge level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST4-9/6/06	030629276-0003	Northwest Area (street-level)	9/6/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST5-9/6/06	030629276-0004	Firehouse #10 (roof level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST6-9/6/06	030629278-0001	Southwest Area (roof level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST7-9/6/06	030629278-0002	Southeast Area (roof level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST8-9/6/06	030629278-0003	Northeast Area (roof level)	9/6/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST9-9/6/06	030629278-0004	Northwest Area (roof level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST10-9/6/06	030629276-0005	North Side Sidewalk Bridge	9/6/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST11-9/6/06	030629276-0006	90 Trinity Place (roof level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST12-9/6/06	030629276-0007	110 Greenwich Street (roof level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST13-9/6/06	030629276-0008	Marriott Hotel, 38th Floor (roof level)	9/6/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST14-9/6/06	030629276-0009	West Face - South end at corner (scaffolding level)	9/6/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST15-9/6/06	030629276-0010	South Face - East end at corner (scaffolding level)	9/6/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST16-9/6/06	030629276-0011	East Face - North end at corner (scaffolding level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST17-9/6/06	030629276-0012	North Face - West end at corner (scaffolding level)	9/6/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/7/06	< 13.00	No	No	
ASBESTOS-ST1-9/7/06	030629428-0001	Southwest Area (sidewalk bridge level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST2-9/7/06	030629428-0002	Southeast Area (sidewalk bridge level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST4-9/7/06	030629428-0003	Northwest Area (street-level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST5-9/7/06	030629428-0004	Firehouse #10 (roof level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST6-9/7/06	030629426-0001	Southwest Area (roof level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST7-9/7/06	030629426-0002	Southeast Area (roof level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST8-9/7/06	030629426-0003	Northeast Area (roof level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST9-9/7/06	030629426-0004	Northwest Area (roof level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST10-9/7/06	030629428-0005	North Side Sidewalk Bridge	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST11-9/7/06	030629428-0006	90 Trinity Place (roof level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST12-9/7/06	030629428-0007	110 Greenwich Street (roof level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST13-9/7/06	030629428-0008	Marriott Hotel, 38th Floor (roof level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST14-9/7/06	030629428-0009	West Face - South end at corner (scaffolding level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST15-9/7/06	030629428-0010	South Face - East end at corner (scaffolding level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST16-9/7/06	030629428-0011	East Face - North end at corner (scaffolding level)	9/7/06	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	
ASBESTOS-ST17-9/7/06	030629428-0012	North Face - West end at corner (scaffolding level)	9/7/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/8/06	< 13.00	No	No	