

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-9/8/10	031025040-0001	Southwest Area (sidewalk bridge level)	9/8/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/9/10	15.00	No	No	
ASBESTOS-ST2-9/8/10	031025040-0002	Southeast Area (sidewalk bridge level)	9/8/10	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/9/10	< 15.00	No	No	
ASBESTOS-ST4-9/8/10	031025040-0003	Northwest Area (street-level)	9/8/10	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/9/10	< 15.00	No	No	
ASBESTOS-ST5-9/8/10	031025040-0004	Firehouse #10 (roof level)	9/8/10	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/9/10	< 15.00	No	No	
ASBESTOS-ST20-9/8/10	031025040-0005	Northeast Area, Sidewalk Bridge	9/8/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/9/10	< 15.00	No	No	
ASBESTOS-ST200-9/8/10	031025040-0008	Station 20 Field Duplicate	9/8/10	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/9/10	< 13.00	No	No	
ASBESTOS-ST21-9/8/10	031025040-0006	Marriott Hotel, 4th Floor	9/8/10	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/9/10	13.00	No	No	
ASBESTOS-ST22-9/8/10	031025040-0007	Roof of 120 Cedar Street	9/8/10	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/9/10	< 15.00	No	No	
ASBESTOS-ST1-9/09/10	031025116-0001	Southwest Area (sidewalk bridge level)	9/9/10	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/10/10	< 15.00	No	No	
ASBESTOS-ST2-9/09/10	031025116-0002	Southeast Area (sidewalk bridge level)	9/9/10	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/10/10	< 15.00	No	No	
ASBESTOS-ST4-9/09/10	031025116-0003	Northwest Area (street-level)	9/9/10	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/10/10	< 13.00	No	No	
ASBESTOS-ST5-9/09/10	031025116-0004	Firehouse #10 (roof level)	9/9/10	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/10/10	< 13.00	No	No	
ASBESTOS-ST20-9/09/10	031025116-0005	Northeast Area, Sidewalk Bridge	9/9/10	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/10/10	< 13.00	No	No	
ASBESTOS-ST21-9/09/10	031025116-0006	Marriott Hotel, 4th Floor	9/9/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/10/10	< 13.00	No	No	
ASBESTOS-ST22-9/09/10	031025116-0007	Roof of 120 Cedar Street	9/9/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/10/10	< 13.00	No	No	
ASBESTOS-ST1-9/10/10	031025260-0001	Southwest Area (sidewalk bridge level)	9/10/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST2-9/10/10	031025260-0002	Southeast Area (sidewalk bridge level)	9/10/10	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST4-9/10/10	031025260-0003	Northwest Area (street-level)	9/10/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST5-9/10/10	031025260-0004	Firehouse #10 (roof level)	9/10/10	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST20-9/10/10	031025260-0005	Northeast Area, Sidewalk Bridge	9/10/10	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST21-9/10/10	031025260-0006	Marriott Hotel, 4th Floor	9/10/10	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST22-9/10/10	031025260-0007	Roof of 120 Cedar Street	9/10/10	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST1-9/11/10	031025261-0001	Southwest Area (sidewalk bridge level)	9/11/10	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST2-9/11/10	031025261-0002	Southeast Area (sidewalk bridge level)	9/11/10	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST4-9/11/10	031025261-0003	Northwest Area (street-level)	9/11/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST5-9/11/10	031025261-0004	Firehouse #10 (roof level)	9/11/10	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 15.00	No	No	
ASBESTOS-ST20-9/11/10	031025261-0005	Northeast Area, Sidewalk Bridge	9/11/10	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST21-9/11/10	031025261-0006	Marriott Hotel, 4th Floor	9/11/10	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST22-9/11/10	031025261-0007	Roof of 120 Cedar Street	9/11/10	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST1-9/12/10	031025259-0001	Southwest Area (sidewalk bridge level)	9/12/10	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST2-9/12/10	031025259-0002	Southeast Area (sidewalk bridge level)	9/12/10	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST4-9/12/10	031025259-0003	Northwest Area (street-level)	9/12/10	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST5-9/12/10	031025259-0004	Firehouse #10 (roof level)	9/12/10	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST20-9/12/10	031025259-0005	Northeast Area, Sidewalk Bridge	9/12/10	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST21-9/12/10	031025259-0006	Marriott Hotel, 4th Floor	9/12/10	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	
ASBESTOS-ST22-9/12/10	031025259-0007	Roof of 120 Cedar Street	9/12/10	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/13/10	< 13.00	No	No	