

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-9/15/06	030630557-0001	Southwest Area (sidewalk bridge level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST2-9/15/06	030630557-0002	Southeast Area (sidewalk bridge level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST4-9/15/06	030630557-0003	Northwest Area (street-level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST5-9/15/06	030630557-0004	Firehouse #10 (roof level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST6-9/15/06	030630558-0001	Southwest Area (roof level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST7-9/15/06	030630558-0002	Southeast Area (roof level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST8-9/15/06	030630558-0003	Northeast Area (roof level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST9-9/15/06	030630558-0004	Northwest Area (roof level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST10-9/15/06	030630557-0005	North Side Sidewalk Bridge	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST11-9/15/06	030630557-0006	90 Trinity Place (roof level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST12-9/15/06	030630557-0007	110 Greenwich Street (roof level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST13-9/15/06	030630557-0008	Marriott Hotel, 38th Floor (roof level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST14-9/15/06	030630557-0009	West Face - South end at corner (scaffolding level)	9/15/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST15-9/15/06	030630557-0010	South Face - East end at corner (scaffolding level)	9/15/06	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST16-9/15/06	030630557-0011	East Face - North end at corner (scaffolding level)	9/15/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST17-9/15/06	030630557-0012	North Face - West end at corner (scaffolding level)	9/15/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST1-9/16/06	030630559-0001	Southwest Area (sidewalk bridge level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST2-9/16/06	030630559-0002	Southeast Area (sidewalk bridge level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST4-9/16/06	030630559-0003	Northwest Area (street-level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST5-9/16/06	030630559-0004	Firehouse #10 (roof level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST6-9/16/06	030630560-0001	Southwest Area (roof level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST7-9/16/06	030630560-0002	Southeast Area (roof level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST8-9/16/06	030630560-0003	Northeast Area (roof level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST9-9/16/06	030630560-0004	Northwest Area (roof level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST10-9/16/06	030630559-0005	North Side Sidewalk Bridge	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST11-9/16/06	030630559-0006	90 Trinity Place (roof level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST12-9/16/06	030630559-0007	110 Greenwich Street (roof level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST13-9/16/06	030630559-0008	Marriott Hotel, 38th Floor (roof level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST14-9/16/06	030630559-0009	West Face - South end at corner (scaffolding level)	9/16/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST15-9/16/06	030630559-0010	South Face - East end at corner (scaffolding level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST16-9/16/06	030630559-0011	East Face - North end at corner (scaffolding level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST17-9/16/06	030630559-0012	North Face - West end at corner (scaffolding level)	9/16/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST1-9/17/06	030630561-0001	Southwest Area (sidewalk bridge level)	9/17/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST2-9/17/06	030630561-0002	Southeast Area (sidewalk bridge level)	9/17/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST4-9/17/06	030630561-0003	Northwest Area (street-level)	9/17/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST5-9/17/06	030630561-0004	Firehouse #10 (roof level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST6-9/17/06	030630562-0001	Southwest Area (roof level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST7-9/17/06	030630562-0002	Southeast Area (roof level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST8-9/17/06	030630562-0003	Northeast Area (roof level)	9/17/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST9-9/17/06	030630562-0004	Northwest Area (roof level)	9/17/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST10-9/17/06	030630561-0005	North Side Sidewalk Bridge	9/17/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST11-9/17/06	030630561-0006	90 Trinity Place (roof level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST12-9/17/06	030630561-0007	110 Greenwich Street (roof level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST13-9/17/06	030630561-0008	Marriott Hotel, 38th Floor (roof level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST14-9/17/06	030630561-0009	West Face - South end at corner (scaffolding level)	9/17/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST15-9/17/06	030630561-0010	South Face - East end at corner (scaffolding level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST16-9/17/06	030630561-0011	East Face - North end at corner (scaffolding level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	
ASBESTOS-ST17-9/17/06	030630561-0012	North Face - West end at corner (scaffolding level)	9/17/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/18/06	< 13.00	No	No	