

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-9/22/06	030631368-0001	Southwest Area (sidewalk bridge level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST2-9/22/06	030631368-0002	Southeast Area (sidewalk bridge level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST4-9/22/06	030631368-0003	Northwest Area (street-level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST5-9/22/06	030631368-0004	Firehouse #10 (roof level)	9/22/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST10-9/22/06	030631368-0005	North Side Sidewalk Bridge	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST11-9/22/06	030631368-0006	90 Trinity Place (roof level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST12-9/22/06	030631368-0007	110 Greenwich Street (roof level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST13-9/22/06	030631368-0008	Marriott Hotel, 38th Floor (roof level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST14-9/22/06	030631368-0009	West Face - South end at corner (scaffolding level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST15-9/22/06	030631368-0010	South Face - East end at corner (scaffolding level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST16-9/22/06	030631368-0011	East Face - North end at corner (scaffolding level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST17-9/22/06	030631368-0012	North Face - West end at corner (scaffolding level)	9/22/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST1-9/23/06	030631386-0001	Southwest Area (sidewalk bridge level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST2-9/23/06	030631386-0002	Southeast Area (sidewalk bridge level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST4-9/23/06	030631386-0003	Northwest Area (street-level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST5-9/23/06	030631386-0004	Firehouse #10 (roof level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST10-9/23/06	030631386-0005	North Side Sidewalk Bridge	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST11-9/23/06	030631386-0006	90 Trinity Place (roof level)	9/23/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST12-9/23/06	030631386-0007	110 Greenwich Street (roof level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST13-9/23/06	030631386-0008	Marriott Hotel, 38th Floor (roof level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST14-9/23/06	030631386-0009	West Face - South end at corner (scaffolding level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST15-9/23/06	030631386-0010	South Face - East end at corner (scaffolding level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST16-9/23/06	030631386-0011	East Face - North end at corner (scaffolding level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST17-9/23/06	030631386-0012	North Face - West end at corner (scaffolding level)	9/23/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST1-9/24/06	030631361-0001	Southwest Area (sidewalk bridge level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST2-9/24/06	030631361-0002	Southeast Area (sidewalk bridge level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST4-9/24/06	030631361-0003	Northwest Area (street-level)	9/24/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST5-9/24/06	030631361-0004	Firehouse #10 (roof level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST10-9/24/06	030631361-0005	North Side Sidewalk Bridge	9/24/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST11-9/24/06	030631361-0006	90 Trinity Place (roof level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST12-9/24/06	030631361-0007	110 Greenwich Street (roof level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST13-9/24/06	030631361-0008	Marriott Hotel, 38th Floor (roof level)	9/24/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST14-9/24/06	030631361-0009	West Face - South end at corner (scaffolding level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST15-9/24/06	030631361-0010	South Face - East end at corner (scaffolding level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST16-9/24/06	030631361-0011	East Face - North end at corner (scaffolding level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST17-9/24/06	030631361-0012	North Face - West end at corner (scaffolding level)	9/24/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/06	< 13.00	No	No	
ASBESTOS-ST1-9/25/06	030631490-0001	Southwest Area (sidewalk bridge level)	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST2-9/25/06	030631490-0002	Southeast Area (sidewalk bridge level)	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST4-9/25/06	030631490-0003	Northwest Area (street-level)	9/25/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST5-9/25/06	030631490-0004	Firehouse #10 (roof level)	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST10-9/25/06	030631490-0005	North Side Sidewalk Bridge	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST11-9/25/06	030631490-0006	90 Trinity Place (roof level)	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST12-9/25/06	030631490-0007	110 Greenwich Street (roof level)	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST13-9/25/06	030631490-0008	Marriott Hotel, 38th Floor (roof level)	9/25/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST14-9/25/06	030631490-0009	West Face - South end at corner (scaffolding level)	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST15-9/25/06	030631490-0010	South Face - East end at corner (scaffolding level)	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST16-9/25/06	030631490-0011	East Face - North end at corner (scaffolding level)	9/25/06	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	
ASBESTOS-ST17-9/25/06	030631490-0012	North Face - West end at corner (scaffolding level)	9/25/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/06	< 13.00	No	No	