

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm ²)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-9/23/08	030833579-0001	Southwest Area (sidewalk bridge level)	9/23/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST2-9/23/08	030833579-0002	Southeast Area (sidewalk bridge level)	9/23/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST4-9/23/08	030833579-0003	Northwest Area (street-level)	9/23/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST5-9/23/08	030833579-0004	Firehouse #10 (roof level)	9/23/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST10-9/23/08	030833579-0005	North Side Sidewalk Bridge	9/23/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST100-9/23/08	030833579-0013	Station 10 Field Duplicate	9/23/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST11-9/23/08	030833579-0006	90 Trinity Place (roof level)	9/23/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST12-9/23/08	030833579-0007	110 Greenwich Street (roof level)	9/23/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	13.00	No	No	
ASBESTOS-ST13-9/23/08	030833579-0008	Marriott Hotel, 38th Floor (roof level)	9/23/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST14-9/23/08	030833579-0009	West Face - South end at corner (scaffolding level)	9/23/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST15-9/23/08	030833579-0010	South Face - East end at corner (scaffolding level)	9/23/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 15.00	No	No	
ASBESTOS-ST16-9/23/08	030833579-0011	East Face - North end at corner (scaffolding level)	9/23/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST17-9/23/08	030833579-0012	North Face - West end at corner (scaffolding level)	9/23/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/24/08	< 13.00	No	No	
ASBESTOS-ST1-9/24/08	030833714-0001	Southwest Area (sidewalk bridge level)	9/24/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST2-9/24/08	030833714-0002	Southeast Area (sidewalk bridge level)	9/24/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST4-9/24/08	030833714-0003	Northwest Area (street-level)	9/24/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST5-9/24/08	030833714-0004	Firehouse #10 (roof level)	9/24/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST10-9/24/08	030833714-0005	North Side Sidewalk Bridge	9/24/08	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST11-9/24/08	030833714-0006	90 Trinity Place (roof level)	9/24/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST12-9/24/08	030833714-0007	110 Greenwich Street (roof level)	9/24/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST13-9/24/08	030833714-0008	Marriott Hotel, 38th Floor (roof level)	9/24/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST14-9/24/08	030833714-0009	West Face - South end at corner (scaffolding level)	9/24/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST15-9/24/08	030833714-0010	South Face - East end at corner (scaffolding level)	9/24/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST16-9/24/08	030833714-0011	East Face - North end at corner (scaffolding level)	9/24/08	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST17-9/24/08	030833714-0012	North Face - West end at corner (scaffolding level)	9/24/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/25/08	< 13.00	No	No	
ASBESTOS-ST1-9/25/08	030833869-0001	Southwest Area (sidewalk bridge level)	9/25/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST2-9/25/08	030833869-0002	Southeast Area (sidewalk bridge level)	9/25/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST4-9/25/08	030833869-0003	Northwest Area (street-level)	9/25/08	1	2.850	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	Note 1
ASBESTOS-ST5-9/25/08	030833869-0004	Firehouse #10 (roof level)	9/25/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST10-9/25/08	030833869-0005	North Side Sidewalk Bridge	9/25/08	1	3.480	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST11-9/25/08	030833869-0006	90 Trinity Place (roof level)	9/25/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST12-9/25/08	030833869-0007	110 Greenwich Street (roof level)	9/25/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST13-9/25/08	030833869-0008	Marriott Hotel, 38th Floor (roof level)	9/25/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST14-9/25/08	030833869-0009	West Face - South end at corner (scaffolding level)	9/25/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST15-9/25/08	030833869-0010	South Face - East end at corner (scaffolding level)	9/25/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST16-9/25/08	030833869-0011	East Face - North end at corner (scaffolding level)	9/25/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ASBESTOS-ST17-9/25/08	030833869-0012	North Face - West end at corner (scaffolding level)	9/25/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/26/08	< 13.00	No	No	
ABESTOS-ST1-9/26/08	030834031-0001	Southwest Area (sidewalk bridge level)	9/26/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 15.00	No	No	
ABESTOS-ST2-9/26/08	030834031-0002	Southeast Area (sidewalk bridge level)	9/26/08	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 15.00	No	No	
ABESTOS-ST4-9/26/08	030834031-0003	Northwest Area (street-level)	9/26/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 15.00	No	No	
ABESTOS-ST5-9/26/08	030834031-0004	Firehouse #10 (roof level)	9/26/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 13.00	No	No	
ABESTOS-ST10-9/26/08	030834031-0005	North Side Sidewalk Bridge	9/26/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 15.00	No	No	
ABESTOS-ST11-9/26/08	030834031-0006	90 Trinity Place (roof level)	9/26/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 13.00	No	No	
ABESTOS-ST12-9/26/08	030834031-0007	110 Greenwich Street (roof level)	9/26/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 13.00	No	No	
ABESTOS-ST13-9/26/08	030834031-0008	Marriott Hotel, 38th Floor (roof level)	9/26/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 13.00	No	No	
ABESTOS-ST14-9/26/08	030834031-0009	West Face - South end at corner (scaffolding level)	9/26/08	1	2.910	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 13.00	No	No	
ABESTOS-ST15-9/26/08	030834031-0010	South Face - East end at corner (scaffolding level)	9/26/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 13.00	No	No	
ABESTOS-ST16-9/26/08	030834031-0011	East Face - North end at corner (scaffolding level)	9/26/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 13.00	No	No	
ABESTOS-ST17-9/26/08	030834031-0012	North Face - West end at corner (scaffolding level)	9/26/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/27/08	< 13.00	No	No	
ASBESTOS-ST1-9/27/08	030834240-0001	Southwest Area (sidewalk bridge level)	9/27/08	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST2-9/27/08	030834240-0002	Southeast Area (sidewalk bridge level)	9/27/08	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST4-9/27/08	030834240-0003	Northwest Area (street-level)	9/27/08	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST5-9/27/08	030834240-0004	Firehouse #10 (roof level)	9/27/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST10-9/27/08	030834240-0005	North Side Sidewalk Bridge	9/27/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST11-9/27/08	030834240-0006	90 Trinity Place (roof level)	9/27/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST12-9/27/08	030834240-0007	110 Greenwich Street (roof level)	9/27/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST13-9/27/08	030834240-0008	Marriott Hotel, 38th Floor (roof level)	9/27/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST14-9/27/08	030834240-0009	West Face - South end at corner (scaffolding level)	9/27/08	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST15-9/27/08	030834240-0010	South Face - East end at corner (scaffolding level)	9/27/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST16-9/27/08	030834240-0011	East Face - North end at corner (scaffolding level)	9/27/08	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST17-9/27/08	030834240-0012	North Face - West end at corner (scaffolding level)	9/27/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST1-9/28/08	030834243-0001	Southwest Area (sidewalk bridge level)	9/28/08	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST2-9/28/08	030834243-0002	Southeast Area (sidewalk bridge level)	9/28/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST4-9/28/08	030834243-0003	Northwest Area (street-level)	9/28/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST5-9/28/08	030834243-0004	Firehouse #10 (roof level)	9/28/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST10-9/28/08	030834243-0005	North Side Sidewalk Bridge	9/28/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST11-9/28/08	030834243-0006	90 Trinity Place (roof level)	9/28/08	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST12-9/28/08	030834243-0007	110 Greenwich Street (roof level)	9/28/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST13-9/28/08	030834243-0008	Marriott Hotel, 38th Floor (roof level)	9/28/08	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 13.00	No	No	
ASBESTOS-ST14-9/28/08	030834243-0009	West Face - South end at corner (scaffolding level)	9/28/08	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST15-9/28/08	030834243-0010	South Face - East end at corner (scaffolding level)	9/28/08	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST16-9/28/08	030834243-0011	East Face - North end at corner (scaffolding level)	9/28/08	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	
ASBESTOS-ST17-9/28/08	030834243-0012	North Face - West end at corner (scaffolding level)	9/28/08	1	3.190	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/29/08	< 15.00	No	No	

Note:

- Due to a final flow rate below 2.0 lpm for asbestos at Station 4 (Northwest Area [street-level]) on September 25, 2008, the sample volume and subsequent sample result are estimated.