

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
										NA	Air Quality Levels	Site Specific Trigger Levels		
										70				
Target Air Quality Levels														
EPA Site Specific Trigger Levels														
ASBESTOS-ST1-9/29/06	030632167-0001	Southwest Area (sidewalk bridge level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST2-9/29/06	030632167-0002	Southeast Area (sidewalk bridge level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST4-9/29/06	030632167-0003	Northwest Area (street-level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST5-9/29/06	030632167-0004	Firehouse #10 (roof level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST10-9/29/06	030632167-0005	North Side Sidewalk Bridge	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST11-9/29/06	030632167-0006	90 Trinity Place (roof level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST12-9/29/06	030632167-0007	110 Greenwich Street (roof level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST13-9/29/06	030632167-0008	Marriott Hotel, 38th Floor (roof level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST14-9/29/06	030632167-0009	West Face - South end at corner (scaffolding level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST15-9/29/06	030632167-0010	South Face - East end at corner (scaffolding level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST16-9/29/06	030632167-0011	East Face - North end at corner (scaffolding level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST17-9/29/06	030632167-0012	North Face - West end at corner (scaffolding level)	9/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST1-9/30/06	030632170-0001	Southwest Area (sidewalk bridge level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST2-9/30/06	030632170-0002	Southeast Area (sidewalk bridge level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST4-9/30/06	030632170-0003	Northwest Area (street-level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST5-9/30/06	030632170-0004	Firehouse #10 (roof level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST10-9/30/06	030632170-0005	North Side Sidewalk Bridge	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST11-9/30/06	030632170-0006	90 Trinity Place (roof level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST12-9/30/06	030632170-0007	110 Greenwich Street (roof level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST13-9/30/06	030632170-0008	Marriott Hotel, 38th Floor (roof level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST14-9/30/06	030632170-0009	West Face - South end at corner (scaffolding level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST15-9/30/06	030632170-0010	South Face - East end at corner (scaffolding level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST16-9/30/06	030632170-0011	East Face - North end at corner (scaffolding level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST17-9/30/06	030632170-0012	North Face - West end at corner (scaffolding level)	9/30/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST1-10/1/06	030632172-0001	Southwest Area (sidewalk bridge level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST2-10/1/06	030632172-0002	Southeast Area (sidewalk bridge level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST4-10/1/06	030632172-0003	Northwest Area (street-level)	10/1/06	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST5-10/1/06	030632172-0004	Firehouse #10 (roof level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST10-10/1/06	030632172-0005	North Side Sidewalk Bridge	10/1/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST11-10/1/06	030632172-0006	90 Trinity Place (roof level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST12-10/1/06	030632172-0007	110 Greenwich Street (roof level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST13-10/1/06	030632172-0008	Marriott Hotel, 38th Floor (roof level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST14-10/1/06	030632172-0009	West Face - South end at corner (scaffolding level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST15-10/1/06	030632172-0010	South Face - East end at corner (scaffolding level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST16-10/1/06	030632172-0011	East Face - North end at corner (scaffolding level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		
ASBESTOS-ST17-10/1/06	030632172-0012	North Face - West end at corner (scaffolding level)	10/1/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/2/06	< 13.00	No	No		