

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-9/30/05	030529623-0001	Southwest Area (street-level)	9/30/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST2-9/30/05	030529623-0002	Southeast Area (street-level)	9/30/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST4-9/30/05	030529623-0004	Northwest Area (street-level)	9/30/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST5-9/30/05	030529623-0005	Firehouse #10 (roof level)	9/30/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST10-9/30/05	030529623-0003	North Side Sidewalk Bridge	9/30/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST1-10/1/05	030529640-0001	Southwest Area (street-level)	10/1/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST2-10/1/05	030529640-0002	Southeast Area (street-level)	10/1/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST4-10/1/05	030529640-0004	Northwest Area (street-level)	10/1/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST5-10/1/05	030529640-0005	Firehouse #10 (roof level)	10/1/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST10-10/1/05	030529640-0003	North Side Sidewalk Bridge	10/1/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST1-10/2/05	030529641-0001	Southwest Area (street-level)	10/2/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST2-10/2/05	030529641-0002	Southeast Area (street-level)	10/2/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST4-10/2/05	030529641-0004	Northwest Area (street-level)	10/2/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST5-10/2/05	030529641-0005	Firehouse #10 (roof level)	10/2/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST10-10/2/05	030529641-0003	North Side Sidewalk Bridge	10/2/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/3/2005	< 19.00	No	No		
ASBESTOS-ST1-10-3/05	030529713-0001	Southwest Area (street-level)	10/3/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No		
ASBESTOS-ST2-10/3/05	030529713-0002	Southeast Area (street-level)	10/3/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No		
ASBESTOS-ST4-10/3/05	030529713-0003	Northwest Area (street-level)	10/3/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No		
ASBESTOS-ST5-10/3/05	030529713-0004	Firehouse #10 (roof level)	10/3/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No		
ASBESTOS-ST10-10/3/05	030529713-0005	North Side Sidewalk Bridge	10/3/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/2005	< 19.00	No	No		
ASBESTOS-ST1-10/4/05	03529858-0001	Southwest Area (street-level)	10/4/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No		
ASBESTOS-ST2-10/4/05	03529858-0002	Southeast Area (street-level)	10/4/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No		
ASBESTOS-ST4-10/4/05	03529858-0003	Northwest Area (street-level)	10/4/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No		
ASBESTOS-ST5-10/4/05	03529858-0004	Firehouse #10 (roof level)	10/4/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No		
ASBESTOS-ST10-10/4/05	03529858-0005	North Side Sidewalk Bridge	10/4/2005	1	4.680	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/2005	< 19.00	No	No		