

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels										70	Levels	Trigger Levels	
ASBESTOS-ST1-10/3/07	030732949-0001	Southwest Area (sidewalk bridge level)	10/3/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST2-10/3/07	030732949-0002	Southeast Area (sidewalk bridge level)	10/3/07	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST4-10/3/07	030732949-0003	Northwest Area (street-level)	10/3/07	1	3.180	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST5-10/3/07	030732949-0004	Firehouse #10 (roof level)	10/3/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST10-10/3/07	030732949-0005	North Side Sidewalk Bridge	10/3/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST11-10/3/07	030732949-0006	90 Trinity Place (roof level)	10/3/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST12-10/3/07	030732949-0007	110 Greenwich Street (roof level)	10/3/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST13-10/3/07	030732949-0008	Marriott Hotel, 38th Floor (roof level)	10/3/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST14-10/3/07	030732949-0009	West Face - South end at corner (scaffolding level)	10/3/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST15-10/3/07	030732949-0010	South Face - East end at corner (scaffolding level)	10/3/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST16-10/3/07	030732949-0011	East Face - North end at corner (scaffolding level)	10/3/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST17-10/3/07	030732949-0012	North Face - West end at corner (scaffolding level)	10/3/07	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/4/07	< 13.00	No	No	
ASBESTOS-ST1-10/04/07	030733066-0001	Southwest Area (sidewalk bridge level)	10/4/07	1	3.160	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 15.00	No	No	
ASBESTOS-ST2-10/04/07	030733066-0002	Southeast Area (sidewalk bridge level)	10/4/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST4-10/04/07	030733066-0003	Northwest Area (street-level)	10/4/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST5-10/04/07	030733066-0004	Firehouse #10 (roof level)	10/4/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST10-10/04/07	030733066-0005	North Side Sidewalk Bridge	10/4/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST11-10/04/07	030733066-0006	90 Trinity Place (roof level)	10/4/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST12-10/04/07	030733066-0007	110 Greenwich Street (roof level)	10/4/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST13-10/04/07	030733066-0008	Marriott Hotel, 38th Floor (roof level)	10/4/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST14-10/04/07	030733066-0009	West Face - South end at corner (scaffolding level)	10/4/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST15-10/04/07	030733066-0010	South Face - East end at corner (scaffolding level)	10/4/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST16-10/04/07	030733066-0011	East Face - North end at corner (scaffolding level)	10/4/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST17-10/04/07	030733066-0012	North Face - West end at corner (scaffolding level)	10/4/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/5/07	< 13.00	No	No	
ASBESTOS-ST1-10/5/07	030733144-0001	Southwest Area (sidewalk bridge level)	10/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST2-10/5/07	030733144-0002	Southeast Area (sidewalk bridge level)	10/5/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST4-10/5/07	030733144-0003	Northwest Area (street-level)	10/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST5-10/5/07	030733144-0004	Firehouse #10 (roof level)	10/5/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST10-10/5/07	030733144-0005	North Side Sidewalk Bridge	10/5/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST11-10/5/07	030733144-0006	90 Trinity Place (roof level)	10/5/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST12-10/5/07	030733144-0007	110 Greenwich Street (roof level)	10/5/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST13-10/5/07	030733144-0008	Marriott Hotel, 38th Floor (roof level)	10/5/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST14-10/5/07	030733144-0009	West Face - South end at corner (scaffolding level)	10/5/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST15-10/5/07	030733144-0010	South Face - East end at corner (scaffolding level)	10/5/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST16-10/5/07	030733144-0011	East Face - North end at corner (scaffolding level)	10/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	
ASBESTOS-ST17-10/5/07	030733144-0012	North Face - West end at corner (scaffolding level)	10/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/6/07	< 13.00	No	No	