

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										NA			
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-10/27/2006	030635426-0001	Southwest Area (sidewalk bridge level)	10/27/06	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST2-10/27/2006	030635426-0002	Southeast Area (sidewalk bridge level)	10/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST4-10/27/2006	030635426-0003	Northwest Area (street-level)	10/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST5-10/27/2006	030635426-0004	Firehouse #10 (roof level)	10/27/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST10-10/27/2006	030635426-0005	North Side Sidewalk Bridge	10/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST11-10/27/2006	030635426-0006	90 Trinity Place (roof level)	10/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST12-10/27/2006	030635426-0007	110 Greenwich Street (roof level)	10/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST13-10/27/2006	030635426-0008	Marriott Hotel, 38th Floor (roof level)	10/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST14-10/27/2006	030635426-0009	West Face - South end at corner (scaffolding level)	10/27/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST15-10/27/2006	030635426-0010	South Face - East end at corner (scaffolding level)	10/27/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST16-10/27/2006	030635426-0011	East Face - North end at corner (scaffolding level)	10/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST17-10/27/2006	030635426-0012	North Face - West end at corner (scaffolding level)	10/27/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST1-10/28/06	030635430-0001	Southwest Area (sidewalk bridge level)	10/28/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST2-10/28/06	030635430-0002	Southeast Area (sidewalk bridge level)	10/28/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST4-10/28/06	030635430-0003	Northwest Area (street-level)	10/28/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST5-10/28/06	030635430-0004	Firehouse #10 (roof level)	10/28/06	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST10-10/28/06	030635430-0005	North Side Sidewalk Bridge	10/28/06	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST11-10/28/06	030635430-0006	90 Trinity Place (roof level)	10/28/06	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST12-10/28/06	030635430-0007	110 Greenwich Street (roof level)	10/28/06	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST13-10/28/06	030635430-0008	Marriott Hotel, 38th Floor (roof level)	10/28/06	1	2.840	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST1-10/29/06	030635423-0001	Southwest Area (sidewalk bridge level)	10/29/06	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST2-10/29/06	030635423-0002	Southeast Area (sidewalk bridge level)	10/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST4-10/29/06	030635423-0003	Northwest Area (street-level)	10/29/06	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST5-10/29/06	030635423-0004	Firehouse #10 (roof level)	10/29/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST10-10/29/06	030635423-0005	North Side Sidewalk Bridge	10/29/06	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST11-10/29/06	030635423-0006	90 Trinity Place (roof level)	10/29/06	1	3.210	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST12-10/29/06	030635423-0007	110 Greenwich Street (roof level)	10/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	
ASBESTOS-ST13-10/29/06	030635423-0008	Marriott Hotel, 38th Floor (roof level)	10/29/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	10/30/06	< 13.00	No	No	

Note:

1. Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) were not available on October 28 and 29, 2006. High winds and/or strong rain on these days made these stations inaccessible and media change and sample recovery were not possible.