

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments	
Target Air Quality Levels											NA	Air Quality Levels	Site Specific Trigger Levels	Comments
EPA Site Specific Trigger Levels											70			
ASBESTOS-ST1-11/4/05	030533303-0001	Southwest Area (street-level)	11/4/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST2-11/4/05	030533303-0002	Southeast Area (sidewalk bridge level)	11/4/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST4-11/4/05	030533303-0003	Northwest Area (street-level)	11/4/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST5-11/4/05	030533303-0004	Firehouse #10 (roof level)	11/4/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST10-11/4/05	030533303-0005	North Side Sidewalk Bridge	11/4/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST11-11/4/05	030533303-0006	90 Trinity Place (roof level)	11/4/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST12-11/4/05	030533303-0007	110 Greenwich Street (roof level)	11/4/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST13-11/4/05	030533303-0008	Marriott Hotel, 38th Floor (roof level)	11/4/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST1-11/5/05	030533300-0001	Southwest Area (street-level)	11/5/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST2-11/5/05	030533300-0002	Southeast Area (sidewalk bridge level)	11/5/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST4-11/5/05	030533300-0003	Northwest Area (street-level)	11/5/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST5-11/5/05	030533300-0004	Firehouse #10 (roof level)	11/5/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST10-11/5/05	030533300-0005	North Side Sidewalk Bridge	11/5/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST11-11/5/05	030533300-0006	90 Trinity Place (roof level)	11/5/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST12-11/5/05	030533300-0007	110 Greenwich Street (roof level)	11/5/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST13-11/5/05	030533300-0008	Marriott Hotel, 38th Floor (roof level)	11/5/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST1-11/6/05	030533302-0001	Southwest Area (street-level)	11/6/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST2-11/6/05	030533302-0002	Southeast Area (sidewalk bridge level)	11/6/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST4-11/6/05	030533302-0003	Northwest Area (street-level)	11/6/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST5-11/6/05	030533302-0004	Firehouse #10 (roof level)	11/6/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST10-11/6/05	030533302-0005	North Side Sidewalk Bridge	11/6/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST11-11/6/05	030533302-0006	90 Trinity Place (roof level)	11/6/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST12-11/6/05	030533302-0007	110 Greenwich Street (roof level)	11/6/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST13-11/6/05	030533302-0008	Marriott Hotel, 38th Floor (roof level)	11/6/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/7/2005	< 13.00	No	No		
ASBESTOS-ST1-11/7/05	030533445-0001	Southwest Area (street-level)	11/7/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/8/2005	< 13.00	No	No		
ASBESTOS-ST2-11/7/05	030533445-0002	Southeast Area (sidewalk bridge level)	11/7/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/8/2005	< 13.00	No	No		
ASBESTOS-ST4-11/7/05	030533445-0003	Northwest Area (street-level)	11/7/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/8/2005	< 13.00	No	No		
ASBESTOS-ST5-11/7/05	030533445-0004	Firehouse #10 (roof level)	11/7/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/8/2005	< 13.00	No	No		
ASBESTOS-ST10-11/7/05	030533445-0005	North Side Sidewalk Bridge	11/7/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/8/2005	< 13.00	No	No		
ASBESTOS-ST11-11/7/05	030533445-0006	90 Trinity Place (roof level)	11/7/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/8/2005	< 13.00	No	No		
ASBESTOS-ST12-11/7/05	030533445-0007	110 Greenwich Street (roof level)	11/7/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/8/2005	< 13.00	No	No		
ASBESTOS-ST13-11/7/05	030533445-0008	Marriott Hotel, 38th Floor (roof level)	11/7/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/8/2005	< 13.00	No	No		
ASBESTOS-ST1-11/8/05	030533573-0001	Southwest Area (street-level)	11/8/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/2005	< 13.00	No	No		
ASBESTOS-ST2-11/8/05	030533573-0002	Southeast Area (sidewalk bridge level)	11/8/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/2005	< 13.00	No	No		
ASBESTOS-ST5-11/8/05	030533573-0004	Firehouse #10 (roof level)	11/8/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/2005	< 13.00	No	No		
ASBESTOS-ST10-11/8/05	030533573-0005	North Side Sidewalk Bridge	11/8/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/2005	< 13.00	No	No		
ASBESTOS-ST11-11/8/05	030533573-0006	90 Trinity Place (roof level)	11/8/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/2005	< 13.00	No	No		
ASBESTOS-ST12-11/8/05	030533573-0007	110 Greenwich Street (roof level)	11/8/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/2005	< 13.00	No	No		
ASBESTOS-ST13-11/8/05	030533573-0008	Marriott Hotel, 38th Floor (roof level)	11/8/2005	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/2005	< 13.00	No	No		

The sample collected on 11/8/2005 at Station 4 (Northwest Area [street-level]) was overloaded (e.g. with wood dust) and not suitable for analysis.