

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)		Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
										NA	70			
										Target Air Quality Levels EPA Site Specific Trigger Levels				
ASBESTOS-ST1-11/8/05	030533573-0001	Southwest Area (street-level)	11/8/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/05	< 13.00		No	No	Station 4 result obtained from SEM analysis due to overloading filter.
ASBESTOS-ST2-11/8/05	030533573-0002	Southeast Area (sidewalk bridge level)	11/8/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/05	< 13.00		No	No	
ASBESTOS-ST4-11/8/05	030533573-0003	Northwest Area (street-level)	11/8/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/05	6.17		No	No	
ASBESTOS-ST5-11/8/05	030533573-0004	Firehouse #10 (roof level)	11/8/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/05	< 13.00		No	No	
ASBESTOS-ST10-11/8/05	030533573-0005	North Side Sidewalk Bridge	11/8/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/05	< 13.00		No	No	
ASBESTOS-ST11-11/8/05	030533573-0006	90 Trinity Place (roof level)	11/8/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/05	< 13.00		No	No	
ASBESTOS-ST12-11/8/05	030533573-0007	110 Greenwich Street (roof level)	11/8/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/05	< 13.00		No	No	
ASBESTOS-ST13-11/8/05	030533573-0008	Marriott Hotel, 38th Floor (roof level)	11/8/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/9/05	< 13.00		No	No	
ASBESTOS-ST1-11/10/05	030533844-0001	Southwest Area (street-level)	11/10/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/05	< 13.00		No	No	
ASBESTOS-ST2-11/10/05	030533844-0002	Southeast Area (sidewalk bridge level)	11/10/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/05	< 13.00		No	No	
ASBESTOS-ST4-11/10/05	030533844-0003	Northwest Area (street-level)	11/10/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/05	< 13.00		No	No	
ASBESTOS-ST5-11/10/05	030533844-0004	Firehouse #10 (roof level)	11/10/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/05	< 13.00		No	No	
ASBESTOS-ST10-11/10/05	030533844-0005	North Side Sidewalk Bridge	11/10/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/05	< 13.00		No	No	
ASBESTOS-ST11-11/10/05	030533844-0006	90 Trinity Place (roof level)	11/10/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/05	< 13.00		No	No	
ASBESTOS-ST12-11/10/05	030533844-0007	110 Greenwich Street (roof level)	11/10/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/05	< 13.00		No	No	
ASBESTOS-ST13-11/10/05	030533844-0008	Marriott Hotel, 38th Floor (roof level)	11/10/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/11/05	< 13.00		No	No	
ASBESTOS-ST1-11/11/05	030534149-0001	Southwest Area (street-level)	11/11/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST2-11/11/05	030534149-0002	Southeast Area (sidewalk bridge level)	11/11/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST4-11/11/05	030534149-0003	Northwest Area (street-level)	11/11/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST5-11/11/05	030534149-0004	Firehouse #10 (roof level)	11/11/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST10-11/11/05	030534149-0005	North Side Sidewalk Bridge	11/11/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST11-11/11/05	030534149-0006	90 Trinity Place (roof level)	11/11/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST12-11/11/05	030534149-0007	110 Greenwich Street (roof level)	11/11/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST13-11/11/05	030534149-0008	Marriott Hotel, 38th Floor (roof level)	11/11/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST1-11/12/05	030534150-0001	Southwest Area (street-level)	11/12/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST2-11/12/05	030534150-0002	Southeast Area (sidewalk bridge level)	11/12/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST4-11/12/05	030534150-0003	Northwest Area (street-level)	11/12/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST5-11/12/05	030534150-0004	Firehouse #10 (roof level)	11/12/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST10-11/12/05	030534150-0005	North Side Sidewalk Bridge	11/12/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST11-11/12/05	030534150-0006	90 Trinity Place (roof level)	11/12/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST12-11/12/05	030534150-0007	110 Greenwich Street (roof level)	11/12/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST13-11/12/05	030534150-0008	Marriott Hotel, 38th Floor (roof level)	11/12/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST1-11/13/05	030534151-0001	Southwest Area (street-level)	11/13/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST2-11/13/05	030534151-0002	Southeast Area (sidewalk bridge level)	11/13/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST4-11/13/05	030534151-0003	Northwest Area (street-level)	11/13/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST5-11/13/05	030534151-0004	Firehouse #10 (roof level)	11/13/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST10-11/13/05	030534151-0005	North Side Sidewalk Bridge	11/13/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST11-11/13/05	030534151-0006	90 Trinity Place (roof level)	11/13/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST12-11/13/05	030534151-0007	110 Greenwich Street (roof level)	11/13/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST13-11/13/05	030534151-0008	Marriott Hotel, 38th Floor (roof level)	11/13/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/14/05	< 13.00		No	No	
ASBESTOS-ST1-11/14/05	030534278-0001	Southwest Area (street-level)	11/14/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/05	< 13.00		No	No	
ASBESTOS-ST2-11/14/05	030534278-0002	Southeast Area (sidewalk bridge level)	11/14/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/05	< 13.00		No	No	
ASBESTOS-ST4-11/14/05	030534278-0003	Northwest Area (street-level)	11/14/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/05	< 13.00		No	No	
ASBESTOS-ST5-11/14/05	030534278-0004	Firehouse #10 (roof level)	11/14/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/05	< 13.00		No	No	
ASBESTOS-ST10-11/14/05	030534278-0005	North Side Sidewalk Bridge	11/14/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/05	< 13.00		No	No	
ASBESTOS-ST11-11/14/05	030534278-0006	90 Trinity Place (roof level)	11/14/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/05	< 13.00		No	No	
ASBESTOS-ST12-11/14/05	030534278-0007	110 Greenwich Street (roof level)	11/14/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/05	< 13.00		No	No	
ASBESTOS-ST13-11/14/05	030534278-0008	Marriott Hotel, 38th Floor (roof level)	11/14/05	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/15/05	< 13.00		No	No	