

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality	Site Specific	Comments
EPA Site Specific Trigger Levels										70	Levels	Trigger Levels	
ASBESTOS-ST1-11/18/07	030736960-0001	Southwest Area (sidewalk bridge level)	11/18/07	1	2.700	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	Note 1
ASBESTOS-ST2-11/18/07	030736960-0002	Southeast Area (sidewalk bridge level)	11/18/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST4-11/18/07	030736960-0003	Northwest Area (street-level)	11/18/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST5-11/18/07	030736960-0004	Firehouse #10 (roof level)	11/18/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST10-11/18/07	030736960-0005	North Side Sidewalk Bridge	11/18/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST11-11/18/07	030736960-0006	90 Trinity Place (roof level)	11/18/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST12-11/18/07	030736960-0007	110 Greenwich Street (roof level)	11/18/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST13-11/18/07	030736960-0008	Marriott Hotel, 38th Floor (roof level)	11/18/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST14-11/18/07	030736960-0009	West Face - South end at corner (scaffolding level)	11/18/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST15-11/18/07	030736960-0010	South Face - East end at corner (scaffolding level)	11/18/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST16-11/18/07	030736960-0011	East Face - North end at corner (scaffolding level)	11/18/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST17-11/18/07	030736960-0012	North Face - West end at corner (scaffolding level)	11/18/07	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/19/07	< 13.00	No	No	
ASBESTOS-ST1-11/19/07	030737047-0001	Southwest Area (sidewalk bridge level)	11/19/07	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 13.00	No	No	
ASBESTOS-ST2-11/19/07	030737047-0002	Southeast Area (sidewalk bridge level)	11/19/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 15.00	No	No	
ASBESTOS-ST4-11/19/07	030737047-0003	Northwest Area (street-level)	11/19/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	15.00	No	No	
ASBESTOS-ST5-11/19/07	030737047-0004	Firehouse #10 (roof level)	11/19/07	1	3.130	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 15.00	No	No	
ASBESTOS-ST10-11/19/07	030737047-0005	North Side Sidewalk Bridge	11/19/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 15.00	No	No	
ASBESTOS-ST100-11/19/07	030737047-0013	Station 10 Field Duplicate	11/19/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 13.00	No	No	
ASBESTOS-ST11-11/19/07	030737047-0006	90 Trinity Place (roof level)	11/19/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 13.00	No	No	
ASBESTOS-ST12-11/19/07	030737047-0007	110 Greenwich Street (roof level)	11/19/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 13.00	No	No	
ASBESTOS-ST13-11/19/07	030737047-0008	Marriott Hotel, 38th Floor (roof level)	11/19/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 13.00	No	No	
ASBESTOS-ST14-11/19/07	030737047-0009	West Face - South end at corner (scaffolding level)	11/19/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 13.00	No	No	
ASBESTOS-ST15-11/19/07	030737047-0010	South Face - East end at corner (scaffolding level)	11/19/07	1	3.140	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 15.00	No	No	
ASBESTOS-ST16-11/19/07	030737047-0011	East Face - North end at corner (scaffolding level)	11/19/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 15.00	No	No	
ASBESTOS-ST17-11/19/07	030737047-0012	North Face - West end at corner (scaffolding level)	11/19/07	1	2.940	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/20/07	< 13.00	No	No	
ASBESTOS-ST1-11/20/07	030737129-0001	Southwest Area (sidewalk bridge level)	11/20/07	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST2-11/20/07	030737129-0002	Southeast Area (sidewalk bridge level)	11/20/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST4-11/20/07	030737129-0003	Northwest Area (street-level)	11/20/07	1	3.260	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST5-11/20/07	030737129-0004	Firehouse #10 (roof level)	11/20/07	1	3.120	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST10-11/20/07	030737129-0005	North Side Sidewalk Bridge	11/20/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST11-11/20/07	030737129-0006	90 Trinity Place (roof level)	11/20/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST12-11/20/07	030737129-0007	110 Greenwich Street (roof level)	11/20/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST13-11/20/07	030737129-0008	Marriott Hotel, 38th Floor (roof level)	11/20/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST14-11/20/07	030737129-0009	West Face - South end at corner (scaffolding level)	11/20/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST15-11/20/07	030737129-0010	South Face - East end at corner (scaffolding level)	11/20/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST16-11/20/07	030737129-0011	East Face - North end at corner (scaffolding level)	11/20/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST17-11/20/07	030737129-0012	North Face - West end at corner (scaffolding level)	11/20/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/21/07	< 13.00	No	No	
ASBESTOS-ST1-11/21/07	030737218-0001	Southwest Area (sidewalk bridge level)	11/21/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST2-11/21/07	030737218-0002	Southeast Area (sidewalk bridge level)	11/21/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST4-11/21/07	030737218-0003	Northwest Area (street-level)	11/21/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST5-11/21/07	030737218-0004	Firehouse #10 (roof level)	11/21/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST10-11/21/07	030737218-0005	North Side Sidewalk Bridge	11/21/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST11-11/21/07	030737218-0006	90 Trinity Place (roof level)	11/21/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST12-11/21/07	030737218-0007	110 Greenwich Street (roof level)	11/21/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST13-11/21/07	030737218-0008	Marriott Hotel, 38th Floor (roof level)	11/21/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST14-11/21/07	030737218-0009	West Face - South end at corner (scaffolding level)	11/21/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST15-11/21/07	030737218-0010	South Face - East end at corner (scaffolding level)	11/21/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST16-11/21/07	030737218-0011	East Face - North end at corner (scaffolding level)	11/21/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST17-11/21/07	030737218-0012	North Face - West end at corner (scaffolding level)	11/21/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST1-11/22/07	030737217-0001	Southwest Area (sidewalk bridge level)	11/22/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST4-11/22/07	030737217-0003	Northwest Area (street-level)	11/22/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST5-11/22/07	030737217-0004	Firehouse #10 (roof level)	11/22/07	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST10-11/22/07	030737217-0005	North Side Sidewalk Bridge	11/22/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST11-11/22/07	030737217-0006	90 Trinity Place (roof level)	11/22/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST12-11/22/07	030737217-0007	110 Greenwich Street (roof level)	11/22/07	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST13-11/22/07	030737217-0008	Marriott Hotel, 38th Floor (roof level)	11/22/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST14-11/22/07	030737217-0009	West Face - South end at corner (scaffolding level)	11/22/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST15-11/22/07	030737217-0010	South Face - East end at corner (scaffolding level)	11/22/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST16-11/22/07	030737217-0011	East Face - North end at corner (scaffolding level)	11/22/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	
ASBESTOS-ST17-11/22/07	030737217-0012	North Face - West end at corner (scaffolding level)	11/22/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	11/23/07	< 13.00	No	No	

- Note:
1. Due to flow rate RPD exceedance (23.8%) for asbestos at Station 1 (Southwest Area [sidewalk bridge level]) on November 18, 2007, the sample volume and subsequent sample result are estimated.
  2. Asbestos sample at Station 2 (Southeast Area [sidewalk bridge level]) on November 22, 2007 was not available for analysis on account of operator error.