

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality Levels	Site Specific Trigger Levels	
EPA Site Specific Trigger Levels										70			
ASBESTOS-ST1-12/29/08	030845066-0001	Southwest Area (sidewalk bridge level)	12/29/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST2-12/29/08	030845066-0002	Southeast Area (sidewalk bridge level)	12/29/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST4-12/29/08	030845066-0003	Northwest Area (street-level)	12/29/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST5-12/29/08	030845066-0004	Firehouse #10 (roof level)	12/29/08	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST10-12/29/08	030845066-0005	North Side Sidewalk Bridge	12/29/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST100-12/29/08	030845066-0013	Station 10 Field Duplicate	12/29/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST11-12/29/08	030845066-0006	90 Trinity Place (roof level)	12/29/08	1	2.990	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST12-12/29/08	030845066-0007	110 Greenwich Street (roof level)	12/29/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST13-12/29/08	030845066-0008	Marriott Hotel, 38th Floor (roof level)	12/29/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST14-12/29/08	030845066-0009	West Face - South end at corner (scaffolding level)	12/29/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST15-12/29/08	030845066-0010	South Face - East end at corner (scaffolding level)	12/29/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST16-12/29/08	030845066-0011	East Face - North end at corner (scaffolding level)	12/29/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST17-12/29/08	030845066-0012	North Face - West end at corner (scaffolding level)	12/29/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/30/08	< 13.00	No	No	
ASBESTOS-ST1-12/30/08	030845184-0001	Southwest Area (sidewalk bridge level)	12/30/08	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 15.00	No	No	
ASBESTOS-ST2-12/30/08	030845184-0002	Southeast Area (sidewalk bridge level)	12/30/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST4-12/30/08	030845184-0003	Northwest Area (street-level)	12/30/08	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST5-12/30/08	030845184-0004	Firehouse #10 (roof level)	12/30/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST10-12/30/08	030845184-0005	North Side Sidewalk Bridge	12/30/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST11-12/30/08	030845184-0006	90 Trinity Place (roof level)	12/30/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST12-12/30/08	030845184-0007	110 Greenwich Street (roof level)	12/30/08	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST13-12/30/08	030845184-0008	Marriott Hotel, 38th Floor (roof level)	12/30/08	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 15.00	No	No	
ASBESTOS-ST14-12/30/08	030845184-0009	West Face - South end at corner (scaffolding level)	12/30/08	1	2.870	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST15-12/30/08	030845184-0010	South Face - East end at corner (scaffolding level)	12/30/08	1	2.820	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST16-12/30/08	030845184-0011	East Face - North end at corner (scaffolding level)	12/30/08	1	2.770	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST17-12/30/08	030845184-0012	North Face - West end at corner (scaffolding level)	12/30/08	1	2.800	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	12/31/08	< 13.00	No	No	
ASBESTOS-ST1-12/31/08	030900074-0001	Southwest Area (sidewalk bridge level)	12/31/08	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 15.00	No	No	
ASBESTOS-ST2-12/31/08	030900074-0002	Southeast Area (sidewalk bridge level)	12/31/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	
ASBESTOS-ST4-12/31/08	030900074-0003	Northwest Area (street-level)	12/31/08	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	
ASBESTOS-ST5-12/31/08	030900074-0004	Firehouse #10 (roof level)	12/31/08	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	
ASBESTOS-ST10-12/31/08	030900074-0005	North Side Sidewalk Bridge	12/31/08	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	
ASBESTOS-ST11-12/31/08	030900074-0006	90 Trinity Place (roof level)	12/31/08	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	
ASBESTOS-ST12-12/31/08	030900074-0007	110 Greenwich Street (roof level)	12/31/08	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	
ASBESTOS-ST13-12/31/08	030900074-0008	Marriott Hotel, 38th Floor (roof level)	12/31/08	1	2.980	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 15.00	No	No	
ASBESTOS-ST14-12/31/08	030900074-0009	West Face - South end at corner (scaffolding level)	12/31/08	1	6.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	Note 1
ASBESTOS-ST15-12/31/08	030900074-0010	South Face - East end at corner (scaffolding level)	12/31/08	1	6.340	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	Note 1
ASBESTOS-ST16-12/31/08	030900074-0011	East Face - North end at corner (scaffolding level)	12/31/08	1	6.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	Note 1
ASBESTOS-ST17-12/31/08	030900074-0012	North Face - West end at corner (scaffolding level)	12/31/08	1	6.320	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/3/09	< 13.00	No	No	Note 1
ASBESTOS-ST1-1/1/09	030900073-0001	Southwest Area (sidewalk bridge level)	1/1/09	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/09	< 13.00	No	No	
ASBESTOS-ST2-1/1/09	030900073-0002	Southeast Area (sidewalk bridge level)	1/1/09	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/09	< 13.00	No	No	
ASBESTOS-ST4-1/1/09	030900073-0003	Northwest Area (street-level)	1/1/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/09	< 13.00	No	No	
ASBESTOS-ST5-1/1/09	030900073-0004	Firehouse #10 (roof level)	1/1/09	1	3.080	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/09	< 13.00	No	No	
ASBESTOS-ST10-1/1/09	030900073-0005	North Side Sidewalk Bridge	1/1/09	1	3.000	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/09	< 13.00	No	No	
ASBESTOS-ST11-1/1/09	030900073-0006	90 Trinity Place (roof level)	1/1/09	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/09	< 13.00	No	No	
ASBESTOS-ST12-1/1/09	030900073-0007	110 Greenwich Street (roof level)	1/1/09	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/09	< 13.00	No	No	
ASBESTOS-ST13-1/1/09	030900073-0008	Marriott Hotel, 38th Floor (roof level)	1/1/09	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	1/2/09	< 13.00	No	No	

Note:

- The asbestos sample volumes at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 [South Face - East end at corner [scaffolding level]], Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on December 31, 2008 represent 2 consecutive 24-hour periods as samples could not be retrieved on January 1, 2009 due to hazardous conditions posed by ice and snow on the scaffolding.
- Asbestos samples at Station 14 (West Face - South end at corner [scaffolding level: 15th floor]), Station 15 [South Face - East end at corner [scaffolding level]], Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on January 1, 2009 were not accessible due to hazardous conditions posed by ice and snow on the scaffolding. Refer to samples collected on December 31, 2008 which reflect 2 consecutive 24-hour periods.