

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m ³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target	Exceeds EPA	Comments
									0.25	Air Quality Levels	Site Specific Trigger Levels	
									25			
Target Air Quality Levels												
EPA Site Specific Trigger Levels												
Dioxins/Furans-ST1-03/15/07	P7647_4773_002	Southwest Area (sidewalk bridge level)	3/15/07	321	Dioxin	TO-9A	AP	3/19/07	0.0367	No	No	
Dioxins/Furans-ST2-03/15/07	P7647_4773_003	Southeast Area (sidewalk bridge level)	3/15/07	327	Dioxin	TO-9A	AP	3/19/07	0.0334	No	No	
Dioxins/Furans-ST4-03/15/07	P7647_4773_004	Northwest Area (street-level)	3/15/07	330	Dioxin	TO-9A	AP	3/19/07	0.0307	No	No	
Dioxins/Furans-ST5-03/15/07	P7647_4773_005	Firehouse #10 (roof level)	3/15/07	342	Dioxin	TO-9A	AP	3/19/07	0.0276	No	No	
Dioxins/Furans-ST10-03/15/07	P7647_4773_006	North Side Sidewalk Bridge	3/15/07	345	Dioxin	TO-9A	AP	3/19/07	0.0268	No	No	
Dioxins/Furans-ST100-03/15/07	P7647_4773_014	Station 10 Field Duplicate	3/15/07	337	Dioxin	TO-9A	AP	3/19/07	0.0396	No	No	
Dioxins/Furans-ST11-03/15/07	P7647_4773_007	90 Trinity Place (roof level)	3/15/07	341	Dioxin	TO-9A	AP	3/19/07	0.0286	No	No	
Dioxins/Furans-ST12-03/15/07	P7647_4773_008	110 Greenwich Street (roof level)	3/15/07	330	Dioxin	TO-9A	AP	3/19/07	0.0253	No	No	
Dioxins/Furans-ST13-03/15/07	P7647_4773_009	Marriott Hotel, 38th Floor (roof level)	3/15/07	342	Dioxin	TO-9A	AP	3/19/07	0.0295	No	No	
Dioxins/Furans-ST14-03/15/07	P7647_4773_010	West Face - South end at corner (scaffolding level)	3/15/07	327	Dioxin	TO-9A	AP	3/19/07	0.0256	No	No	
Dioxins/Furans-ST15-03/15/07	P7647_4773_011	South Face - East end at corner (scaffolding level)	3/15/07	342	Dioxin	TO-9A	AP	3/19/07	0.0234	No	No	
Dioxins/Furans-ST16-03/15/07	P7647_4773_012	East Face - North end at corner (scaffolding level)	3/15/07	343	Dioxin	TO-9A	AP	3/19/07	0.0201	No	No	
Dioxins/Furans-ST17-03/15/07	P7647_4773_013	North Face - West end at corner (scaffolding level)	3/15/07	338	Dioxin	TO-9A	AP	3/19/07	0.0310	No	No	
Dioxins/Furans-ST1-03/16/07	P7653_4775_002	Southwest Area (sidewalk bridge level)	3/16/07	313	Dioxin	TO-9A	AP	3/20/07	0.0284	No	No	
Dioxins/Furans-ST2-03/16/07	P7653_4775_003	Southeast Area (sidewalk bridge level)	3/16/07	318	Dioxin	TO-9A	AP	3/20/07	0.0309	No	No	
Dioxins/Furans-ST4-03/16/07	P7653_4775_004	Northwest Area (street-level)	3/16/07	314	Dioxin	TO-9A	AP	3/20/07	0.0420	No	No	
Dioxins/Furans-ST5-03/16/07	P7653_4775_005	Firehouse #10 (roof level)	3/16/07	348	Dioxin	TO-9A	AP	3/20/07	0.0286	No	No	
Dioxins/Furans-ST10-03/16/07	P7653_4775_006	North Side Sidewalk Bridge	3/16/07	328	Dioxin	TO-9A	AP	3/20/07	0.0269	No	No	
Dioxins/Furans-ST100-03/16/07	P7653_4775_014	Station 10 Field Duplicate	3/16/07	341	Dioxin	TO-9A	AP	3/20/07	0.0249	No	No	
Dioxins/Furans-ST11-03/16/07	P7653_4775_007	90 Trinity Place (roof level)	3/16/07	334	Dioxin	TO-9A	AP	3/20/07	0.0401	No	No	
Dioxins/Furans-ST12-03/16/07	P7653_4775_008	110 Greenwich Street (roof level)	3/16/07	328	Dioxin	TO-9A	AP	3/20/07	0.0249	No	No	
Dioxins/Furans-ST13-03/16/07	P7653_4775_009	Marriott Hotel, 38th Floor (roof level)	3/16/07	335	Dioxin	TO-9A	AP	3/20/07	0.0268	No	No	

Note:

1. Dioxins/Furans samples at Station 14 (West Face - South end at corner [scaffolding level]), Station 15 (South Face - East end at corner [scaffolding level]), Station 16 (East Face - North end at corner [scaffolding level]), and Station 17 (North Face - West end at corner [scaffolding level]) on March 16, 2007 were not available for analysis. The hoists to the scaffolding were not in service.