

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									<b>300</b>			
<b>Target Air Quality Levels</b>												
<b>EPA Site Specific Trigger Levels</b>									<b>3,000</b>			
TotalHg-ST1-1/26/07	07BR0126-01	Southwest Area (sidewalk bridge level)	1/26/07	0.54	Mercury	EPA 324/1631	BRL	1/30/07	< 28.0	No	No	
TotalHg-ST2-1/26/07	07BR0126-02	Southeast Area (sidewalk bridge level)	1/26/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST4-1/26/07	07BR0126-03	Northwest Area (street-level)	1/26/07	0.61	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST5-1/26/07	07BR0126-04	Firehouse #10 (roof level)	1/26/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST10-1/26/07	07BR0126-05	North Side Sidewalk Bridge	1/26/07	0.61	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST11-1/26/07	07BR0126-06	90 Trinity Place (roof level)	1/26/07	0.59	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST12-1/26/07	07BR0126-07	110 Greenwich Street (roof level)	1/26/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST13-1/26/07	07BR0126-08	Marriott Hotel, 38th Floor (roof level)	1/26/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST14-1/26/07	07BR0126-09	West Face - South end at corner (scaffolding level)	1/26/07	0.56	Mercury	EPA 324/1631	BRL	1/30/07	< 27.0	No	No	
TotalHg-ST15-1/26/07	07BR0126-10	South Face - East end at corner (scaffolding level)	1/26/07	0.56	Mercury	EPA 324/1631	BRL	1/30/07	< 27.0	No	No	
TotalHg-ST16-1/26/07	07BR0126-11	East Face - North end at corner (scaffolding level)	1/26/07	0.58	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST17-1/26/07	07BR0126-12	North Face - West end at corner (scaffolding level)	1/26/07	0.56	Mercury	EPA 324/1631	BRL	1/30/07	< 27.0	No	No	
TotalHg-ST1-1/27/07	07BR0132-01	Southwest Area (sidewalk bridge level)	1/27/07	0.58	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST2-1/27/07	07BR0132-02	Southeast Area (sidewalk bridge level)	1/27/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST4-1/27/07	07BR0132-03	Northwest Area (street-level)	1/27/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST5-1/27/07	07BR0132-04	Firehouse #10 (roof level)	1/27/07	0.56	Mercury	EPA 324/1631	BRL	1/30/07	< 27.0	No	No	
TotalHg-ST10-1/27/07	07BR0132-05	North Side Sidewalk Bridge	1/27/07	0.62	Mercury	EPA 324/1631	BRL	1/30/07	< 24.0	No	No	
TotalHg-ST11-1/27/07	07BR0132-06	90 Trinity Place (roof level)	1/27/07	0.59	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST12-1/27/07	07BR0132-07	110 Greenwich Street (roof level)	1/27/07	0.58	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST13-1/27/07	07BR0132-08	Marriott Hotel, 38th Floor (roof level)	1/27/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST14-1/27/07	07BR0132-09	West Face - South end at corner (scaffolding level)	1/27/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST15-1/27/07	07BR0132-10	South Face - East end at corner (scaffolding level)	1/27/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST16-1/27/07	07BR0132-11	East Face - North end at corner (scaffolding level)	1/27/07	0.59	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST17-1/27/07	07BR0132-12	North Face - West end at corner (scaffolding level)	1/27/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST1-1/28/07	07BR0133-01	Southwest Area (sidewalk bridge level)	1/28/07	0.60	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST2-1/28/07	07BR0133-02	Southeast Area (sidewalk bridge level)	1/28/07	0.52	Mercury	EPA 324/1631	BRL	1/30/07	< 29.0	No	No	
TotalHg-ST4-1/28/07	07BR0133-03	Northwest Area (street-level)	1/28/07	0.61	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST5-1/28/07	07BR0133-04	Firehouse #10 (roof level)	1/28/07	0.53	Mercury	EPA 324/1631	BRL	1/30/07	< 28.0	No	No	
TotalHg-ST10-1/28/07	07BR0133-05	North Side Sidewalk Bridge	1/28/07	0.57	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST11-1/28/07	07BR0133-06	90 Trinity Place (roof level)	1/28/07	0.56	Mercury	EPA 324/1631	BRL	1/30/07	< 27.0	No	No	
TotalHg-ST12-1/28/07	07BR0133-07	110 Greenwich Street (roof level)	1/28/07	0.58	Mercury	EPA 324/1631	BRL	1/30/07	< 26.0	No	No	
TotalHg-ST13-1/28/07	07BR0133-08	Marriott Hotel, 38th Floor (roof level)	1/28/07	0.56	Mercury	EPA 324/1631	BRL	1/30/07	< 27.0	No	No	
TotalHg-ST14-1/28/07	07BR0133-09	West Face - South end at corner (scaffolding level)	1/28/07	0.61	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST15-1/28/07	07BR0133-10	South Face - East end at corner (scaffolding level)	1/28/07	0.63	Mercury	EPA 324/1631	BRL	1/30/07	< 24.0	No	No	
TotalHg-ST16-1/28/07	07BR0133-11	East Face - North end at corner (scaffolding level)	1/28/07	0.61	Mercury	EPA 324/1631	BRL	1/30/07	< 25.0	No	No	
TotalHg-ST17-1/28/07	07BR0133-12	North Face - West end at corner (scaffolding level)	1/28/07	0.62	Mercury	EPA 324/1631	BRL	1/30/07	< 24.0	No	No	